December 23, 1999

Carolina Power & Light Company
ATTN: Mr. James Scarola
Vice President - Harris Plant
Shearon Harris Nuclear Power Plant
P. O. Box 165, Mail Code: Zone 1
New Hill, NC 27562-0165

SUBJECT: INSPECTION PLAN FOR SHEARON HARRIS

Dear Mr. Scarola:

On December 6, 1999, the NRC staff reviewed the performance of Shearon Harris as reflected in the performance indicators and inspection results in order to integrate performance information and to plan for inspection activities at your facility from January 3, 2000, through July 31, 2000. The purpose of this letter is to inform you of our plans for future inspections at your facility.

We have not identified any areas in which you crossed a performance threshold. Therefore we plan to conduct only baseline inspections at your facility over the next seven months. However, the results of a triennial fire protection inspection are still under review and may involve further inspection.

Enclosure 1 details the scheduled inspections that will occur from January 3, 2000, through July 31, 2000. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The last four months of the inspection plan are tentative and will be revised at the end-of-cycle review meeting.

Enclosure 2 contains a historical listing of plant issues, referred to as the Plant Issue Matrix (PIM), that were identified during the pilot plant inspection program period. The PIM includes items summarized from inspection reports or other docketed correspondence between NRC and Carolina Power & Light.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room (PDR).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact Brian Bonser at (404) 562-4560 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

(Original signed by B. Bonser)

Brian R. Bonser, Chief Reactor Projects Branch 4 Division of Reactor Projects

Docket No.: 50-400 License No.: NPF-63

Enclosures: 1. Shearon Harris Inspection/Activity Plan

2. Plant Issue Matrix

cc w/encls: (See page 3)

cc w/encls:

Terry C. Morton, Manager
Performance Evaluation and
Regulatory Affairs CPB 9
Carolina Power & Light Company
Electronic Mail Distribution

Chris L. Burton
Director of Site Operations
Carolina Power & Light Company
Shearon Harris Nuclear Power Plant
Electronic Mail Distribution

Bo Clark
Plant General Manager—Harris Plant
Carolina Power & Light Company
Shearon Harris Nuclear Power Plant
Electronic Mail Distribution

Donna B. Alexander, Manager Regulatory Affairs Carolina Power & Light Company Shearon Harris Nuclear Power Plant Electronic Mail Distribution

Johnny H. Eads, Supervisor Licensing/Regulatory Programs Carolina Power & Light Company Shearon Harris Nuclear Power Plant Electronic Mail Distribution

William D. Johnson
Vice President & Corporate Secretary
Carolina Power & Light Company
Electronic Mail Distribution

John H. O'Neill, Jr. Shaw, Pittman, Potts & Trowbridge 2300 N. Street, NW Washington, DC 20037-1128

Mel Fry, Director
Division of Radiation Protection
N. C. Department of Environmental
Commerce & Natural Resources
Electronic Mail Distribution

Peggy Force Assistant Attorney General State of North Carolina Electronic Mail Distribution

Public Service Commission State of South Carolina P. O. Box 11649 Columbia, SC 29211

Chairman of the North Carolina Utilities Commission P. O. Box 29510 Raleigh, NC 27626-0510

Robert P. Gruber Executive Director Public Staff NCUC P. O. Box 29520 Raleigh, NC 27626

Vernon Malone, Chairman Board of County Commissioners of Wake County P. O. Box 550 Raleigh, NC 27602

Richard H. Givens, Chairman Board of County Commissioners of Chatham County Electronic Mail Distribution

Distribution w/encls: (See page 4)

Distribution w/encl:

L. Plisco, RII

W. Dean, NRR/DIPM/IIPB

H. Berkow, NRR

B. Bonser, RII

R. Laufer, NRR

G. MacDonald, RII

J. Coley, RII

R. Baldwin, RII

J. Lenahan, RII

E. Testa, RII

D. Thompson, RII

PUBLIC

OFFICE	DRP/RII	DRS/RII	DRS/RII	DRS/RII	DRS/RII	1		
SIGNATURE	GMacDonald:vg	KBarr	ABeliste Low	HChristensen	KLandis			
NAME	Com	X	14071	RH M	KUT			
DATE	12/21/99	(2) ₂) _{/99}	12/2/ /99	12/2 / /99	12/1/199	12/ /99	12/	/99
E-MAIL COPY?	YES) NO	YES NO	/ (YES NO	YES NO	YES NO	YES NO	YES	NO

OFFICIAL RECORD COPY DOCUMENT NAME: G:\HARRIS\PPR\99q3\midcycleletter.wpd

Page 1 of 1

12/20/1999 15:25:33

HARRIS

Inspection / Activity Plan 01/01/2000 - 07/30/2000

No. of Staff | No. assigned Planned Dates Inspection on Site Units Inspection Activity to Procedure Start End Title Type OLB - REACTOR SAFETY 3 1 IP 71114.01 **Drill and Exercise Inspection** 3 01/10/2000 01/14/2000 Other Routine EB - TEMPORARY INSTRUCTION 2 IP 2515/143 Shearon Harris Spent Fuel Pool (C and D) Expansion 2 01/24/2000 01/28/2000 Safety Issues - SAFEGUARDS **PSB** IP 71130.01 Access Authorization 02/14/2000 02/18/2000 Other Routine IP 71130.02 **Access Control** 02/14/2000 02/18/2000 Other Routine **PSB** - RADIATION SAFETY IP 71121.02 **ALARA Planning and Controls** 03/06/2000 03/10/2000 Other Routine - TEMPORARY INSTRUCTION PB4 IP 2515/142 Draindown During Shutdown and Common-Mode Failure (NRC GL 98-02) 1 04/17/2000 04/21/2000 Safety issues MB - REACTOR SAFETY IP 71111.08 Inservice Inspection Activities (I,B) 04/24/2000 04/28/2000 Other Routine **PSB** - RADIATION SAFETY IP 71121.01 Access Control to Radiologically Significant Areas 04/28/2000 Other Routine 04/24/2000 IP 71121.02 **ALARA Planning and Controls** 04/24/2000 04/28/2000 Other Routine MB - REACTOR SAFETY 3 IP 71111.02 Changes to License Conditions and Safety Analysis Report (M,B) 05/01/2000 05/05/2000 Other Routine IP 71111.17 Permanent Plant Modifications (M,B) 2 05/01/2000 05/05/2000 Other Routine PB4 - PROBLEM ID & RESOLUTION 3 IP 71152 Identification and Resolution of Problems 3 06/05/2000 06/09/2000 Other Routine

Page: 1 of 3 12/23/1999 08:30:51 IR Report 4

United States Nuclear Regulatory Commission Revised Oversight Process PLANT ISSUE MATRIX

By Cornerstone

Region II 05000400 - HARRIS 1

Date	Source	ΙĐ	Туре	Cornerstone	Significance Determination	Item Title Item Description/Significance
10/09/1999	1999006-01	NRC	NCV	Barrier Integrity	Green	FAILURE TO RECOGNIZE THAT AN A (1) GOAL WAS EXCEEDED.
						The licensee failed to take appropriate corrective action under 10CFR50.65 (a)(1) when a maintenance rule (a)(1) performance goal was exceeded for the Target Rock Position Indication performance monitoring group in system 9001, containment isolation valves. The established goal of no more than one failure in 18 months was exceeded on June 11, 1999, but was not recognized by the licensee, and appropriate corrective action was not taken until another functional failure occurred on August 17, 1999.
					•	This issue was characterized as a Non-Cited Violation and was determined to have low risk significance because failure of the Target Rock position indicators did not prevent operators from determining valve positions, and other more time-consuming methods were available. Second, the failure to recognize that a maintenance rule goal had been exceeded did not affect the ability of any valve to operate.
07/17/1999	1999004-01	NRC	NCV	Barrier Integrity	Green	MODE 4 ENTRY AND SUBSEQUENT UNIT OPERATION WITH AN INOPERABLE CONTAINMENT ISOLATION
						Operating the unit with valve 1CC-176 inoperable and taking no action to comply with Technical Specification (TS) Action requirements during the period from November 24, 1998, through December 6, 1998, was a violation of TS 3.6.3, Containment Systems.
1. •						For approximately 11 days the licensee operated the unit with an inoperable component cooling water system containment-isolation valve. The subject valve isolates component cooling water flow to the reactor coolant drain tank heat exchanger and the excess letdown heat exchanger. The scenario requiring the use of valve 1CC-176 to shut in order to contain a radioactive release was estimated at E-14/year, a relatively low risk significance and was a green inspection finding. The system piping is a closed loop inside containment and is neither a high-energy line nor a bypass leakage path. The failure of the valve to close would be indicated in the control room. Emergency procedures require operators to verify valve closure and manually close valves which did not close automatically. During the subject period the valve could be shut from a manual handswitch on the main control board.
07/17/1999	1999004-02	NRC	NCV	Barrier Integrity	Green	FAILURE TO DEMONSTRATE THE OPERABILITY OF CONTAINMENT-ISOLATION VALVES PRIOR TO ENE
					•	Failure to perform an adequate cycling test and verify the isolation time of valve 1CC-176 and failure to verify the isolation time of valve 1CC-202 prior to entering Mode 4 on November 24, 1998, and the subsequent entry into Mode 4, was a violation of surveillance requirement TS 4.6.3.1 and TS 4.0.4.
						The licensee's program to implement this surveillance did not consider the fact that a portion of the containment isolation valves could not be fully tested from the control room handswitch. As a result valves 1CC-176 and 1CC-202 were not adequately tested to meet the TS surveillance requirement prior to entry into mode 4. For risk significance see item 1999004-01.
07/17/1999	1999004-03	NRC	NCV	Barrier Integrity	Green	FAILURE TO IDENTIFY AND CORRECT CONDITIONS ADVERSE TO QUALITY (2 EXAMPLES) (SECTIONS 4)
						Failure to promptly identify and correct a test deficiency during a surveillance test on November 22, 1998, and failure to correct the causes of the failure of valve 1CC-176 to shut during a surveillance test on December 6, 1998, were two examples of a violation of 10 CFR 50, Appendix B, Criterion XVI, Corrective Action.
						The first example involved failure to use the corrective action program to document a test deficiency which identified that there was a problem with valve 1CC-176 prior to entry into mode 4. The second example involved a failure to correct the causes of the 1CC-176 inoperability which would have allowed the event described in item 1999004-01 to reoccur without being identified by post maintenance /surveillance testing. For risk significance see item 1999004-01.

Page: 2 of 3 12/23/1999 08:30:51 IR Report 4

United States Nuclear Regulatory Commission Revised Oversight Process PLANT ISSUE MATRIX

By Cornerstone

Region II 05000400 - HARRIS 1

Date	Source	lD	Туре	Cornerstone	Significance Determination	item Title Item Description/Significance
11/23/19	99 01014-99273	Licensee	VIO	Physical Protection	Green	Failure To Comply With The Regulations In 10 CFR Part 73 and The Provisions Of The Harris Physical Sec Four Examples of a GREEN finding related to access authorization were identified. The examples included: (1) Failure to review and evaluate background information for persons granted unescorted access, (2) Continuation of the granting unescorted access authorization, (3) Failure to maintain original data on which the licensee granted unescorted access authorization for five years, and (4) Failure to log safeguards events within 24 hours
						of discovery. Since it was determined that the individuals granted unescorted access would have been granted access if the background information had been actually verified, the significance of the violation, under the NRC significance determination process was determined to be a GREEN finding. Although the violation was identified by the licensee, due to the failure to restore compliance within a reasonable time a notice of violation is warranted.
						This item was closed by letter dated 11/23/99 (EA 99-273) and documented in inspection report 50-400/99-007.

Page: 3 of 3 12/23/1999 08:30:51 IR Report 4

United States Nuclear Regulatory Commission Revised Oversight Process PLANT ISSUE MATRIX

By Comerstone

Legend

Type Codes:

AV Apparent Violation

FIN Finding

NCV NonCited Violation

URI Unresolved item

VIO Violation

ID Codes:

NRC	NRC
Self	Self-Revealed
Licensee	Licensee

AVs are apparent violations of NRC Requirements that are being considered for escalated enforcement action in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Action" (Enforcement Policy), NUREG-1600. However, the NRC has not reached its final enforcement decision on the issues identified by the AVs and the PIM entries may be modified when the final decisions are made.

URIs are unresolved items about which more information is required to determine whether the issue in question is an acceptable item, a deviation, a nonconformance, or a violation. A URI may also be a potential violation that is not likely to be considered for escalated enforcement action. However, the NRC has not reached its final conclusions on the issues, and the PIM entries may be modified when the final conclusions are made.