



FPL Energy Duane Arnold, LLC
3277 DAEC Road
Palo, Iowa 52324

FPL Energy.

Duane Arnold Energy Center

May 3, 2007

NG-07-0355
10 CFR 73.71

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555-0001

Duane Arnold Energy Center
Docket 50-331
License No. DPR-49

Licensee Event Report #2007-S01-00

Please find attached the subject Licensee Event Report (LER) submitted in accordance with 10 CFR 73.71. This letter contains no new NRC commitments.

Gary Van Middlesworth
Site Vice President, Duane Arnold Energy Center
FPL Energy Duane Arnold, LLC

cc: Administrator, Region III, USNRC
Project Manager, DAEC, USNRC
Resident Inspector, DAEC, USNRC

IE74

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 50 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Duane Arnold Energy Center	2. DOCKET NUMBER 05000 331	3. PAGE 1 OF 3
---	---	---------------------------------

4. TITLE
Unauthorized Person Allowed Entry to Duane Arnold Energy Center Protected Area

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
03	06	2007	2007	S 1	0	05	03	2007		05000
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING MODE 5	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: <i>(Check all that apply)</i>									
10. POWER LEVEL 0	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)						
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input checked="" type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)						
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER						
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A						

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME Thomas R. Byrne - Senior Licensing Engineer	TELEPHONE NUMBER <i>(Include Area Code)</i> (319) 851-7929
--	---

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input type="radio"/> YES <i>(If yes, complete 15. EXPECTED SUBMISSION DATE)</i> <input checked="" type="radio"/> NO	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR

ABSTRACT *(Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)*

On March 6, 2007, a visitor flagged in the Personnel Access Data System (PADS) to be denied Protected Area (PA) access was allowed into the Duane Arnold Energy Center (DAEC) PA as an escorted visitor. The visitor was inside the protected area for 38 minutes and was escorted by an FPL Energy Duane Arnold employee for the duration of the time he was inside the DAEC PA. The visitor did not perform work on any plant equipment during this time. Subsequent to the discovery that this visitor should have been denied access, the visitor's access as an escorted visitor was revoked.

The cause of the event was personnel who performed the PADS check did not recognize that the visitor was prohibited access to the DAEC PA and consequently allowed escorted access. An error trap existed in that the denial statement in PADS, that was intended to indicate that the visitor should be denied access, was ambiguous and was misinterpreted by DAEC personnel performing the background check.

There were no actual safety consequences and no effect on public health and safety as a result of this event.

Neither this abstract nor the narrative portion of this report contains safeguards information.

This report is submitted pursuant to the requirements of 10 CFR 73.71(a)(4).

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Duane Arnold Energy Center	05000331	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 of 3
		2007	-- S01	-- 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

I. Description of Event:

On March 6, 2007, a contractor reported to the Duane Arnold Energy Center (DAEC) to gain access to the DAEC Protected Area (PA) as an escorted visitor. While checking the visitor's status in the Personnel Access Data System (PADS), it was identified that the visitor should be denied access to the DAEC PA. An initial review by FPL Energy Duane Arnold determined that the individual had entered the DAEC PA on March 5, 2007 as an escorted visitor. The DAEC card reader history showed he was inside the PA for 38 minutes on March 5, 2007, and was escorted by an FPL Energy Duane Arnold employee for the entire time he was inside the DAEC PA. The visitor did not perform work on any plant equipment during this time.

PADS administration was contacted and verified that the visitor's social security number was run through the PADS system twice on the afternoon of March 5, 2007, and that a flag on the PADS screen stating "contact access" was present. Through interviews, it was identified that two separate DAEC security personnel had run the PADS check in accordance with a plant procedure but failed to identify the computer prompt to contact access.

There were no structures, systems, or components inoperable at the start of the event.

II. Assessment of Safety Consequences:

Since the unauthorized visitor was escorted at all times and did not exhibit any symptoms of aberrant behavior during the 38 minute period of PA entry, there was little or no safety significance to this event. Therefore, this event had no effect on the health or safety of the public.

III. Cause of Event:

Personnel who performed the PADS check did not recognize that the visitor was prohibited access to the DAEC PA and consequently allowed escorted access.

In reviewing the process for checking visitor's social security numbers through PADS, an error trap was identified in the training provided to security personnel to look for a denial statement in the PADS check screen. The denial statement in PADS for an individual to be denied access is "contact access." Personnel did not understand that this denial statement meant the visitor was prohibited access to the DAEC PA.

IV. Corrective Actions:

DAEC security personnel reviewed all personnel who had been flagged in the PADS identification check process from August 10, 2006 (date of completion of an FPL Energy Duane Arnold Nuclear Oversight PADS assessment) to the date of the incident and verified that all personnel who had received the "contact access" prompt were not permitted access to the PA. (ACE001702)

DAEC security personnel contacted all FPL sites to brief them of the incident and developed a training presentation that was shared with the fleet to prevent reoccurrence at any of the FPL sites. (ACE001702)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Duane Arnold Energy Center	05000331	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 of 3
		2007	-- S01	-- 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

A training presentation for all security personnel was developed to highlight what the PADS screens would look like for an individual who is not to be allowed access. Initial Security training has been modified to include this information. (ACE001702)

A formal request was made to the PADS administration to change the screen displayed to help highlight when unescorted access was denied at other facilities. PADS administration has since contacted the industry and provided the following information:

“A new color coded message scheme will be devised to provide the operator with a color-coded visual aid when operating the PADS Visitor ID Check process. The message text will be expanded to state “DO NOT ALLOW VISITOR TO ENTER CONTACT ACCESS.” In addition, the operator will be required to acknowledge the “DO NOT ALLOW VISITOR TO ENTER CONTACT ACCESS” message by typing a six digit challenge code presented to the operator. The code must be entered by the operator in order to clear the screen and perform the next check.” (ACE001702)

V. Additional Information:

Previous Similar Occurrences:

A search for similar incidents revealed that Catawba has reported as a one-hour report a similar event on April 11, 2007 in which an entry of an unauthorized person (escorted visitor) into the protected area occurred. No other similar events were available in the INPO Operating Experience database.

A review of LERs at the DAEC over the last 3 years identified no LERs with similar events with similar causes.

EIIS System and Component Codes:

None

Reporting Requirements:

This event is reportable per 10 CFR 73, Appendix G, Section I(b) which states that an actual entry of an unauthorized person into a protected area, material access area, controlled access area, vital area, or transport must be reported within one hour of discovery, followed by a written report within 60 days.

This report is being submitted under 10 CFR 73.71(a)(4)