

June 11, 2008

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Stop P1-137
Washington, DC 20555-0001

ULNRC-05518



Ladies and Gentlemen:

**DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
UNION ELECTRIC CO.
FACILITY OPERATING LICENSE NPF-30
RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION
REGARDING REPORT OF FIRST REPLACEMENT STEAM GENERATOR
TUBE IN-SERVICE INSPECTION (TAC NO. MD7372)
Reference: AmerenUE ULNRC-05450, Results of First Replacement Steam
Generator Tube In-Service Inspection, dated October 25, 2007**

By the referenced letter and pursuant to Technical Specification 5.6.10, "Steam Generator Tube Inspection Report," AmerenUE (Union Electric Company) submitted a report of the results of Callaway Plant's first replacement steam generator tube in-service inspection.

From its review of this report, the NRC staff transmitted via e-mail a request for additional information (RAI) containing several individual questions/requests for which responses from AmerenUE are needed in order to support completion of the NRC's review. Accordingly, this letter provides AmerenUE's response to the NRC's RAI in Attachment 1. Within the attachment, each of the individual questions/responses contained in the associated RAI is stated and immediately followed with AmerenUE's response. Text from the NRC's RAI is shown in italics.

Additional information supporting AmerenUE's responses to the RAI questions is provided in Attachments 2 through 4 of this letter. Responding to the NRC's RAI requires no changes to be made to the subject report, and there are no new commitments in this letter.

A047
NRC


ULNRC-05518

June 11, 2008

Page 2

For any questions regarding the attached information, please contact Scott A. Maglio at 573-676-8719 or Tom Elwood at 573-676-6479.

Sincerely,



Keith A. Mills

Manager, Plant Engineering

DJW/nls

- Attachments:
- 1) Responses to NRC RAI Questions/Requests Regarding the Report of Results of Callaway Plant's First Replacement Steam Generator Tube In-Service Inspection
 - 2) Tube Sheet Naming Convention
 - 3) Tube Sheet Map (Cold Leg)
 - 4) Tube Sheet Map (Hot Leg)

ULNRC-05518

June 11, 2008

Page 3

cc: Mr. Elmo E. Collins, Jr.
Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-4005

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. Mohan C. Thadani (2 copies)
Licensing Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop O-8G14
Washington, DC 20555-2738

Index and send hardcopy to QA File A160.0761

Hardcopy:

Certrec Corporation
4200 South Hulen, Suite 422
Fort Worth, TX 76109
(Certrec receives ALL attachments as long as they are non-safeguards and may be publicly disclosed.)

**Electronic distribution for the following can be made via Responses and Reports
ULNRC Distribution:**

C. D. Naslund
A. C. Heflin
T. E. Herrmann
G. A. Hughes
S. M. Maglio
T. B. Elwood
L. H. Graessle
S. L. Gallagher
L. M. Belsky (NSRB)
R. H. Reed
D. J. Walker
Mr. Ron Reynolds, Director (SEMA)
Mr. Edward Gray, Senior REP Planner (SEMA)
Mr. John Campbell, REP Planner (SEMA)
Ms. Diane M. Hooper (WCNOC)
Mr. Dennis Buschbaum (TXU)
Mr. Scott Bauer (Palo Verde)
Mr. Stan Ketelsen (PG&E)
Mr. Scott Head (STP)
Mr. John O'Neill (Pillsbury Winthrop Shaw Pittman LLP)
Mr. Floyd Gilzow (DNR)

**RESPONSE TO NRC RAI QUESTIONS/REQUESTS REGARDING THE
REPORT OF RESULTS OF CALLAWAY PLANT'S FIRST REPLACEMENT
STEAM GENERATOR TUBE IN-SERVICE INSPECTION**

RESPONSES TO NRC PRELIMINARY RAI QUESTIONS/REQUESTS

In its letter dated October 25, 2007, Union Electric Company (the licensee) submitted the report of results from Callaway Plant's first replacement steam generator tube in-service inspection. This report is currently under review by the NRC staff. Via e-mail sent to AmerenUE on March 5, 2008, the NRC staff has requested the following additional information.

1. *You indicated that no active degradation was identified in your steam generators during the 15th Refueling Outage steam generator tube inspections; however, you also indicated that you had identified several tubes with wear at the anti-vibration bars. Please clarify your definition of "active degradation mechanism". The staff has found that the industry's (Electric Power Research Institute's) definition of active degradation in Revision 6 to the Pressurized Water Reactor Steam Generator Examination Guidelines is misleading since tubes could have degradation that is progressing (or present on the tubes) but the degradation could be classified as "not active" (refer to ML010320218 and ML012200349). As a result, please confirm that other than wear at the anti-vibration bars, that you did not find any service-induced indications (i.e., those not attributable to manufacturing) during your inspections. If you did find other indications, please provide the location, orientation, and measured sizes of these indications.*

Response

As discussed in the Pressurized Water Reactor (PWR) Steam Generator (SG) Guidelines, Rev. 6, the definition of Active Degradation Mechanism is as follows:

Active Degradation Mechanism: A combination of 10 or more new indications ($\geq 20\%$ through-wall) of thinning, pitting, wear (excluding loose part wear), or impingement and previous indications that display an average growth rate equal to or greater than 25% of the repair limit in one inspection-to-inspection interval in any one steam generator,

One or more new or previously identified indications ($\geq 20\%$ through-wall) which display a growth equal to or greater than the repair limit in one inspection-to-inspection interval, or

Any crack indication (outside diameter intergranular attack/stress corrosion cracking or primary-side stress corrosion cracking)

Based on this definition, Callaway has no active degradation mechanisms.

PWR SG Guidelines, Revision 7 has been implemented into Callaway's SG Program since the issuance of the 180-day report transmitted via ULNRC-05450 dated October 25, 2007. Revision 7 has changed the definition of active degradation mechanism to the following:

Active Degradation Mechanism: Historical term now synonymous with the term "existing" degradation that is found in the EPRI SG Integrity Assessment Guidelines.

It is believed this change in definition was in response to ML010320218 and ML012200349. Based on this definition, Callaway did not find any service-induced indications other than the AVB bar wear during the RF-15 inspection.

2. *Please provide the effective full power months at the time of your first in-service inspection following the replacement of your steam generators.*

Response

The replacement steam generators had 18 effective full power months (EFPM) of service when they were inspected during RF-15.

3. *For future reference, please provide the following information regarding the design of your replacement steam generators: the tubesheet thickness (with and without clad), the method used to expand the tubes into the tubesheet and the extent of expansion, the extent to which any tubes were stress relieved following bending, the radius of the smallest radius tubes, the tube support plate thickness (including the flow distribution baffle, if any), the anti-vibration bar cross section (e.g., rectangular) and the depth of penetration of the anti-vibration bars. In addition, please provide a tubesheet map, sketch of each steam generator showing the tube support naming convention, and clarify the number of tubes in the steam generators since you indicated that you performed a 100% inspection which was indicated to be 5536 tubes, (and other prior documentation from meetings with the Nuclear Regulatory Commission indicates that there are 5872 tubes per steam generator).*

Response

Tubesheet thickness (with and without clad):

Thickness without clad: 22.047"
Cladding thickness: 0.24"

Method used to expand tubes into tubesheet:

Hydraulic expansion

Extent of expansion:

Tubes were expanded throughout the entirety of the tubesheet.

Extent to which any tubes were stress relieved following bending:

Rows 1-18 were stress relieved.

The radius of the smallest radius tubes:

2.559"

The tube support plate thickness (including the flow distribution baffle, if any):

1.192"

The anti-vibration bar cross section (e.g., rectangular):

Rectangular 0.5" X 0.1388"

The depth of penetration of the anti-vibration bars:

Not known

Provide a tubesheet map:

See Letter Attachments 3 and 4.

Provide sketch of each steam generator showing the tube support naming convention:

See Letter Attachment 2 (representative of each steam generator).

Clarify the number of tubes in the steam generators since you indicated that you performed a 100% inspection which was indicated to be 5536 tubes, (and other documentation from meetings with the Nuclear Regulatory Commission indicates that there are 5872 tubes per steam generator):

Bobbin Straights and Bobbin Candycane rows were unintentionally omitted from Table 1 of the original submitted report. Table 1 should appear as follows:

ECT Task	Extent	SG A	SG B	SG C	SG D	Total
100% Bobbin F/L	Tube end hot to tube end cold	5535	5536	5536	5536	22143
Bobbin Straights	O8H-THE	336	336	336	336	1344
Bobbin Candycane	O8H-TEC	336	336	336	336	1344
MRPC periphery tubes	Top of Tubesheet +3"/-3"	935	935	935	935	3740
MRPC S.I.	Specified location	40	48	52	35	175

There are 5872 tubes per steam generator. One tube was plugged in SG A prior to putting it in service.

4. *Regarding the scope of your inspections, discuss whether any plug or secondary side inspections (including foreign object search and retrieval inspections) were performed. If so, discuss the results. If any loose parts or degraded conditions were identified, please discuss the actions taken to ensure acceptable steam generator performance until the next scheduled inspection.*

Response

The single existing plug in SG A was inspected. FOSAR was performed on all 4 SGs. No foreign objects were discovered. Visual inspection of the steam drum on SG A and SG D was performed. No degraded conditions were identified. Utilizing primary side eddy current data, a Sludge Loading Analysis report was performed for all 4 SGs. An expected light layer of magnetite was confirmed.

5. *Please clarify the following sentence: "Callaway did not perform repairs to any tubes because no tubes exceeded the repair criteria." In particular, confirm that no tube repairs were performed since no tubes exceeded the repair criteria and tube integrity will be maintained until the next steam generator inspection given the flaw sizes that were left in service. The staff notes that sometimes repair may be necessary*

to ensure tube integrity even though the depth of the flaw does not exceed the tube repair criteria. This depends on plant-specific growth rates and other considerations.

Response

Operational assessments were performed per the EPRI Integrity Assessment Guidelines. A repair limit of 21% through-wall (TW) was established (using conservative growth rates) in order to validate Callaway's tube integrity for 4.2 EFPY. This repair limit is stricter than the 40% TW limit provided in the Callaway Plant Technical Specifications. Neither limit was exceeded (greatest indication was 14% TW) and therefore no tubes were plugged during RF-15.

6. *Please clarify whether the +Point examinations performed in the periphery at the top of the tubesheet included both the hot- and cold-leg tubes.*

Response

Periphery tubes in both the hot and cold leg tubes were inspected with the +Point. Refer to Letter Attachments 3 and 4 for more detail.

7. *The staff is aware of at least one chemical excursion that affected the steam generator water chemistry. Please discuss the nature of all chemical excursions that occurred during your first cycle of operation. In addition, discuss the implications of these chemical excursions.*


Response

On 3/9/07 Chemistry noted a high sodium trend in the Hotwell Section 4. The increase occurred rapidly. Per plant procedure APA-ZZ-01021, steam generator blow down limits were exceeded and the plant entered action level 3 (action levels based on the EPRI Secondary Water Chemistry Guidelines) on sodium, sulfate and chloride. Prolonged operations in Action Level 3 could shorten the life of the steam generators. The plant entered action level 3 at 8:20 am and was subsequently shut down at 10:43 am. The prompt shutdown resulted from reactor manual trip due to loss of control of 'C' steam generator water level.

As part of the corrective action program, an investigation into the chemistry problems of this event revealed that the cause of the impurity ingress was a circulation water intrusion caused by a puncture of an IP condenser tube Section 4, in turn caused by a slop-drain support failure. All actions taken to mitigate the chemistry impact to the steam generators were done in accordance with the EPRI Secondary Water Chemistry Guidelines, and as a result, significant consequences were likely prevented.

An integrated exposure analysis was conducted as a reference. This analysis showed that the excursion was 35 ppb-days versus 50 ppb-days which would have required plant shutdown. It is likely that all actions taken were necessary to keep steam generator exposure from reaching levels that might have accelerated steam generator degradation. Assessments of degradation indicated that the likelihood of accelerated tube degradation is small. A complete analysis was conducted including a post-event hide-out return. The hideout return analysis at the outage following the excursion indicated very low rates of hide-out return.




TUBE SHEET NAMING CONVENTION



- SECTION A-A -

- SECTION B-B -

- SECTION C-C -



NOTE 1:
 SET DRAWING - WEIGH-DO-DOOP - GENERAL POSITIVE - INTERNAL VIEW - PART LIST
 EBOOK SIG
 SET DRAWING - WEIGH-DO-DOOP - GENERAL POSITIVE - EXTERNAL VIEW
 EBOOK SIG
 SET DRAWING - WEIGH-DO-DOOP - GENERAL POSITIVE - INTERNAL VIEW -
 DETAILS AND PART LIST - EBOOK SIG
 SET DRAWING - WEIGH-DO-DOOP - GENERAL POSITIVE - EXTERNAL VIEW -
 DETAILS AND PART LIST - EBOOK SIG

NOTE 2:
 THE APPEARANCE OF THE METALS, TAPS AND DRAWINGS MUST HAVE A TOLERANCE
 EQUAL TO 1/8" BE WITH REGARDS TO THE 1/8" AND VIEWS OF THE FIGURE LOCATED
 ON THE TUB-SHELL

NOTE 3:
 DRAWING FOR PARTIAL COVER HANGING IS SHOWN IN DRAWINGS
 WEIGH-DO-DOOP - GENERAL POSITIVE - INTERNAL VIEW - EBOOK SIG
 WEIGH-DO-DOOP - GENERAL POSITIVE - EXTERNAL VIEW - DETAILS AND PART LIST -
 EBOOK SIG



NOTE 4:
 REVISIONS
 MAKE TIGHT ENOUGH APPROXIMATE OF THIS
 REVISIONS OF THIS DRAWING FOR INFORMATION
 CAN BE ADJUSTED DURING THE 1/8" OF CLEAR

ACCESS HOLE
 1/8" DIA
 1/8" DIA

1 MAINWAY
 2 WALK WAY
 3 SIGNAL FRAME CLAMP
 4 SIGNAL SYSTEM
 5 CABLE TRAY

1 ACCESS HOLE
 2 ACCESS FOR WIRE TENSION

DESIGN DATA		PROJECT DATA	
DESIGN	PRIMARY SEE DESIGN PARTS LIST (1/1)	DATE	01-1973
CONSTRUCTION	SECONDARY SEE DESIGN PARTS LIST (1/2)	PROJECT	CALLAWAY NPP - 73/19T RSG
	TERMINATION SEE DESIGN PARTS LIST (1/3)	PLANT	CALLAWAY NPP
	SECONDARY SEE DESIGN PARTS LIST (1/4)	PLANT TRAYS	NUMBER OF TRAYS
	SECONDARY SEE DESIGN PARTS LIST (1/5)	PLANT TRAYS	TRAY COORDINATES
	SECONDARY SEE DESIGN PARTS LIST (1/6)	PLANT TRAYS	TRAY SPACING
	SECONDARY SEE DESIGN PARTS LIST (1/7)	PLANT TRAYS	TRAY SUPPORTS
	SECONDARY SEE DESIGN PARTS LIST (1/8)	PLANT TRAYS	TRAY BRACING
	SECONDARY SEE DESIGN PARTS LIST (1/9)	PLANT TRAYS	TRAY CONNECTIONS
	SECONDARY SEE DESIGN PARTS LIST (1/10)	PLANT TRAYS	TRAY ADAPTERS
	SECONDARY SEE DESIGN PARTS LIST (1/11)	PLANT TRAYS	TRAY COLLARS
	SECONDARY SEE DESIGN PARTS LIST (1/12)	PLANT TRAYS	TRAY GASKETS
	SECONDARY SEE DESIGN PARTS LIST (1/13)	PLANT TRAYS	TRAY LIDS
	SECONDARY SEE DESIGN PARTS LIST (1/14)	PLANT TRAYS	TRAY RINGS
	SECONDARY SEE DESIGN PARTS LIST (1/15)	PLANT TRAYS	TRAY SCREWS
	SECONDARY SEE DESIGN PARTS LIST (1/16)	PLANT TRAYS	TRAY WELDS
	SECONDARY SEE DESIGN PARTS LIST (1/17)	PLANT TRAYS	TRAY ZONES
	SECONDARY SEE DESIGN PARTS LIST (1/18)	PLANT TRAYS	TRAY ZONES



AS-BUILT

PERSIAN ENGINEERING

M-1183-00004 000

CLIENT	Ameren UE
NO. OF SHEETS / NO. OF SHEETS	0303.115
NO. OF SHEETS / NO. OF SHEETS	
FRAMATOME, AMP	CPWY

VALID FOR US APPLICATIONS

CALLAWAY NPP - 73/19T RSG

GENERAL ASSEMBLY -
 INTERNAL VIEW -
 (EBOOK) - EBOOK SIGS -

EQUIPMENT DRAWING

FRAMATOME AMP
 PERSIAN ENGINEERING 00-0004

TUBE SHEET MAP (COLD LEG)

Callaway Unit 1 04/07 - 1RFO15

GROUP
A C/L TTS +3/-3

TUBES
965

C/L Top of Tubesheet + Point Examination w/ Probe 610PP

AREVA - FDMS map module Version 5.0

S/G A
COLD
PRIMARY FACE


TOTAL TUBES: 5872
SELECTED TUBES: 965
OUT OF SERVICE (#): 1

SCALE: 0.084494 X

Thu Mar 22 17:01:46 2007

Callaway Unit 1: S/G A COLD FANP - 73/19T(GV/CA294)

This drawing is the property of AREVA NP Inc, an AREVA and Siemens company and is loaned upon condition that it is not to be reproduced or copied, in whole or in part, or used for furnishing information to others, or for any other purpose detrimental to the interests of AREVA NP Inc and will be returned upon request.



TUBE SHEET MAP (HOT LEG)

Callaway Unit 1 04/07 - 1RFO15

GROUP
A H/L TTS +3/-3

TUBES
965

H/L Top of Tubesheet +Point Examination w/ Probe 610PP

AREVA - FDMS map module Version 5.0

S/G A
HOT
PRIMARY FACE

TOTAL TUBES: 5872
SELECTED TUBES: 965
OUT OF SERVICE (#): 1

SCALE: 0.084494 X
Thu Mar 22 16:59:42 2007
Callaway Unit 1: S/G A HOT FANP - 73/19T(GV/CA294)
This drawing is the property of AREVA NP Inc, an AREVA and Siemens company and is loaned upon condition that it is not to be reproduced or copied, in whole or in part, or used for furnishing information to others, or for any other purpose detrimental to the interests of AREVA NP Inc and will be returned upon request.

