



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

May 22, 1981

Mr J G Keppler
Office of Inspection & Enforcement
US Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

AC Interlock Design Problem

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.1.i. An interlock associated with an engineered safeguards system was found to be improperly designed.

David M. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

-over-

*A002
5/1*

810600 1443
S

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | N | M | N | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 3 | 7 | 0 | 5 | 0 | 8 | 8 | 1 | 8 | 0 | 5 | 2 | 2 | 8 | 1 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | AC interlock permitting auto blowdown with ADS was energized with core spray pump
0 3 | not running. AC interlock is energized when a pressure > 85 psi exists in the
0 4 | line and should be energized only when a pump is running. Occurrence reportable
0 5 | under Technical Specifications 6.7.B.1.i. No previous similar reportable events.
0 6 | No effect on public health or safety.
0 7 |
0 8 |

0 9 | S | F | 11 | B | 12 | A | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16

17 | LER/RO REPORT NUMBER | 8 | 1 | 21 | 22 | 23 | 24 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 0 | 32
18 | X | 18 | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | N | 24 | A | 25 | Z | 9 | 9 | 9 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | AC interlock instrument tap located downstream of pump discharge check valve on
1 1 | section of line that remains pressurized following pump shutdown. Partially secured
1 2 | open pump discharge check valve bypass valve to allow line depressurization while
1 3 | still maintaining core spray pipe filled. Modification being pursued to move
1 4 | instrument tap upstream of pump discharge check valve.

1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | ECCS Test | 32

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

1 8 | 0 | 0 | 0 | 40 | NA | 41

1 9 | Z | 42 | NA | 43

2 0 | N | 44 | NA | 45

NAME OF PREPARER: A. V. Wojchouski

ONE: (612)295-5151

810-600 1 445