



Northern States Power Company

414 Nicollet Mall Minneapolis, Minnesota 55401 Telephone (612) 330-5500

May 22, 1981

Mr J G Keppler Office of Inspection & Enforcement U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

> MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Racking Out Of Energized 4-Kv Breaker And Subsequent Events

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.c in that it represents inadequate implementation of procedural controls.

Dail Mu, seg son L O Mayer, PE

Manager of Nuclear Support Services

LOM/DMM/jh

cc Director, IE, USNRC Director, MIPC, USNRC (3) NRC Resident Inspector MPCA

Attn: J W Ferman

Attachment

-over-

LICENSEE EVENT REPORT

| | CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
|------------|--|
| 0 1 | M N M N P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 E |
| O 1 8 | REPORT L 6 0 5 0 0 0 2 6 3 7 0 4 2 7 8 1 8 0 5 2 2 8 1 9 SOURCE 60 DOCKET NUMBER 68 68 69 EVENT DATE 74 75 REPORT DATE 80 |
| 0 2 | During refueling outage, bus fault on essential bus caused momentary loss of entire |
| 0 3 | 4.16KV bus network. Diesel generator provided power to redundant essential bus. |
| 0 4 | Reportable under Tech. Spec. 6.7.B.2.c. No similar occurrences. No affect on |
| 0 5 | public health and safety. |
| 0 6 | |
| 0 7 | |
| 0 8 | |
| 0 9 7 8 | CODE SUBCODE COMPONENT CODE SUBCODE SU |
| | LER/RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE TYPE NO. O O O 9 24 26 27 OCCURRENCE REPORT TYPE NO. O 3 L L O O O O O O O O O O O |
| | ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER ACTION FUTURE COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER ACTION ON PLANT METHOD 12 OF 10 O O O O O O O O O O O O O O O O O O |
| 10 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Operator error caused initial bus fault. Undervoltage relaying system resulted |
| 11 | in the loss of all 4.16KV buses. Undervoltage relaying modified to allow over- |
| 1 2 | current relaying to isolate faulted bus from total 4.16KV network. Operator |
| 1 3 | annual retraining program will include proper breaker operations. |
| 1 4 7 ε | g |
| 1 5 | ACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DISCOVERY DISCOVERY DESCRIPTION 32 DI |
| 1 6 RE | CTIVITY CONTENT SLEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA LOCATION OF RELEASE (36) |
| 1 7 | PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 NA |
| 1 8 | 9 PERSONNEL INJURIES 13 NUMBER DESCRIPTION (41) 0 0 0 40 NA |
| 7 ε 1 g | Loss of OH DAMAGE TO FACILITY 43 TYPE DESCRIPTION D 42 Breaker, Breaker Cubicle, Bus Stabs |
| | PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY |
| 7 8 | NA (612) 205 5351 |
| 1 | ** NAME OF PREPARER Lawrence Pudlick [8106001444] |