

Bradley J. Sawatzke Columbia Generating Station P.O. Box 968, PE08 Richland, WA 99352-0968 Ph. 509.377.4300 | F. 509.377.4150 bjsawatzke@energy-northwest.com

February 8, 2012 GO2-12-022

10 CFR 50.73

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555-0001

Subject: COLUMBIA GENERATING STATION, DOCKET NO. 50-397 LICENSEE EVENT REPORT NO. 2011-004-00

Dear Sir or Madam:

Transmitted herewith is Licensee Event Report No. 2011-004-00 for Columbia Generating Station. This report is submitted pursuant to 10 CFR 50.73(a)(2)(v)(C) and 10 CFR 50.73(a)(2)(v)(D). The enclosed report discusses items of reportability and corrective actions taken related to an event which occurred December 10, 2011 that caused secondary containment differential pressure to exceed Technical Specification limits for a short period of time due to ice buildup and subsequent release from reactor building air filters.

There are no commitments being made to the NRC by this letter. If you have any questions or require additional information, please contact Mr. ZK Dunham at (509) 377-4735.

Respectfully,

BJ Sawatzke Vice President, Nuclear Generation & Chief Nuclear Officer

Attachment: Licensee Event Report 2011-004-00

cc: NRC Region IV Administrator NRC NRR Project Manager NRC Senior Resident Inspector/988C RN Sherman – BPA/1399 WA Horin – Winston & Strawn

NRC FORM (10-2010)	1 366 _ICEI (Se	U.S. N NSEE E ee revers ligits/cha	EVENT RI	EPORT (L ed number o each block)	COMMIS .ER) of	SION	APF Estir 80 h fed I Sect 000 Offic Man infor NRC infor	PROVED mated bu ours. Re back to in tion (T-5 1, or by i ce of Info agemen mation of may no mation of	D BY OMB urden per re eported less ndustry. Se F53), U.S. nternet e-m imation and t and Budg collection do t conduct o collection.	NO sons end Nuc nail t d Re et, V oes or sp	D. 3150-010 onse to com is learned a comments clear Regul to <u>infocoller</u> egulatory A Washingtor not display ponsor, and	04 nply with regardin atory Co <u>cts.resou</u> ffairs, NE n, DC 205 a curren I a perso	this ma orated i g burde mmissic rce@nr EOB-10 503. If a tly valid n is not	ndatory nto the n estim on, Was <u>c.gov</u> , a 202 (31 a means OMB c require	EXPIRE collection licensing ate to the hington, and to the 50-0104 sused to control ne d to resp	ES 10/31/2013 on request: g process and e FOIA/Privacy DC 20555- e Desk Officer,), Office of impose an umber, the ond to, the
1. FACILIT	Y NAN Co	ie Iumbia	Generati	ng Station			2. D	OCKET	NUMBER) 39 239	97		· 3. PA	GE	1 OF	3
4. TITLE Seconda	ary C	ontainn	nent Low	Differentia	l Press	sure (due 1	o Ice	Buildup	•						
5. EV	ENT D	ATE	6.	LER NUMBE	R		7. RE	PORT	DATE		8	3. OTHE	R FAC	LITIES	INVOL	VED
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	мог	NTH	DAY	YEAR	F	FACILITY	NAME			DOC	KET NUMBER
12	10	2011	201	1 - 004 -	00	0	2	08	2012	F	FACILITY				DOC	KET NUMBER 05000
9. OPERA 1 10. POWEF 100	TING N		11. TI 20.22 2	HIS REPORT 201(b) 201(d) 203(a)(1) 203(a)(2)(i) 203(a)(2)(ii) 203(a)(2)(iii) 203(a)(2)(iv) 203(a)(2)(v) 203(a)(2)(v)	IS SUBM	20 20 20 50 50 50 50 50 50 50 50 50 50 50	2203 2203 2203 2203 36(c) .36(c) .36(c) .36(c) .46(a) .73(a) .73(a)	SUANT (a)(3)(i) (a)(4) (1)(i)(A) (1)(ii)(A) (1)(ii)(A) (2) (3)(ii) (2)(i)(A) (2)(i)(B)	TO THE F [[[[[[[[[[[[[[[[[[[2UIREMEN 50.73(a)(2 50.73(a)(2 50.73(a)(2 50.73(a)(2 50.73(a)(2 50.73(a)(2 50.73(a)(2 50.73(a)(2 50.73(a)(2 50.73(a)(2	ITS OF 2)(i)(C) 2)(ii)(A) 2)(ii)(B) 2)(iii) 2)(iii) 2)(iii) 2)(iv)(A) 2)(v)(A) 2)(v)(B) 2)(v)(C) 2)(v)(D)	10 CFF	1 §: (C 5 5 5 5 5 5 7 0 7 0 5 5 5 5 5 5 5 5 5 5 5 5 5	heck all 0.73(a)(0.73(a)(0.73(a)(0.73(a)(0.73(a)(0.73(a)(3.71(a)(3.71(a)(THER pecify in	that apply) 2)(vii) 2)(viii)(A) 2)(viii)(B) 2)(viii)(B) 2)(ix)(A) 2)(x) 4) 5) Abstract below
					12. LICE	NSEE	CONT	ACTE		ER	1			0	r in NRC	Form 366A
FACILITY N Bichard	NAME	rcia Prir	ncinal Licer	nsing Engir	heer						TE	LEPHO	NE NU	MBER	(Include	Area Code)
Thomas a	- Clui	1	3. COMPLET		FOREA	СНСС	MPO)ES			REPOR	RT		
CAUSE	SY	STEM	COMPONENT	MANU- FACTURE	R	EPORTA TO EPI	NBLE X		CAUSE		SYSTEM	COMP	ONENT	MA FACT	NU- URER	REPORTABLE TO EPIX
		14. 9								1	15. EXPECT SUBMISSIC	TED DN	MON	тн	DAY	YEAR
	t yes, c	complete	5. EXPECTE	D SUBMISSI	ON DATE	=)			,		DATE					
ABSTRA On 12/10 specifica were exe consequ release standard taken to	ACT 0/11, ation ceede uence on ex d ope mitig	(Limit to second allowated the the s for the terior a rating p gate pol	1400 space dary conta- ble limits for resulting e is event. in filters s procedure tential for	s, i.e., appro ainment wa or a period excursion The caus upplying t s for cold icing on fil	oximately as decl d of ap was bo e for th he read weathe lters.	v 15 si lared proxil unde e eve ctor b er ope	ingle-: inop mate ed by ent v ouildi eratio	spaced berabl ely two v analy vas de ng H\ ons to	typewritte e due to o minute rtical res rtermine /AC sys lower t	en l o di es. sul ed 1 ster he	<i>lines)</i> ifferentia While Its and t to be icc m. Corn thresho	al pres techni hus th e build rective old at v	ssure cal sp ere v lup a actic which	exce becifie vere i nd su ons w posi	eding cation no saf bsequ ill enh tive st	technical limits ety uent ance eps are

.

 \mathbb{Z}_{n-1}

.

NRC FORM 366A (10-2010)			U.S. NUCLE	EAR REGULA	TORY COMMISSION
	LICENSEE EVE CONTINU	NT REPOR	RT (LER) EET		
1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE	
Columbia Generating Station	05000397	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 3

NARRATIVE

Plant Conditions

At the time of the event, the plant was in Mode 1 and 100 percent power. There were no structures, systems, or components that were inoperable at the start of the event that contributed to the event. Reactor building exhaust [VL] was in a normal alignment with REA-FN-1A, one of two 100 percent capacity exhaust fans [FAN], running with REA-FN-1B in standby condition. Reactor building exhaust filters [FLT] had been observed to be icing over due to adverse environmental conditions (the area had been under a deep freeze since 12/8/11 and humidity was approximately 90 percent for this same time period) and steps had been taken to monitor the filters and advance roll filters on a more frequent basis.

Event Description

The control room received a high secondary containment differential pressure alarm on 12/10/11 at 04:43. The pressure excursion resulted in a peak pressure of approximately 0.03 inches water gauge and an unplanned entry into LCO 3.6.4.1A. In response to the alarm, Operations swapped from REA-FN-1A and ROA-FN-1A to REA-FN-1B and ROA-FN-1B. Reactor Exhaust Air (REA) Differential Pressure (DP) controller [VA], REA-DPIC-1A was then able to maintain Reactor Building pressure below the Technical Specification (TS) limit of -0.25 inches water gauge after two minutes, as designed.

This event is reportable as an event that could have prevented fulfillment of a safety function needed to control the release of radiation and mitigate the consequences of an accident per 10 CFR 50.73(a)(2)(v)(C) & 10 CFR 50.73(a)(2)(v)(D). A 10 CFR 50.72(b)(3)(v)(C) and 10 CFR 50.72(b)(3)(v)(D) notification was made via Event Number 47516. Note that the original Event Notification incorrectly listed the event time as 04:56, review of plant data after the fact confirmed the actual time the TS limit was exceeded was 04:43.

Immediate Corrective Actions

The shift manager authorized a verbal procedure change to SOP-COLDWEATHER-OPS to allow for cutting of the roll filter of Reactor Building Outside Air (ROA) during extreme cold conditions when it was recognized that existing guidance in the procedure was insufficient to counter the ongoing conditions.

Assessment of Safety Consequences

This event resulted in an unplanned entry into LCO 3.6.4.1A. Containment pressure was above -0.25 inches water gauge for approximately two minutes. The actual pressure response of secondary containment [NH] during this event was bounded by existing drawdown and dose analyses and thus there are no actual safety consequences to this event.

Cause of Event

The DP decrease was caused by buildup and subsequent release of ice on the ROA filter and bird screen allowing an increased amount of air to be pulled into the Reactor Building [NG] in a short amount of time. The resulting rapid pressure transient was on a time scale shorter than that which the flow controllers [TC] could respond.

			U.S. NUCLE	AR REGULATO	ORY COMMISSION
(10-2010)			BT (LEB)		
	CONTINU	ATION SH	IEET		
1. FACILITY NAME	2. DOCKET		6. LER NUMBER		3. PAGE
Oslumbia Osassatian Otatian	0500007	YEAR	SEQUENTIAL	REV NO	0.05.0
Columbia Generating Station	05000397		2011 - 004 - 00		3 OF 3
NARRATIVE		L		K	· · · · · · · · · · · · · · · · · · ·
Similar Events					
A search of corrective action docume filters. Both events occurred in Dece pressure on secondary containment	ents back to 2004 ember 2008, but r	revealed	only two instance ulted in exceeding	s of noted g TS allowa	icing on outside ble differential
Further Corrective Actions					
Additional corrective actions will form	nalize enhanceme	ents to SO			ade as immedia
corrective actions as well as to inclu	de precautions ab	out condit	tions of high humi	dity and lov	v temperatures
and to lower the threshold for advan	cing roll filters with	hobserve	d icing.		, iomporatoroo
	-		-		
Energy Industry Identification Syster	n (EIIS) Informatio	on codes f	rom IEEE Standa	rds 805-19	84 and 803-198
are represented in brackets as [XX]	and [XXX] throug	hout the be	ody of the narrativ	/e.	
	1 · · · ·	• •			
		· .			
		• .			
	• • • • • • •	· .			
	· · · · · · ·				
· · · · · · · · · · · · · · · · · · ·					
· · · · · · · · · · · · · · · · · · ·					
		· .			
· · · · · · · · · · · · · · · · · · ·					
		· .			
		· .	· · · · · · · · · · · · · · · · · · ·		
		· · · · · · · · · · · · · · · · · · ·			
		· · · · · · · · · · · · · · · · · · ·			
		· · · · · · · · · · · · · · · · · · ·			
		· . · · ·			
		· . · . · .			

· · · ·

÷