

Tennessee Valley Authority, 1101 Market Street, Chattanooga, Tennessee 37402

August 24, 2012

10 CFR 50.55a

ATTN: Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555-0001

> Browns Ferry Nuclear Plant, Unit 3 Facility Operating License No. DPR-68 NRC Docket No. 50-296

Subject: American Society of Mechanical Engineers Section XI, Inservice Inspection, System Pressure Test, Containment Inservice Inspection, and Repair and Replacement Programs - Owner's Activity Report for Cycle 15 Operation

The Tennessee Valley Authority is submitting the Browns Ferry Nuclear Plant, American Society of Mechanical Engineers (ASME), Section XI, Owner's Activity Report for Unit 3 Cycle 15 operation. The report is contained in the enclosure to this letter and is in accordance with the requirements of ASME Code Case N-532-4, "Alternative Requirements to Repair and Replacement Documentation Requirements and Inservice Summary Report Preparation and Submission as Required by IWA-4000 and IWA-6000, Section XI, Division 1."

The report is an overview of the results from inservice examinations that were performed on components within the ASME Section XI boundary, up to and including the Unit 3 Cycle 15 refueling outage, during the second inspection period of the third 10-year inspection interval. The applicable provisions of the ASME Code require that this report be submitted 90 days from the end of the applicable outage. The Unit 3 Cycle 15 refueling outage ended on May 26, 2012. Accordingly, this submittal is due by August 24, 2012.

U.S. Nuclear Regulatory Commission Page 2 August 24, 2012

There are no new regulatory commitments in this letter. If you have any questions regarding this report, please contact Thomas A. Hess at (423) 751-3487.

Respectfully,

D.E. anthe For J. W. Shea

Vice President, Nuclear Licensing

Enclosure: American Society of Mechanical Engineers, Section XI, Third 10-Year Inspection Interval, Inservice Inspection, System Pressure Test, Containment Inspection, and Repair and Replacement Programs, Owner's Activity Report for Cycle 15 Operation

cc (Enclosure):

NRC Regional Administrator - Region II NRC Senior Resident Inspector - Browns Ferry Nuclear Plant Enclosure

# **Tennessee Valley Authority**

#### Browns Ferry Nuclear Plant Unit 3

### American Society of Mechanical Engineers, Section XI, Third 10-Year Inspection Interval

#### Inservice Inspection, System Pressure Test, Containment Inservice Inspection, and Repair and Replacement Programs

**Owner's Activity Report for Cycle 15 Operation** 

(See Attached)

Report Number	BFNU3C15				
Plant Browns	Ferry				
Jnit No. 3	Commercial service date	03/01/1977	Refueling outag	ge no.	15
Current inspectior	n interval <u>3rd</u>	Current inspe	ection period	2nd	
	FORM OAR-1 OWNER'S	ACTIVITY REP	PORT		
			······································		
Report Number <u>BFNU3</u>	C15				
Plant Browns Ferry Nu	clear Plant, P.O. Box 2000, Decatur, AL 35602-2000	J			
Unit No. <u>3</u> (if applicable)	_ Commercial service date <u>March 1, 1977</u>	Refueling Outa	ge no. <u>Cycle 15</u>		
Current Inspection Interv	val Third Ten Year Inspection Interval	(1st, 2nd, 3rd, other)			
Current Inspection Perio		,,			
		(1st, 2nd, 3rd)			
Edition and Addenda of	Section XI applicable to the inspection plans 2001 E	dition through 2003 Adder	ida		
Date and Revision of ins	spection plan	2			
Edition and Addenda of	Section XI applicable to repairs and replacements, if	different than the inspectio	n plan 2004 Edition		
Code Cases used: <u>N-4</u>	60, N-508-3, N-528-1, N-532-4, N-552, N-577, N-586 ((/ applicable		86-1. N-695. N-702		

#### **CERTIFICATE OF CONFORMANCE**

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of \_\_\_\_\_U3C15\_\_\_ conform to the requirements of Section XI. (refueling outage number)

EFF Bayon Aco: End Din Date B-9-12 MY Signed

#### CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of <u>Tennessee</u> and employed by <u>HSB CT</u> of <u>Hartford</u>. <u>Connecticut</u> have inspected the items described in this Owner's Activity Report and state that to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirement of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the examinations, tests, replacements, evaluations, and corrective measures described in this report. Furthermore, neither the Inspector nor his employer shall be liable in min manner for any personal injury or property damage or a loss of any kind arising from or connected with this Inspection.

S/10/12 Date \_

#### TADI EC

TΑ	BL	.ES
TΑ	BL	.ES

Report N	umber	BFNU3C15			
Plant	Browns	Ferry			
Unit No.	3	Commercial service date	03/01/1977	Refueling outage no.	15
Current i	nspection	interval <u>3rd</u>	Current ins	pection period 2nd	
		TAE	BLE 1		

#### ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRE EVALUATIONS FOR CONTINUED SERVICE

Examination		
Category and Item Number	Item Description	Evaluation Description
F-A, Item F1.10B	Material deformation on the lower washer and top of RPV Head Flange due to an entrapped foreign object during a VT-1 examination. (RPV-WASH-3-50) [NOI U3RF15-002]	EVALUATED ACCEPTABLE (No Corrective Measures Required. The identified condition was the result of entrapment of a small washer between the RPV washer and the RPV Flange that resulted in an impression of the entrapped washer in the upper side of the RPV head Flange that is not a pressure boundary sealing surface. RPV Closure Head Assembly drawing 131855E states that surface finishes may have isolated tool marks or similar depressions provided they are minor in nature and are not on sealing surfaces used to seal pressure boundaries. The RPV Flange thickness is 2'-7"± 1/8". The impression caused by the entrapped washer was approximately 1/64" in depth. As a measure of good practice, the RPV washer was replaced.
F-A, Item F1.10C	As-Found constant spring support setting out-of-range. Range 8.7 ± 1/2 increment. As-Found 9.7 West Spring and 9.9 East Spring. (3-47B400-114) [NOI U3CRF15-004]	EVALUATED ACCEPTABLE (No Corrective Measures Required. Piping movement from the cold set to hot position is upward and thermal movement is less than the available travel. The springs did not bottom out during service. The as-found settings represent the final position after pipe movement through the available travel of the springs during the last operating cycle. This support was repaired U3R14. These springs have limited travel range tolerance and are difficult to reset. Since the as-found cold set positions were near bottoming out, the springs were reset to the cold set position to provide acceptable margin for continued operation.

## TABLES

Report Number Plant Brown	BFNU3C15 is Ferry					
Unit No. 3	Commercial	service date	03/01/197	7 Refuelin	g outage no. 15	
Current inspection	Current inspection interval 3rd Current inspection period 2nd					
ABSTRACT	TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE					
	Item	Descri	otion	Date	Repair/Replacement	
Code Class	Description	of We	ork	Completed	Plan Number	
CODE CLASS 3	Through wall leak in 2.5" EECW piping (~1/2 gallon per minute)	Cut old pipin replace with		08/07/2011	Work Order 112536582	
CODE CLASS 2	Physical damage on studs. Not service induced. (3-FCV-074-0071)	STUDS/ REPLA		05/09/2012	Work Order 111044049	

TA	BL	.ES
----	----	-----

Report N	umber	BFNU3C15		······································	
Plant	Browns	Ferry			
Unit No.	3	Commercial service date	03/01/1977	Refueling outage no.	15
Current ir	nspection	interval <u>3rd</u>	Current ins	pection period 2nd	······

# Summary of IWE Indications for U3C15

The summary table below is provided in accordance with the requirements of 10 CFR 50.55a(b)(2)(ix)(A) and 10 CFR 50.55a(b)(2)(ix)(D).

Examination Category and Item Number	Component Identifier	Indication Description	Acceptability/Corrective Action	Inaccessible Area (Location and Evaluation)	Additional Samples
E-A E1.11	Suppression Chamber PSC EXT 3-B-1 PSC EXT 3-B-2 PSC EXT 3-B-3 PSC EXT 3-B-4 PSC EXT 3-B-5 PSC EXT 3-B-6 PSC EXT 3-B-7 PSC EXT 3-B-7 PSC EXT 3-B-7 PSC EXT 3-B-10 PSC EXT 3-B-10 PSC EXT 3-B-11 PSC EXT 3-B-12 PSC EXT 3-B-13 PSC EXT 3-B-14 PSC EXT 3-B-15 PSC EXT 3-B-16	Mechanical damage, dings, dents, minor corrosion, pitting, scrapes, arc strikes, weld deposit, chip marks, grind marks, and minor surface indications. [NOI U3RF15-005]	Engineering accept-as-is. Conditions noted do not impact structural integrity or leak tightness of the SCV. The conditions identified are expected based on the age and service conditions of the SCV. None of the conditions noted were suspect. No detrimental flaws have been observed.	None	None

TABL	.ES
------	-----

Report N	umber E	BFNU3C15			
Plant	Browns Fe	erry	·		
Unit No.	3	Commercial service date	03/01/1977	Refueling outage no.	15
Current i	nspection in	nterval <u>3rd</u>	Current ins	pection period 2nd	

# ATTACHMENT A

The following welds were calculated to have ASME Section XI Code examination coverage 90 percent or less. TVA will submit a request for relief for these weld examinations in separate correspondence.

1

WELD ID	CONFIG	Limitation	%
GR-3-63	Valve to Pipe	single side exam	50%
DRHR-3-12	Valve to Flued Head	single side exam	30%
RWCU-3-007-003	Pipe to Tee	single side exam	57.85%
RWCU-3-007-011	Valve to Pipe	single side exam	88.6%
N1B-NV	Nozzle to Vessel	joint geometry	25.27%
N4A-NV	Nozzle to Vessel	joint geometry	32.31%
N4B-NV	Nozzle to Vessel	joint geometry	32.38%
N4C-NV	Nozzle to Vessel	joint geometry	32.38%
N4D-NV	Nozzle to Vessel	joint geometry	32.31%
N4E-NV	Nozzle to Vessel	joint geometry	32.38%
N4F-NV	Nozzle to Vessel	joint geometry	32.38%
N9-NV	Nozzle to Vessel	joint geometry	27.96%
N10-NV	Nozzle to Vessel	joint geometry	74.10%
N10-IR	Inner Radius	joint geometry	90%