## **ENCLOSURE 3**

Browns Ferry Nuclear Units 1, 2 and 3 Licensee Event Report 50-259/2013-001-00

NRC FORM 366		U.S.	NUCLEA	R REGULA	TORY C	OMMISS	ION	API	PROVED	BY O	MB NO. 3	150-0104		EXPIRES 10/31/2013				
LICENSEE EVENT REPORT (LER)					Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.							ocess and IA/Privacy IC 20555- sk Officer, Office of mpose an imber, the						
1. FACI			-l D	lant /DE	TAIN I Incid	4			2. [	DOCKET				3. F	AGE	-		
Brov	wns F	erry ivu	clear P	iant (Br	N), Unit	1			<u> </u>	<u> </u>	JOUC	00259			i i	of 8	<u> </u>	
					nsistenci				ect	Probal	ble						_	
5. E	VENT	DATE	6.	LER NUM	BER	7. R	EPORT D	DATE	$\Box$				IER FAC	ILITIE	S INVOL			
монтн	DAY	YEAR	YEAR	SEQUENT NUMBE		монтн	DAY	YEA	R	FACILITY BFN,	Un	it 2					000	260
02	06	2013	2013	- 001	- 00	04	08	201	13 FACILITY NAME BFN, Unit 3						DOCKE 05		1BER 1296	
9 OPE	RATINO	MODE	11	THIS RE	PORT IS S	UBMITTI	ED PURS	SUAN	T TC	THE R	FQU	REMEN	TS OF 10	CFR	8: (Check	all tha	t anr	ılv)
0. 0		,		2201(b)			).2203(a)					73(a)(2)(		•	50.7			.,,
	4		20.	2201(d)		□ 20	).2203(a)	(3)(ii)				73(a)(2)(			50.7	3(a)(2	)(viii)	(A)
	1		<b>20.</b> :	2203(a)(1)		□ 20	).2203(a)	(4)										
			<b>2</b> 0.:	2203(a)(2)	(i)	□ 50	).36(c)(1)	(i)(A)			$\square$ 50.73(a)(2)(iii) $\square$ 50.73(a)(2)(ix)(A)						A)	
10. PO\	VER LE	EVEL	<b>2</b> 0.:	2203(a)(2)	(ii)	□ 50	).36(c)(1)	(ii)(A)			$\square$ 50.73(a)(2)(iv)(A) $\square$ 50.73(a)(2)(x)							
				2203(a)(2)		50.36(c)(2)				50.73(a)(2)(v)(A)				73.71(a)(4)				
				2203(a)(2)					50.73(a)(2)(v)(B)				73.71(a)(5)					
	100			2203(a)(2)			).73(a)(2)				_	.73(a)(2)(			☐ OTH			
			20.:	2203(a)(2)	(vi)	□ 50	).73(a)(2)	(i)(B)			50	.73(a)(2)(	v)(D)		Form		act beid	w or in NRC
				-	12	. LICENS	SEE CON	ITACI	ΓFO	R THIS	LER							
FACILITY													TEL	EPHON	E NUMBER (I			ode)
Christ	tophe	r Benne	tt, Lice	nsing E	ngineer								]		256-72	9-24	75	
			13. COM	IPLETE O	NE LINE FO	OR EAC	H COMP	ONEN	IT F	AILURE	DES	CRIBED	IN THIS	REPO	RT			
CAU	SE	SYSTEM	сом	IPONENT	MANU- FACTURER		ORTABLE O EPIX		CAL	JSE	SY	STEM	СОМРО	NENT	MANU- FACTURI			ORTABLE D EPIX
																		·
		14.	SUPPLE	MENTAL	REPORT E	XPECT	ED						PECTED		MONTH	DAN	,	YEAR
⊠ ve						l no					ISSION		<b></b>		$\rightarrow$			
YES (If yes, complete 15. EXPECTED SUBMISSION DATE) NO DATE 06 12 2013  ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)																		
ABSTRA	CT (Lin	nit to 1400 s <sub>i</sub>	paces, i.e.,	approximat	ely 15 single-	spaced ty	pewritten l	ines)										
(	On July 28, 2009, the Tennessee Valley Authority (TVA) identified latent design input inconsistencies in																	
I	hydrological computer modeling used for probable maximum flood (PMF) calculations.																	
•	The ro	ot cause	s of the	condition	n were a	n orgai	nization	al be	hav	vior wh	ich a	allowed	the late	ent in	put			
i	incons	istencies	s to go u	ındetect	ed and m	anager	ment fa	ilure	to p	orovide	ove	ersight o	of the in	npact	t of river	syste	em	1

The root causes of the condition were an organizational behavior which allowed the latent input inconsistencies to go undetected and management failure to provide oversight of the impact of river system changes on the calculated value of the PMF. The corrective actions to prevent recurrence are to procedurally require a Flood Protection Program, develop formal Flood Protection Program Management Implementing Procedure(s) and Design Standards/Guides, create a formal documented risk management process for all engineering products, formalize the elements of engineering technical rigor, and implement an upper tier integrated risk management process.

Upon discovery, TVA implemented both immediate and interim corrective actions to ensure the Fort Loudoun, Cherokee, Tellico and Watts Bar dams would not overtop during an assumed PMF event.

The TVA is currently performing an analysis to determine the safety significance of this condition at the Browns Ferry Nuclear Plant (BFN), Units 1, 2, and 3. Until the analysis is complete, TVA is reporting this condition as an unanalyzed condition that significantly degraded plant safety. The TVA will submit a supplement to the LER upon completion of the analysis.

## **LICENSEE EVENT REPORT (LER)**

CONTINUATION SHEET

CONTINUATION SHELT								
FACILITY NAME (1)	DOCKET (2)	L	ER NUMBER (6	PAGE (3)				
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Browns Ferry Nuclear Plant, Unit 1	05000259	2013	001	00	2 of 8			

#### NARRATIVE

## I. Plant Operating Condition(s) Before the Event

At the time of discovery, the Browns Ferry Nuclear Plant (BFN), Units 1, 2, and 3, were in Mode 1 at approximately 100 percent rated thermal power.

## II. Description of the Event(s)

#### A. Event

On July 28, 2009, Tennessee Valley Authority (TVA) identified latent computer modeling inconsistencies that adversely affected probable maximum flood (PMF) analyses. Specifically, TVA identified the potential to overtop and fail earthen embankments at Cherokee, Fort Loudon, Tellico and Watts Bar Dams. The potential to overtop and fail earthen embankments was identified based on an ongoing effort at that time to update, revalidate and verify the design basis flooding calculations for TVA nuclear plants.

The updating of the affected calculations included (1) unit hydrograph changes, (2) software code errors, (3) dam rating curve changes, (4) median reservoir level changes, (5) flood operation changes, (6) Dallas Bay omission (impacting BFN only), (7) and overflow areas at Watts Bar Dam. The overtopping and failure of the specified earthen embankments could have resulted in an increase in the PMF level at WBN, Sequoyah Nuclear Plant (SQN) and BFN and had the potential to affect systems required for safe shutdown. At the time, this condition represented an unanalyzed condition at all three sites. Subsequent analysis determined that the calculated increase in flood level at WBN from a PMF event in which the specified earthen embankments were overtopped and failed rendered existing flood mode procedures ineffective. This exposure existed for some period of time prior to the identification of the unanalyzed condition in 2009.

There have been subsequent studies for past operability that have shown that the PMF level for BFN remains below the licensing and design basis PMF level of 572.5 feet above sea level. However, those studies were for past operability and did not use inputs and assumptions in line with the licensing basis. TVA is currently performing analysis to determine the safety significance of this condition. Until the analysis is complete, TVA is reporting this condition as an unanalyzed condition that significantly degraded plant safety for BFN, Units 1, 2 and 3. TVA will submit a supplement to the LER upon completion of the analysis.

Upon discovery, TVA implemented interim and immediate corrective actions to ensure the Fort Loudoun, Cherokee, Tellico and Watts Bar dams would not overtop during an assumed PMF event.

## B. Status of Structures, Components, or Systems that were Inoperable at the Start of the Event and that Contributed to the Event

There were no inoperable structures, components, or systems that contributed to the event.

## **LICENSEE EVENT REPORT (LER)**

**CONTINUATION SHEET** 

FACILITY NAME (1)	(1) DOCKET (2) LER NUMBER (6)							
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Browns Ferry Nuclear Plant, Unit 1	05000259	2013	001	00	3 of 8			

## NARRATIVE

## C. Dates and Approximate Times of Occurrences

Date	Description						
1960~1970s	TVA develops hydrology modeling software (Simulated Open						
	Channel Hydraulics (SOCH)).						
1982	· TVA begins dam safety program consistent with Federal						
	Guidelines for Dam Safety.						
1985	TVA's Engineering Laboratory issues the spillway coefficient						
	report, "Method for Estimating Discharge at Overflow						
	Spillways with Curved Crests and Radial Gates." TVA						
	estimates orifice discharges using a single curve in the U.S.						
	Army Corps of Engineers' Hydraulic Design Criteria (HDC).						
1998	TVA reassesses effects of dam safety modifications on PMF						
	using SOCH.						
2003	TVA Water Management initiates River Operations Study						
	(ROS) Environmental Impact Statement (EIS) to evaluate						
	impacts of potential changes to operation of the TVA reservoir						
	system.						
October 30,	TVA submits the Bellefonte Nuclear Plant (BLN) Units 3 and 4						
2007	Combined License Application (COLA). The 1998 flood						
	reassessment calculation is used as the basis for Final Safety						
	Analysis Report section 2.4.						
March 19,	NRC issues Notice of Violation for failure to implement the						
2008	quality assurance program for the SOCH modeling.						
March 2008	During verification and validation of SOCH inputs and codes,						
to	latent inconsistencies and necessary changes in PMF						
September	calculations are identified. The cumulative effects of these						
2012	inconsistencies and changes predict potential dam						
	overtopping at Fort Loudoun, Cherokee, Watts Bar and Tellico						
	dams during a PMF.						
July 28,	TVA determines that based on certain PMF modeling						
2009	concerns the Fort Loudoun Dam could be overtopped and fail						
	and the resulting PMF levels could exceed the original design						
	and licensing basis elevations.						

## LICENSEE EVENT REPORT (LER)

**CONTINUATION SHEET** 

FACILITY NAME (1)	DOCKET (2)		ER NUMBER (6	PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Browns Ferry Nuclear Plant, Unit 1	05000259	2013	001	00	4 of 8	

#### NARRATIVE

August 14,	TVA determines that based on certain PMF modeling					
2009	concerns the Fort Loudoun Dam could be overtopped and fail					
	and the resulting PMF levels could exceed the original design					
	and licensing basis elevations.					
September	TVA determines that if the Cherokee Dam were to overtop and					
24, 2009	fail, the PMF levels could exceed the original design and					
	licensing basis elevations.					
December	HESCO modular flood barrier installation at affected dams to					
30, 2009	raise earthen embankments.					
February 6,	TVA notified the NRC that due to the potential to overtop and					
2013	fail earthen embankments at four dams, BFN was in an					
	unanalyzed condition that could have resulted in an increased					
	PMF level.					

## D. Manufacturer and Model Number (or other identification) of Each Component that Failed During the Event

There were no failed components associated with this condition.

#### E. Other Systems or Secondary Functions Affected

There were no other systems or secondary functions affected by this condition.

### F. Method of Discovery of Each Component or System Failure or Procedural Error

On July 28, 2009, as part of an ongoing validation of SOCH model and sub-codes, TVA concluded that the spillway discharge coefficient previously used in the Fort Loudoun Dam Rating Curve was inconsistent with more recent model test data. Additional research revealed that the same was true for Cherokee, Tellico and Watts Bar dams.

#### G. The Failure Mode, Mechanism, and Effect of Each Failed Component

There were no failed components.

## **H. Operator Actions**

There were no operator actions.

## I. Automatically and Manually Initiated Safety System Responses

There were no safety system responses.

#### III. Cause of the event

## A. The cause of each component or system failure or personnel error, if known:

There were no component or system failures or personnel errors associated with this event.

## LICENSEE EVENT REPORT (LER)

**CONTINUATION SHEET** 

CONTINUATION SILLET									
FACILITY NAME (1)	DOCKET (2)	L	<u> ER NUMBER (6</u>	PAGE (3)					
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
Browns Ferry Nuclear Plant, Unit 1	05000259	2013	001	00	5 of 8				

#### NARRATIVE

## B. The cause(s) and circumstances for each human performance related root cause:

TVA identified two root causes for this condition, each having human performance related aspects.

- 1. An organizational behavior, rooted in over-confidence that TVA was the industry hydrology expert, resulted in the input errors (latent computer modeling inconsistencies) during the development of the SOCH model going undetected.
- TVA Nuclear management's failure to provide oversight of the impact of changes to the
  river system on the calculated PMF at BFN and failure to apply safety-significant
  conservative decision-making for those changes demonstrated that nuclear safety was
  not the overriding priority.

TVA identified two relevant contributing factors.

- 1. Formal process controls were not established that ensure the flood protection program protects critical safety systems for the TVA nuclear sites.
- TVA demonstrated less than adequate shared understanding of the applicable regulatory requirements under which the nuclear sites, as integral components of the river system, must operate.

In 1998 and again in 2004, significant changes to the design of the dams and operation of the river system were implemented. In both cases, the model was used to calculate the impact to the nuclear sites. The Nuclear organization acted upon those results without questioning the validity of the model, the calculations that it supported, or its conclusions. TVA Nuclear remained over-confident in the belief of the accuracy of the model throughout this period.

Since they had been used to license the nuclear stations, the software and model were believed to be correct. The over-confidence in the model continued to exist as late as 2008 when the model was employed in support of the BLN license submittal.

It was not until 2009, during validation of the hydrology model, that TVA realized that there were inconsistencies in the model inputs which, when corrected, resulted in the realization that some upstream dams could overtop and fail. The failure of the dams would overwhelm the planned flood protection actions to protect the safety systems at the TVA nuclear stations.

In summary, the latent design input inconsistencies, and a lack of rigor and oversight due to the overconfidence in the evaluation of changes in the operation of the river system over time, resulted in unrecognized inaccuracies in the PMF calculations.

### IV. Analysis of the event:

#### Reportability Analysis

This condition is being reported in accordance with Title 10 of the Code of Federal Regulations (10 CFR) 50.73(a)(2)(ii)(B) as any event or condition that resulted in the nuclear power plant being in an unanalyzed condition that significantly degraded plant safety.

## LICENSEE EVENT REPORT (LER)

**CONTINUATION SHEET** 

CONTINUENTION SHEET									
FACILITY NAME (1)	DOCKET (2)	L	ER NUMBER (6	)	PAGE (3)				
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
Browns Ferry Nuclear Plant, Unit 1	05000259	2013	001	00	6 of 8				

#### NARRATIVE

### **Operational Analysis**

TVA is currently performing analysis to determine the PMF elevations at BFN prior to the HESCO modular flood barrier installation. This analysis will determine the safety significance of this condition at BFN and a supplement to this report will be submitted once the analysis is complete.

Since installation of the HESCO modular flood barriers, the analyzed conditions at BFN regarding PMF are within design and licensing basis limitations and the interim actions completed in December 2009 will prevent the overtopping and failure of the embankments.

## V. Assessment of Safety Consequences

Upon the discovery of the potential to overtop upstream dams during a PMF event, it was immediately recognized by TVA that interim measures were required to maintain operability of BFN, SQN, and WBN. If overtopping of earthen embankments occurred, the design basis flood was projected to increase to an unacceptable level beyond what SQN and WBN could reasonably protect against. The impacts at BFN would be to a lesser degree, but a specific value has not been determined. A study is currently underway to determine the probable maximum flood elevation at BFN prior to identification of this previously unanalyzed condition. Upon completion of the analysis, TVA will submit a supplement to this LER with the results of the additional analysis of safety consequences.

Since installation of the HESCO modular flood barriers, the analyzed conditions at BFN regarding PMF are within design and licensing basis limitations. TVA believes that the interim actions completed in December 2009 will prevent the overtopping and failure of the embankments.

A. Availability of systems or components that could have performed the same function as the components and systems that failed during the event:

Based on current analysis there are no components or systems that would have failed during a postulated PMF event.

B. For events that occurred when the reactor was shut down, availability of systems or components needed to shutdown the reactor and maintain safe shutdown conditions, remove residual heat, control the release of radioactive material, or mitigate the consequences of an accident:

Based on current analysis there are no components or systems needed to shutdown the reactor and maintain safe shutdown conditions, remove residual heat, control the release of radioactive material, or mitigate the consequences of an accident that would have failed during a postulated PMF event.

C. For failure that rendered a train of a safety system inoperable, an estimate of the elapsed time from discovery of the failure until the train was returned to service:

Based on current analysis there are no components or systems that would have rendered a train of a safety system inoperable during a postulated PMF event.

VI. Corrective Actions - Corrective Actions are being managed by TVA's corrective action program under Problem Evaluation Report (PER) 682212.

## LICENSEE EVENT REPORT (LER)

CONTINUATION SHEET

CONTINUATION SIEEL									
FACILITY NAME (1)	DOCKET (2)	L	ER NUMBER (6	PAGE (3)					
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	,				
Browns Ferry Nuclear Plant, Unit 1	05000259	2013	001	00	7 of 8				

#### NARRATIVE

#### A. Immediate Corrective Actions:

In July and August 2009, TVA implemented interim measures to mitigate impacts of the potential increase in PMF levels. River Operations procedures were modified to require site notifications if greater than or equal to five inches of average rainfall over 72 hours occurs over the Fort Loudoun/Tellico dam watershed area. At the same rainfall threshold, TVA

would mobilize the necessary heavy equipment at the Fort Loudon Marina Saddle dam to effect the saddle dam removal to preserve the integrity of Fort Loudon Dam. During this period, TVA also began installation of HESCO modular flood barriers on the Cherokee, Fort Loudoun, Tellico, and Watts Bar dams. Post-HESCO PMF elevations at the BFN plant are within the Updated Final Safety Analysis Report (UFSAR) requirements.

# B. Corrective Actions to Prevent Recurrence or to reduce probability of similar events occurring in the future:

- Revise the Conduct of the Engineering Organization procedure, to include a Flood Protection Program within the Corporate Nuclear Engineering Organization with the primary function to ensure that the nuclear plant critical safety systems are protected from all postulated flooding conditions.
- 2. Develop a formal Flood Protection Program Management Implementing procedure or procedures. This procedure would (for example) define the Flood Protection Program policy, ownership of the procedures, roles and responsibilities; identify nuclear regulatory requirements; establish governance and oversight expectations, periodic program reviews, training and qualification requirements; and implement flood protection change control board process, and program health reports.
- 3. Develop a Flood Protection Program Design Standard(s) or Design Guide(s) in accordance with engineering programs and processes to control flood protection calculations.
- 4. Formalize the elements of engineering technical rigor in the Conduct of the Engineering Organization procedure.
- Create a formal documented risk management process for all engineering products, informed by INPO 12-008, Excellence in Integrated Risk Management, which includes flood related issues to evaluate including river system operation changes, nuclear plant design changes, design input changes, procedure changes impacting flood protection, Environmental and/or National Environmental Policy Act (NEPA), and Project Management.
- 6. The TVA Nuclear Organization will implement an upper tier integrated risk management process, informed by INPO 12-008.

#### VII. Additional Information

#### A. Previous Similar Events at the Same Plant

A search of BFN Licensee Event Reports (LERs) for Units 1, 2, and 3 for the last several years did not identify any similar events.

A search was performed on the BFN corrective action program. Similar PERs related to the condition reported in this LER are PERs 147337, 158381, and 212253. These PERs involve conditions related to PMF calculations. A review of the corrective action for these PERs

NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

(10-2010)

## LICENSEE EVENT REPORT (LER)

CONTINUATION SHEET

FACILITY NAME (1)	DOCKET (2)	L	ER NUMBER (6	)	PAGE (3)				
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
Browns Ferry Nuclear Plant, Unit 1	05000259	2013	001	00	8 of 8				

#### NARRATIVE

concluded that the corrective actions associated with these PERs would not have prevented this event.

### **B.** Additional Information

There is no additional information.

## C. Safety System Functional Failure Consideration

In accordance with Nuclear Energy Institute (NEI) 99-02, this condition is not considered a safety system functional failure.

## D. Scram with Complications Consideration

This event did not result in an unplanned scram with complications.

### VIII. Commitments

There are no commitments.