



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

REGULATORY DOCKET FILE COPY

DBB

August 22, 1980

DJS Ltr. #80-28

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #80-32/03L-0, Docket #050-249 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(b), conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation.

D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

AUG 25 1980

*A002
S.1.*

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | 9 | I | D | R | S | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
8 9 14 15 25 26 30 57 CAT 58

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 4 | 9 | 7 | 0 | 7 | 2 | 4 | 8 | 0 | 8 | 0 | 8 | 2 | 1 | 8 | 0 | 9
8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal operations while performing APRM rod block and scram functional tests,
03 | APRM 3 failed to initiate a rod block. This was of minimal safety significance since
04 | channel B and the two remaining instruments in channel A were operable. There was no
05 | effect on public health or safety. Previous occurrence: R.O. 50-237/77-5.
06 |
07 |
08 |

09 | I | A | 11 | E | 12 | A | 13 | I | N | S | T | R | U | 14 | X | 15 | Z | 16
9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | 8 | 0 | 23 | 0 | 3 | 2 | 27 | 0 | 3 | 30 | L | 32 | 0 |
21 22 23 24 26 27 28 29 30 31 32
18 | A | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | Y | 24 | N | 25 | G | 0 | 8 | 0 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The cause was a failure of relay K2, model number 35AT6004R1, which prevented rod
11 | block relay (K5) operation. APRM 3 was bypassed and the relay was replaced. The
12 | instrument was satisfactorily tested, and returned to service. APRM rod block and
13 | scram functional tests will continue to be performed monthly.
14 |

15 | E | 28 | 0 | 9 | 6 | 29 | NA | 30 | B | 31 | Operator Observation | 32
8 9 10 12 13 44 45 46 80

16 | 7 | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 44 45 80

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 11 12 13 80

18 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 11 12 80

19 | Z | 42 | NA | 43
7 8 9 11 12 80

20 | N | 44 | NA | 45
7 8 9 10 80

NRC USE ONLY