

A 6/12/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-220

REC: GRIER B H
NRC

ORG: SCHNEIDER R R
NIAGARA MOHAWK PWR

DOC DATE: 06/01/78
DATE RCVD: 06/08/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-220/78-019) ON 05/22/78 CONCERNING
MAINTANANCE SURVEILLANCE TEST N1-MST-V1, FOUND HYDRAULIC SNUBBER 31-HS-1 HAD
FAILED, CAUSED BOTTOM NUT ON THE PIPE COLLAR FELL OFF... W/ATT.

PLANT NAME: NINE MILE PT - UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: PL

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#3 BC**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL
I & E**W/2 ENCL
I & C SYSTEMS BR**W/ENCL
NOVAK/CHECK**W/ENCL
AD FOR ENG**W/ENCL
HANAUER**W/ENCL
AD FOR OPER TECH**W/ENCL
ENGINEERING BR**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
EMERGENCY PLAN BR**W/ENCL
EEB**W/ENCL
PLANT SYSTEMS BR**W/ENCL
AD FOR PLANT SYSTEMS**W/ENCL
REACTOR SAFETY BR**W/ENCL
VOLLMER/BUNCH**W/ENCL
POWER SYS BR**W/ENCL

EXTERNAL:

LPDR'S
OSWEGO, NY**W/ENCL
TIC**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

COPIES NOT SUBMITTED PER
REGULATORY GUIDE 10.1

Aoff

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P+1P

CONTROL NBR: 781600325

***** THE END *****



—

• •

NI 7 200000
NI 1 1000000

NMP-0163

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

June 1, 1978

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit Licensee Event Report, LER 78-19, which is in violation of Section 6.9.2b(9) of the Technical Specifications.

This event was completed in the format designated in NUREG-0161, dated July 1977.

Very truly yours,

ORIGINAL SIGNED BY R.R. SCHNEIDER

R.R. Schneider
Vice President -
Electric Production

mtm

Enc. (3 copies)

cc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

RECEIVED DISTRIBUTION
SERVICES UNIT
1978 JUN 8 AM 10 25
US NRC
DISTRIBUTION SERVICES
BRANCH

781600325

A002
5/1

OFFICE

SECRETARY OF THE ARMY

WASHINGTON, D. C.

11

11

11

11



11

June 1, 1978

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220
LER 78-019/01T-0

Dear Mr. Grier:

During routine shutdown operations, performance of surveillance test N1-MST-V1, found one hydraulic snubber (31-HS-1) in the Feedwater System disconnected from the pipe collar and empty of fluid.

This snubber is a special Fig. 201 Grinnell Hydraulic Shock and Sway Suppressor, size 2 1/2 inches with a 5 inch stroke.

Vibration in the feedwater pipe had loosened the nut on the bottom of the pipe collar, eventually causing it to drop off. This allowed the hydraulic snubber to disconnect from the collar. A failed piston cylinder teflon o-ring resulted in the fluid loss.

In accordance with the requirement of Technical Specification 3.6.4d, the snubber was replaced prior to reactor startup. This condition resulted in minimal safety implications.

Very truly yours,

ORIGINAL SIGNED BY R.R. SCHNEIDER

R.R. Schneider
Vice President -
Electric Production

mtm



11
12

13
14