

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSIO FACIL: 5 AUTH.N MACHON, RECIP.	R.D. Tennessee NAME RECIPIEN	Nuclear P AFFILIATIO Valley A NT AFFILIA	ower Station, N uthority TION	OTARIZED: NO Unit 2, Tenne ment Control D	ssee 05000260
SUBJECT: Forwards LER 93-011 re operation or condition prohibited by TS which resulted from improper LLRT performed on Unit 2 drywell head seal prior to restart from last refueling outage in May 1993. Investigation of event in progress.					
DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR LENCL SIZE: 3+8 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.					
NOTES:					
	RECIPIENT ID CODE/NAME PD2-4-PD	COPIES LTTR ENC 1 1	RECIPI L ID CODE, WILLIAMS,	/NAME LTTR	IES ENCL 1
INTERNAL:	ACRS AEOD/SPD/RRAB NRR/DE/EELB NRR/DORS/OEAB NRR/DRCH/HICB NRR/DRSS/PRPB NRR/DSSA/SRXB RES/DSIR/EIB	1 1 1 1 1 1 1 1 2 2 1 1	AEOD/ROAB FILE CENT NRR/DE/EM NRR/DRCH/I NRR/DRCH/I NRR/DSSA/I NRR/PMAS/I RGN2 FI	ER 02 1 EB 1 HHFB 1 HOLB 1 SPLB 1 IRCB-E 1	2 1 1 1 1 1
EXTERNAL:	L ST LOBBY WARD NOAC MURPHY, G.A NRC PDR	1 1 1 1 1 1	LITCO BRYONO NOAC POOR NUDOCS FU	E,Ŵ. 1	2 1 1
		•			
				•	1
				:	!
					· I

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 27

A04

P

 \mathbb{R}

1

R

Т

0


U

M

E

N

T





Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35609-2000

R. D. (Rick) Machon Vice President, Browns Ferry Nuclear Plant

November 1, 1994

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

10 CFR 50.73

Dear Sir:

BROWNS FERRY NUCLEAR PLANT (BFN) - UNITS 1, 2, AND 3 - DOCKET NOS. 50-259, 50-260, AND 296 - FACILITY OPERATING LICENSE DPR-33, 52, AND 68 - LICENSEE EVENT REPORT 50-260/93011


The enclosed report provides details concerning an operation or condition prohibited by BFN Technical Specifications. This event resulted from an improper local leak rate test (LLRT) performed on the Unit 2 drywell head seal prior to restart from the last refueling outage in May 1993.

On October 2, 1994, the BFN Unit 2 drywell head was removed as part of a scheduled outage. During this evolution, personnel observed that an excessive amount of a sealing material (RTV-102), used to augment the sealing characteristics of the drywell head O-rings, was displaced from the O-ring grooves. Based on this observation, it was determined that the excessive sealing material resulted in an invalid LLRT having been performed on the O-rings during the Unit 2 Cycle 6 refueling outage.

A TVA Incident Investigation of this event is in progress to determine the root cause and corrective actions to prevent recurrence. In Section VII of this report, TVA notes that the results of this investigation will be provided in a supplemental report.

070049

9411070279 941101 PDR ADDCK 05000260 S PDR SERT!



U.S. Nuclear Regulatory Commission Page 2 November 1, 1994


This report is submitted in accordance with 10 CFR 50.73 (a)(2)(i)(B) due to an invalid Technical Specification required LLRT having been performed.

Sincerely,

R. D. Maghon Site Vice President

Enclosure

cc: See page 3



U.S. Nuclear Regulatory Commission Page 3 November 1, 1994

Enclosure
cc (Enclosure):
 INPO Records Center
 Suite 1500
 1100 Circle 75 Parkway
 Atlanta, Georgia 30339

Paul Krippner American Nuclear Insurers Town Center, Suite 300S 29 South Main Street West Hartford, Connecticut 06107

NRC Resident Inspector Browns Ferry Nuclear Plant Route 12, Box 637 Athens, Alabama 35611

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. J. F. Williams, Project Manager U.S. Nuclear Regulatory Commission One White Flint, North 11555 Rockville Pike Rockville, Maryland 20852

