NRC FORM 591M PART 1 (07-2012) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
 LICENSEE/LOCATION INSPECTED: National Aeronautics & Space Administration John H. Glenn Research Center, Lewis Field 21000 Brookpark Road, Mailstop 6-4 Cleveland, OH 44135-3191 			 2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL, 60532-4352 					
REPORT NUMBER(S) 2018001								
3. DOCKET NUMBER(S)		4. LICENSE NUMB	(S) 5. DATE(S) OF INSPECTION		ION			
030-05626		34-00507-16		July 17, 2018				
LICENSEE: The inspection was a Regulatory Commiss procedures and repre-	an examination of the activities conduct ion (NRC) rules and regulations and th esentative records, interviews with pers in the inspection findings, no violations w	ed under your licen e conditions of you onnel, and observ vere identified.	nse as they relate to radiation safe or license. The inspection consist ations by the inspector. The insp	ety and to compliance w ted of selective examina ection findings are as fo	ith the Nuclear tions of llows:			
 Previous violation(s) closed. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied. 								
Non-cited violation(s) were discussed involving the following requirement(s):								
4. During thi cited in ad with 10 C (Violation	is inspection, certain of your activities, a ccordance with NRC Enforcement Polic FR 19.11. s and Corrective Actions)	as described belov y. This form is a N	v and/or attached, were in violatio IOTICE OF VIOLATION, which m	n of NRC requirements lay be subject to posting	and are being in accordance			
Statement of Corrective Actions								
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). Lunderstand that no further written response to NRC will be required unless specifically requested								
TITLE	PRINTED NAME		SIGNATURE		DATE			
LICENSEE'S REPRESENTATIVE								
NRC INSPECTOR	Deborah A. Piskura, Senior Healt	h Physicist	Delvoreh A Roke	nu	7/17/18			
BRANCH CHIEF	Aaron T. McCraw, Chief, MIB		DAU- For	r ATM	7/23/18			
NRC FORM 591M PART 1 (07-2012)								

U.S. NUCLEAR REGULATORY COMMISSION (07-2012) 10 CFR 2.201 DOCKET File Information SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
1. LICENSEE/LOCATION INSPEC	TED:	2. NRC/REGIONAL OFFICE						
National Aeronautics & John H. Glenn Research 21000 Brookpark Road, Cleveland, OH 44135-31 REPORT NUMBER(S) 2018	Space Administration Center, Lewis Field Mailstop 6-4 191	Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352						
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S	S)	5. DATE(S) OF INSPECTION				
030-05626		34-00507-16		July 17, 2018				
6. INSPECTION PROCEDURES U	SED	7. INSPECTION FOCUS AREAS						
87126		03.01 - 03.07						
	SUPPLEM	ENTAL INSPECT	ION INFORMATION					
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTAC	Т	4. TELEPHONE NUMBER				
03620	5	Chris Blasio, M.S., RSO		(216) 433-6520				
✓ Main Office Inspection Next Inspection Date: July 17, 2023								
✓ Field Office Inspection Plum Brook Station, Sandusky, OH								
Temporary Job Site Inspection								
PROGRAM SCOPE								

This was a routine, announced inspection of NASA's John H. Glenn Research Center operations. The licensee was authorized to use byproduct materials with atomic numbers 3-83, a portable moisture density gauge (use limited to neutron exposure/detection), depleted uranium-molybdenum alloy core segments for material testing, and numerous Sr-90, Am-241, Cs-137 small reference sources for counting studies and instrument calibration. The licensee employed 3,000 individuals at its site, with 20 individuals approved as principle investigators for use of RAM; these principle investigators worked under the supervision of the RSO and another individual who were specifically named on the license. The licensee used its material as needed (at least quarterly) based on the testing schedules to support the agency's space mission. The licensee also possessed generally licensed H-3 exit signs and a Cd-109 lead paint analyzer.

This inspection consisted of interviews with licensee personnel, a review of select records, a tour of the laboratories, and independent measurements. The inspector toured the licensee's facility to evaluate the licensee's measures for material security, hazard communication and exposure control. The inspector noted that all radioactive material was secured; all laboratory and storage areas were key-controlled with access granted only to the authorized individuals. The inspector reviewed other aspects of the licensee's radiation protection program, including audits of the radiation protection program, surveys, rad worker and DOT HAZMAT training, survey instrument calibration, physical inventory, waste management (including radwaste shipments), labeling of containers, and postings.

No violations of NRC requirements were identified during this inspection

Gw for ATM 7/23/10