

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Toledo Cardiology Consultants, Inc. 2409 Cherry Street Suite 100 Toledo, OH 43608</p> <p>REPORT NUMBER(S) 2018001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>
---	---

<p>3. DOCKET NUMBER(S)</p> <p>150-00034</p>	<p>4. LICENSE NUMBER(S)</p> <p>OH-02220490000</p>	<p>5. DATE(S) OF INSPECTION</p> <p>July 19, 2018</p>
---	---	--

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Edward F. Harvey	<i>Edward Harvey</i>	8/2/2018
BRANCH CHIEF	Aaron T. McCraw	<i>By U - for ATM</i>	8/2/18

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Toledo Cardiology Consultants, Inc.
2409 Cherry Street
Suite 100
Toledo, OH 43608

REPORT NUMBER(S) 2018001

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

150-00034

4. LICENSE NUMBER(S)

OH-02220490000

5. DATE(S) OF INSPECTION

July 19, 2018

6. INSPECTION PROCEDURES USED

87130

7. INSPECTION FOCUS AREAS

All

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)

02220

2. PRIORITY

3

3. LICENSEE CONTACT

Tim Depinet, CNMT

4. TELEPHONE NUMBER

(419) 251-3700

Main Office Inspection

Next Inspection Date:

N/A

Field Office Inspection

Temporary Job Site Inspection 15450 Northline Road, Southgate, MI

PROGRAM SCOPE

This was an unannounced inspection of a mobile nuclear medicine service based in Toledo, Ohio that was performing work under reciprocity at a temporary job site in Southgate, Michigan. The licensee provided nuclear stress test services to its client approximately once per month. A licensed radiopharmacy delivered unit doses of Tc-99M to the licensee's main office in Toledo. The nuclear medicine technologist (NMT) then transported all radioactive material to their client's location to perform the administrations. The client provided dedicated space for the licensee to perform stress tests.

The inspector toured the area where administrations were performed and evaluated the licensee's measures for material security, hazard communication, and exposure control. The two licensee personnel on site maintained constant surveillance of all radioactive material and had the ability to lock it in their vehicle if needed. The inspector observed two administrations of Tc-99M for stress tests and noted that the NMT wore appropriate dosimetry and decay corrected the dose to ensure that it was within the acceptable range prior to administration. All potentially contaminated waste generated on site was stored in a receptacle and taken to the licensee's main office for decay-in-storage. The NMT possessed a calibrated survey meter to perform area surveys upon completion of administrations for the day. Licensee staff also demonstrated and discussed procedures for package receipt, area surveys, spill response, and waste handling. Through these observations and discussions, the inspector found the licensee's staff to be knowledgeable of radiation protection principles.

The inspector conducted independent and confirmatory surveys of the facility and found no residual contamination or exposures to members of the public in excess of regulatory limits.

No violations of NRC requirements were identified during this inspection.

GW for
ATM
8/2/18