

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [0] [H] [D] [B] [S] [1] [2] [0] [0] [-] [0] [0] [N] [P] [F] [-] [0] [3] [3] [4] [1] [1] [1] [1] [4] [ ] [ ] [5]
7 8 9 14 15 25 26 30 57 CAT 58

CON'T [0] [1] REPORT SOURCE [L] [6] [0] [5] [0] [-] [0] [3] [4] [6] [7] [1] [1] [1] [3] [7] [9] [8] [1] [2] [1] [1] [7] [9] [9]
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0] [2] During work on Facility Change Request (FCR) 79-378, which added arc suppression diodes
[0] [3] to all non-safety related reactor coolant pump auxiliary relay interlock circuits, it
[0] [4] was found that Couch (Deutsch) relay contacts were driving high inductive loads in 26
[0] [5] nuclear safety related circuits. Although there has been no failures of these relays
[0] [6] in the Class IE circuits, this finding is being reported under T.S. 6.9.1.9. There was
[0] [7] no danger to the health and safety of the public or station personnel. There have
[0] [8] been no relay failures in the nuclear safety related circuits. (NP-33-79-126)

[0] [9] SYSTEM CODE [I] [E] (11) CAUSE CODE [B] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [R] [E] [L] [A] [Y] [X] (14) COMP. SUBCODE [A] (15) VALVE SUBCODE [Z] (16)
7 8 9 10 11 12 13 18 19 20
[17] LER/RO REPORT NUMBER [7] [9] (21) [ ] (23) SEQUENTIAL REPORT NO. [1] [0] [9] (24) OCCURRENCE CODE [0] [3] (28) REPORT TYPE [L] (30) REVISION NO. [0] (32)
ACTION TAKEN [F] (33) FUTURE ACTION [Z] (34) EFFECT ON PLANT [C] (35) SHUTDOWN METHOD [Z] (36) HOURS [0] [0] [0] [0] (37) ATTACHMENT SUBMITTED [Y] (41) NPD-4 FORM SUB. [N] (42) PRIME COMP. SUPPLIER [A] (43) COMPONENT MANUFACTURER [C] [6] [4] [9] (47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[1] [0] The cause of the potential Couch (Deutsch) relay failures has been determined to be an
[1] [1] unexpected inductive surge in the circuit when the contacts open which may
[1] [2] cause a shorting of the relay contacts to ground. As a preventative measure, FCR
[1] [3] 79-378 Suppler nt 1 added arc suppression diodes to all 26 Class IE circuits.

[1] [4] FACILITY STATUS [G] (28) % POWER [0] [0] [0] (29) OTHER STATUS [NA] (30) METHOD OF DISCOVERY [D] (31) DISCOVERY DESCRIPTION [ ] (32)
7 8 9 10 12 13 44 45 46 80

[1] [5] ACTIVITY RELEASED OF RELEASE [Z] (33) CONTENT [Z] (34) AMOUNT OF ACTIVITY [NA] (35) LOCATION OF RELEASE [ ] (36)
7 8 9 10 11 44 45 80

[1] [6] PERSONNEL EXPOSURES NUMBER [0] [0] [0] (37) TYPE [Z] (38) DESCRIPTION [NA] (39)
7 8 9 11 12 13 80

[1] [7] PERSONNEL INJURIES NUMBER [0] [0] [0] (40) DESCRIPTION [NA] (41) 1592 218
7 8 9 11 12 13 80

[1] [8] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [NA] (43)
7 8 9 10 80

[1] [9] PUBLICITY ISSUED [N] (44) DESCRIPTION [NA] (45) 7912170303 NRC USE ONLY
7 8 9 10 80

TOLEDO EDISON COMPANY  
DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE  
SUPPLEMENTAL INFORMATION FOR LER NP-33-79-126

DATE OF EVENT: November 13, 1979

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Couch (Deutsch) relays were driving high inductive surge levels in certain nuclear safety related circuits

Conditions Prior to Occurrence: The unit was in Mode 5, with Power (MWT) = 0, and Load (Gross MWE) = 0.

Description of Occurrence: During work on Facility Change Request (FCR) 79-378, which added arc suppression diodes to all non-safety related reactor coolant pump auxiliary relay interlock circuits, it was found that Couch (Deutsch) relay contacts were driving high inductive loads in twenty-six (26) nuclear safety related circuits. Although there have been no failures of these relays in the Class IE circuits, this finding is being reported under Technical Specification 6.9.1.9.

Designation of Apparent Cause of Occurrence: The cause of the potential Couch (Deutsch) relay failures has been determined to be an unexpected inductive surge in the circuit when the contacts open which may cause a shorting of the relay contacts to ground. The initial design did not anticipate the surge in the Class IE circuits.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. There has been no relay failures in the nuclear safety related circuits.

Corrective Action: As a preventative measure, FCR 79-378 Supplement 1 added arc suppression diodes to all twenty-six (26) Class IE circuits. This further assures the operability of the circuits by providing a path for the discharge of the energy in the coil through the diode rather than through the contacts of the interrupting relay.

Failure Data: There have been no previous relay failures in Class IE circuits due to an inductive surge in the circuits. However, in the non-safety related reactor coolant pump auxiliary relay circuit, there has been a failure; refer to Licensee Event Report NP-33-79-121.

LER #79-109

1592 219