



ATTACHMENT TO LICENSEE EVENT REPORT 81-33/01T-0

COMMONWEALTH EDISON COMPANY (CWE)

DRESDEN UNIT #2

DOCKET # 050-237

While blowing down HPCI steam supply line, with HPCI on the turning gear, the auxillary oil pump tripped and the motor was found to be burned. HPCI was declared inoperable and the required surveillances were begun. This event was of minimal safety significance, since all remaining ECCS systems were available. This is the first occurrence of this type. HPCI system control circuits related to the operation of this pump, were tested with no abnormalities noted.

The cause of the failure is unknown. Investigation is continuing to determine the reason for the motor failure. The motor was rewound and tested satisfactorily. HPCI system was returned to service after repairs. A supplemental LER will be submitted when additional information is available.