

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: I L D R S 2; LICENSE NUMBER: 000-0000000-000; LICENSE TYPE: 41111; CAT 58: 4

REPORT SOURCE: L; DOCKET NUMBER: 05000237; EVENT DATE: 040983; REPORT DATE: 050483

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During unit refueling, Reactor Building Fuel Pool Channel "A" High Radiation alarm activated causing the Reactor Building Vent System to trip and isolate which initiated Standby Gas Treatment. Safety implications are minimal since all systems functioned as designed. There was no effect to public health and safety. This is the first occurrence of this kind at Dresden.

SYSTEM CODE: MC; CAUSE CODE: E; CAUSE SUBCODE: A; COMPONENT CODE: RELAYX; COMP SUBCODE: A; VALVE SUBCODE: Z; LER NO REPORT NUMBER: 83; SEQUENTIAL REPORT NO.: 025; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 0; ACTION TAKEN: A; FUTURE ACTION: Z; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: N; NRC-4 FORM SUB: N; PRIME COMP SUPPLIER: N; COMPONENT MANUFACTURER: G080

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

Relay coil 1705-105 in panel 902-40 burned out, thus tripping Reactor Building Vent System which initiated Standby Gas Treatment. The relay coil was replaced and the system returned to normal. No further corrective action deemed necessary.

FACILITY STATUS: H; % POWER: 000; OTHER STATUS: N/A; METHOD OF DISCOVERY: A; DISCOVERY DESCRIPTION: Operator Observation

ACTIVITY CONTENT: Z; AMOUNT OF ACTIVITY: N/A; LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES: NUMBER: 000; TYPE: Z; DESCRIPTION: N/A

PERSONNEL INJURIES: NUMBER: 000; DESCRIPTION: N/A

LOSS OF OR DAMAGE TO FACILITY: TYPE: Z; DESCRIPTION: N/A

PUBLICITY: ISSUED: N; DESCRIPTION: N/A

NAME OF PREPARER: S. Merritt

PHONE: (815) 942-2920 x550

8305170140 830504 PDR ADOCK 05000237 PDR