

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I 2100 RENAISSANCE BOULEVARD, SUITE 100 KING OF PRUSSIA, PENNSYLVANIA 19406-2713

February 12, 2020

Mr. Eric Carr President and Chief Nuclear Officer PSEG Nuclear, LLC. P.O. Box 236 Hancock's Bridge, NJ 08038

SUBJECT: SALEM NUCLEAR GENERATING STATION, UNITS 1 AND 2 – DESIGN BASIS ASSURANCE INSPECTION (TEAMS) INSPECTION REPORT 05000272/2020011 AND 05000311/2020011

Dear Mr. Carr:

On January 30, 2020, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at Salem Nuclear Generating Station, Units 1 and 2 and discussed the results of this inspection with Mr. Charles McFeaters and other members of your staff. The results of this inspection are documented in the enclosed report.

No findings or violations of more than minor significance were identified during this inspection.

This letter, its enclosure, and your response (if any) will be made available for public inspection and copying at <u>http://www.nrc.gov/reading-rm/adams.html</u> and at the NRC Public Document Room in accordance with Title 10 of the *Code of Federal Regulations* 2.390, "Public Inspections, Exemptions, Requests for Withholding."

Sincerely,

/**RA**/

Mel Gray, Chief Engineering Branch 1 Division of Reactor Safety

Docket Nos. 05000272 and 05000311 License Nos. DPR-70 and DPR-75

Enclosure: As stated

cc w/ encl: Distribution via LISTSERV®

SUBJECT: SALEM NUCLEAR GENERATING STATION, UNITS 1 AND 2 – DESIGN BASIS ASSURANCE INSPECTION (TEAMS) INSPECTION REPORT 05000272/2020011 AND 05000311/2020011 DATED FEBRUARY 12, 2020

| DISTRIBUTION w/encl: | |
|---------------------------|-----------------|
| DLew, RA | (R1ORAMAIL Res) |
| RLorson, DRA | (R1ORAMAIL Res) |
| DCollins, DRP | (R1DRPMAIL Res) |
| BWelling, DRP | (R1DRPMAIL Res) |
| JYerokun, DRS | (R1DRSMAIL Res) |
| PKrohn, DRS | (R1DRSMAIL Res) |
| MFerdas, DRP | |
| BBickett, DRP | |
| PFinney, DRP | |
| JHawkins, DRP, SRI | |
| MHardgrove, DRP, RI | |
| SCalabrese, DRP | |
| OLopez-Santiago, RI, OEDO | |
| RidsNrrPMSalem Resource | |
| RidsNrrDorlLpl1 Resource | |
| ROPreports Resource | |
| | |

DOCUMENT NAME: G:\DRS\Engineering Branch 1\-- Kulp\Salem 20-011.docx ADAMS ACCESSION NUMBER: ML20044C865

| SUNSI Review | | | Publicly Availat | | |
|--------------|---------|----------|------------------|--|--|
| OFFICE | RI/DRS | RI/DRP | RI/DRS | | |
| NAME | JKulp | BBickett | MGray | | |
| DATE | 2/12/20 | 2/12/20 | 2/12/20 | | |

OFFICIAL RECORD COPY

U.S. NUCLEAR REGULATORY COMMISSION Inspection Report

| Docket Numbers: | 05000272 and 05000311 |
|------------------------|---|
| License Numbers: | DPR-70 and DPR-75 |
| Report Numbers: | 05000272/2020011 and 05000311/2020011 |
| Enterprise Identifier: | I-2020-011-0004 |
| Licensee: | PSEG Nuclear, LLC. |
| Facility: | Salem Nuclear Generating Station, Units 1 and 2 |
| Location: | Hancocks Bridge, NJ |
| Inspection Dates: | January 13, 2020 to January 30, 2020 |
| Inspectors: | C. Baron, Contractor J. DeBoer, Reactor Inspector A. Della Greca, Contractor J. Kulp, Senior Reactor Inspector A. Patel, Senior Reactor Inspector J. Schoppy, Senior Reactor Inspector |
| Approved By: | Mel Gray, Chief Engineering Branch 1 Division of Reactor Safety |

SUMMARY

The U.S. Nuclear Regulatory Commission (NRC) continued monitoring the licensee's performance by conducting a design basis assurance inspection (teams) at Salem Nuclear Generating Station, Units 1 and 2, in accordance with the Reactor Oversight Process. The Reactor Oversight Process is the NRC's program for overseeing the safe operation of commercial nuclear power reactors. Refer to https://www.nrc.gov/reactors/operating/oversight.html for more information.

List of Findings and Violations

No findings or violations of more than minor significance were identified.

Additional Tracking Items

None.

INSPECTION SCOPES

Inspections were conducted using the appropriate portions of the inspection procedures (IPs) in effect at the beginning of the inspection unless otherwise noted. Currently approved IPs with their attached revision histories are located on the public website at http://www.nrc.gov/reading-rm/doc-collections/insp-manual/inspection-procedure/index.html. Samples were declared complete when the IP requirements most appropriate to the inspection activity were met consistent with Inspection Manual Chapter (IMC) 2515, "Light-Water Reactor Inspection Program - Operations Phase." The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel to assess licensee performance and compliance with Commission rules and regulations, license conditions, site procedures, and standards.

REACTOR SAFETY

71111.21M - Design Bases Assurance Inspection (Teams)

The inspectors evaluated the following components and listed applicable attributes, permanent modifications, and operating experience:

<u>Design Review - Risk-Significant/Low Design Margin Components (IP Section 02.02)</u> (4 Samples)

- (1) 1B Emergency Diesel Generator (Mechanical)
 - Material condition and installed configuration (e.g., visual inspection/walkdown)
 - Normal, abnormal, and emergency operating procedures
 - Consistency among design and licensing bases and other documents/procedures
 - System health report, maintenance effectiveness and records, and corrective action history
 - Design calculations
 - Surveillance testing and recent test results
 - Equipment protection from fire, flood, and water intrusion or spray
 - Heat removal cooling water and ventilation
 - Energy sources, fuel and air (e.g., engine start, operation, and control)

The team used Appendix B guidance for *Valves, Pumps, Instrumentation, and As-Built System*.

(2) Unit 2 Motor Driven Auxiliary Feedwater Pump

- Material condition and installed configuration (e.g., visual inspection/walkdown)
- Normal, abnormal, and emergency operating procedures
- Consistency among design and licensing bases and other documents and procedures
- System health report, maintenance effectiveness and records, and corrective action history
- Equipment/environmental controls and qualification
- Operator actions
- Design calculations

- Surveillance testing and recent test results
- Range, accuracy, and setpoint of installed instrumentation
- Equipment protection from fire, flood, and water intrusion or spray
- Heat removal ventilation

The team used Appendix B guidance for *Valves, Pumps, Instrumentation, and As-Built System*.

- (3) 1B 4KV Switchgear
 - Material condition and installed configuration (e.g., visual inspection/walkdown)
 - Normal, abnormal, and emergency operating procedures
 - Consistency among design and licensing bases and other documents and procedures
 - System health report, maintenance effectiveness and records, and corrective action history
 - Switchgear bus, breaker, and cable sizing
 - Control logic and control power adequacy
 - Equipment vendor documentation
 - Environmental controls and seismic qualification
 - Operator actions
 - Transformer tap settings and degraded grid/voltage drop calculation
 - Load flow analysis
 - Adequacy of electrical power supply for motor and controls
 - Short circuit calculation
 - Overload and short circuit protective relays setting
 - Protection coordination, load in-rush and full load current
 - Range, accuracy, and setpoint of installed instrumentation
 - Technical Specification required surveillance testing and recent test results
 - Component adequacy for minimum voltage

The team used Appendix B guidance for *Valves, Pumps, Instrumentation, and As-Built System*.

- (4) 11CC16 Residual Heat Removal Heat Exchanger Component Cooling Water Isolation Motor Operated Valve
 - Material condition and installed configuration (e.g., visual inspection/walkdown)
 - Normal, abnormal, and emergency operating procedures
 - Consistency among design and licensing bases and other documents and procedures
 - System health report, maintenance effectiveness and records, and corrective action history
 - Control logic
 - Equipment/environmental controls and qualification
 - Operator actions
 - Design calculations
 - Surveillance testing and recent test results
 - Adequacy of electrical power supply for motor and controls

- Thermal overload protection settings
- Protection coordination; Load in-rush and full load current
- Equipment protection from fire, flood, and water intrusion or spray
- Heat removal cooling water and ventilation
- Contactor and fuse ratings; Component adequacy for minimum voltage
- Seismic qualification

The team used Appendix B guidance for *Valves, Pumps, Instrumentation, and As-Built System*.

Design Review - Large Early Release Frequency (LERFs) (IP Section 02.02) (1 Sample)

- (1) Unit 1 Containment Pressure and Vacuum Relief Isolation Valves (1VC5 and 1VC6)
 - Material condition and installed configuration (e.g., visual inspection/walkdown)
 - Normal, abnormal, and emergency operating procedures
 - Consistency among design and licensing bases and other documents and procedures
 - Maintenance records and corrective action history
 - Control logic
 - Equipment/environmental controls and qualification
 - Operator actions
 - Design calculations
 - Surveillance testing and recent test results
 - Adequacy of electrical power supply for motor and controls
 - Range, accuracy, and setpoint of installed instrumentation
 - Heat removal cooling water and ventilation
 - Energy sources, air

The team used Appendix B guidance for *Valves, Pumps, Instrumentation, and As-Built System*.

Modification Review - Permanent Mods (IP Section 02.03) (5 Samples)

- (1) 80111452, Salem 2 Nuclear Instrumentation Upgrade
- (2) 80109929, Mitigating Systems Performance Indicator Non-Safety Related Auxiliary Feedwater Pump Modification
- (3) 80116286, Auxiliary Feedwater Room Cooler Controls Replacement
- (4) 80116637, Unit 2 Solid State Protection System Train A Wiring Rework Per TB-13-7
- (5) 80110461, 11, 21, & 22 Service Water Return Header

Review of Operating Experience Issues (IP Section 02.06) (3 Samples)

- (1) NRC Information Notice 19-02, Emergency Diesel Generator Excitation System Diode Failures, dated June 3, 2019
- (2) NRC Information Notice 15-01, Degraded Ability to Mitigate Flooding Events, dated January 9, 2015
- (3) NRC Information Notice 19-08 Flow Accelerated Corrosion Events, dated October 8, 2019

INSPECTION RESULTS

No findings were identified.

EXIT MEETINGS AND DEBRIEFS

The inspectors verified no proprietary information was retained or documented in this report.

• On January 30, 2020, the inspectors presented the design basis assurance inspection (teams) inspection results to Mr. Charles McFeaters and other members of the licensee staff.

DOCUMENTS REVIEWED

| Inspection Procedure | Туре | Designation | Description or Title | Revision or Date |
|-------------------------|-------------------|----------------------|---|---------------------|
| 71111.21M | Calculations | 317099(15)-01 | Weak Link and Seismic Analysis Reports | Revision 1 |
| | | ES-13-006(Q) | Breaker and Relay Coordination Calculation Safety-Related AC System | Revision 3 |
| | | ES-15.017(Q) | Salem Unit 1 & 2 Analytical Voltage Analysis | Revision 3 |
| | | S-C-CAN-MDC- 2144 | Minimum Containment Air Pressure Prior to a LOCA | Revision 1 |
| | | SC-CBV006-01 | Containment Building Differential Pressure Indication LOOP Uncertainty | Revision 3 |
| | Corrective Action | 20839697 | | |
| | Documents | 20843273 | | |
| | Resulting from | 20843274 | | |
| | Inspection | 20843289 | | |
| | | 20843418 | | |
| | | 20843489 | | |
| | | 20843617 | | |
| | | 20843640 | | |
| | | 20843676 | | |
| | | 20843677 | | |
| | | 20843680 | | |
| | | 20843689 | | |
| | | 20843759 | | |
| | | 20843800 | | |
| | | 20843808 | | |
| | | 20843831 | | |
| | | 20843835 | | |
| | | 20843837 | | |
| | | 20843849 | | |
| | | 20843904 | | |
| | | 20843905 | | |
| | | 20843906 | | |
| | | 20843907 | | |

| Inspection Procedure | Туре | Designation | Description or Title | Revision or Date |
|-------------------------|-------------|-------------|---|---------------------|
| | | 20843908 | | |
| | | 20843962 | | |
| | | 20843974 | | |
| | | 20843982 | | |
| | | 20844003 | | |
| | | 20844005 | | |
| | | 20844017 | | |
| | | 20844059 | | |
| | | 20844060 | | |
| | | 20844105 | | |
| | | 20844131 | | |
| | | 20844146 | | |
| | | 20844147 | | |
| | | 20844154 | | |
| | | 20844157 | | |
| | | 20844157 | | |
| | | 20844165 | | |
| | | 20844171 | | |
| | | 20844181 | | |
| | | 20844182 | | |
| | | 20844194 | | |
| | | 20844197 | | |
| | | 20844240 | | |
| | | 20844244 | | |
| | | 20844252 | | |
| | | 20844264 | | |
| | | 20844321 | | |
| | | 20844322 | | |
| | Engineering | 80096586 | Unit 1 & Unit 2 SSPS Circuit Card Upgrade | Revision 2 |
| | Changes | 80109929 | Mitigating Systems Performance Indicator Non-Safety Related Auxiliary Feedwater Pump Modification | Revision 1 |
| | | 80110461 | 11, 12, 21, and 22 Service Water Nuclear Return Header Isolation Valve, Access Branch, and WEKO Seal | Revision 2 |

| Inspection Procedure | Туре | Designation | Description or Title | Revision or Date |
|-------------------------|---------------|---------------------------|---|---------------------|
| | | 80110461 | No. 11, 12, 21, and 22 Service Water Nuclear Return Header Isolation Valve and Access Branch Pipe and WEKO Seal Installation 50.59 Review | Revision 1 |
| | | 80111452 | Salem 2 Nuclear Instrumentation Upgrade | Revision 2 |
| | | 80116286 | Auxiliary Feedwater Room Cooler Controls Replacement | Revision 0 |
| | | 80116637 | Unit 2 SSPS Train A Wiring Rework per TB-13-7 | Revision 0 |
| | Miscellaneous | IST-SC-INT5 Table 3-1 | Inservice Testing Program Plan Valve Test Table | Revision 0 |
| | | LR-N-17-006 | PSEG Letter to USNRC, "Focused Evaluation of External Flooding for Salem Generating Station, Units 1 and 2" | 6/30/2017 |
| | | S1.0P-ST.DG- 0013 | 1B Diesel Generator Endurance Run | 4/11/2019 |
| | | TB-13-7 | Westinghouse Technical Bulletin, SSPS New Design Universal Logic Board and Safeguards Driver Board 48 VDC Input | 12/10/2013 |
| | Procedures | ER-AA-430 | Conduct of Flow Accelerated Corrosion Activities | Revision 9 |
| | | ER-AA-430-1001 | Guidelines For Flow Accelerated Corrosion Activities | Revision 11 |
| | | OP-AA-102-106 | Operator Response Time Program | Revision 0 |
| | | S1.MD-FT.4KV- 0002(Q) | ESFAS Instrumentation Functional Test 1B 4KV Vital Bus Undervoltage | Revision 31 |
| | | S1.OP-AB.LOCA- 0001(Q) | Shutdown LOCA | Revision 7 |
| | | S1.OP-AB.ZZ- 0002 | Flooding | Revision 4 |
| | | S1.OP-SO.CBV- 0002 | Containment Pressure – Vacuum Relief System Operation | Revision 21 |
| | | S1.OP-SO.DG- 0002 | 1B Diesel Generator Operation | Revision 41 |
| | | S1.OP-ST.4KV- 0001(Q) | Electrical Power Systems, 4KV Vital Bus Transfer | Revision 16 |
| | | S1.OP-ST.CBV- 0001 | Inservice Testing Containment Ventilation Valves | Revision 8 |
| | | S1.RA-ST.CBV- 0001 | Inservice Testing Containment Valves Acceptance Criteria | Revision 18 |

| Inspection Procedure | Туре | Designation | Description or Title | Revision or Date |
|-------------------------|-------------|-------------------------|--|---------------------|
| | | S2.OP-ST.AF- 0002(Q) | Inservice Testing- 22 Auxiliary Feedwater Pump | Revision 18 |
| | | SC.OP-PT.AF- 0001(Z) | Testing the MSPI Pump and Diesel | Revision 0 |
| | Work Orders | 60142009 | | |
| | | 70209851 | | |