

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | J | O | C | P | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T
 0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 1 | 9 | 7 | 0 | 5 | 0 | 7 | 8 | 2 | 8 | 0 | 6 | 0 | 7 | 8 | 2 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During surveillance testing, the thermocouple for safety valve NR28J was
 0 3 | found open. The acoustic monitor for this valve and the two adjacent
 0 4 | valves were all operable, and the setpoint of one of the adjacent
 0 5 | monitors was reduced in accordance with Tech. Spec. section 3.13.B.2.
 0 6 | Since the appropriate actions were taken, the associated acoustic monitor
 0 7 | was operable, and the thermocouple acts as a backup for the acoustic,
 0 8 | the safety significance of the event is considered minimal.

0 9 | I | B | 11 | E | 12 | A | 13 | I | N | S | T | R | U | 14 | E | 15 | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
 17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | 23 | 24 | 0 | 2 | 6 | 25 | 26 | 27 | 0 | 3 | 28 | 29 | L | 30 | 31 | 0 | 32 | 33
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 18 | A | 19 | Z | 20 | 33 | 34 | Z | 35 | 36 | Z | 37 | 21 | 38 | 0 | 0 | 0 | 0 | 39 | 40 | Y | 41 | 23 | 42 | Y | 43 | 24 | 44 | L | 45 | 35 | 46 | X | 9 | 9 | 9 | 47 | 48
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM 308 PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause was attributed to a broken lead wire at the thermocouple. One
 1 1 | of the adjacent valve's acoustic monitor had its setpoint appropriately
 1 2 | reduced in order to comply with the Technical Specifications. The
 1 3 | thermocouple has since been replaced and tested satisfactorily.

1 5 | E | 28 | 0 | 7 | 3 | 29 | NA | 30 | B | 31 | Surveillance Test | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
 1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
ACTIVITY RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
 1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
 1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PERSONNEL INJURIES NUMBER DESCRIPTION
 1 9 | Z | 42 | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
 2 0 | N | 44 | NA | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
PUBLICITY ISSUED DESCRIPTION

NAME OF PREPARER Michael J. Fitzgerald PHONE (609) 971-4896