Mr. Boyce H. Grier, Director Office of Inspection & Enforcement, Region 1 U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

50-2715

Dear Mr. Grier:

This LER refers to the failure of the inboard main steam line 15 1168 dundant outboard isolation valve in accordance with man drain isolation valve to close electrically which resulted in the closing of the redundant outboard isolation valve in accordance with Tech. Spec. 3.7.D.2. Because this valve is inoperable, verification and recording of the position of the redundant isolation valve was begun per Tech. Spec. 4.7.D.2. This is a condition of operating in the degraded mode as permitted by and reportable under Tech. Spec. 6.9.2.b.(2).

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

LIGHT TET ON T
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
P A P B S 2 2 0 0 - 0 0 0 0 0 0 0
CON'T SOURCE L 6 0 5 0 - 0 2 7 7 7 1 0 1 9 7 8 8 1 1 0 8 7 8 9 9 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During start up operations an attempt was made to close the inboard main
steam line drain isolation valve (MO-2-74) using the hand switch in the
old control room. The valve failed to respond. The redundant outboard isolat
ion valve was placed in the closed position. Daily verification and re-
o ording of the outboard valve position was initiated in accordance with
Tech. Spec. 3.7.D.2 and 4.7.D.2. Safety significance is minimal.
Previous similar occurrence LEP 2-78-030/3L-0.
SYSTEM CAUSE CODE SUBCODE SUBC
TO REPORT TO THE TOTAL THE PORT NO. SEQUENTIAL CODE TYPE NO. THE NO. T
ACTION PUTURE FFECT SHUTDOWN HOURS 22 ATTACHMENT NORDA PRIME COMPONENT MANUFACTURER Z (B) A (9) Z (20) Z (21) G (21) (3) Y (24) N (25) L (2 0) 0 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Electrical checks indicated that the Limitorque SMB-000 torque switch on
isolation valve MO-2-74 was defective. The defective torque switch will
be replaced during the next appropriate outage.
(I)
CE L
STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 A STATUS OF DISCOVERY DESCRIPTION 32 A STATUS OF DISCOVERY DESCRIPTION 32
7 8 9 10 12 19 44 45 44
ACTIVITY CONTENT ASSESS AMOUNT OF ACTIVITY (35) 1 6 2 (3) Z (34) N/A LOCATION OF RELEASE (36) N/A 45 46 N/A 45 46
ACTIVITY CONTENT ARELEASE OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 Z (3) Z (34) N/A PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q
ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) 1 6 2 3 3 Z (34) N/A PERSONNEL EXPOSURES NUMBER 1 7 0 0 0 37 Z (38) N/A PERSONNEL INJURIES NUMBER 1 9 PERSONNEL INJURIES NUMBER 1 1 9 0 0 0 40 N/A 1 1 2 80
ACTIVITY CONTENT ARELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 2 3 3 2 (34) N/A PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 1 8 9 1 8 9 1 8 9 1 8 9 1 8 9 1 8 9 1 8 9 1 8 9 1 8 9 1 8 9 1 9 0 0 0 0 40 N/A 1 9 9 1 9 0 0 0 0 0 N/A 1 9 9 1 9 0 0 0 0 0 N/A 1 9 9 1 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
ACTIVITY CONTENT RELEASE OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 2 3 3 2 34 N/A PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 9 PERSON-IEL INJURIES NUMBER DESCRIPTION (41) 1 8 9 PERSON-IEL INJURIES NUMBER DESCRIPTION (41) 1 8 9 11 12 1 COSS OF OR DAMAGE TO FACILITY (43) 1 9 Z 42 N/A

7811160075

50-277 5