LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
-	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 5 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 0 1 1 9 8 2 8 1 2 2 9 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	On January 19, 1982, while performing surveillance requirements to demonstrate
0 3	steam generator operability, indications of tube thinning was detected by eddy
0 4	Current examination. No. 12 Steam Generator required two sample inspections.
0 5	No. 14 Steam Generator required three sample inspections, and reporting as required
0 6	by C-3 result in Technical Specification Table 4.4-2.
0 7	
08	80
7 8	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	17 REPORT NUMBER 8 2 - 0 0 2 - 10 1 X - 2 2 2 2 2 2 2 2 2
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER F 18 X 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 N 25 W 1 2 0 26 33 34 35 36 37 40 41 41 43 42 43 44 44 47 47 47 47 47
110	All tubes degraded above 30% were plugged. Additional exams of Nos. 11 and 13 SG's
111	were conducted and all tubes degraded above 30% were plugged. Tube R44C62 was sent
1 2	to Westinghouse Research and Development Center for chemical and metallurigical testing
1 3	
1 4	
1 5	9 FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 H 28 0 0 0 29 N/A C 31 Eddy Current Examination
	9 10 12 13 44 45 46 CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) Z (33) Z (34) N/A N/A
7 8	9 10 11 44 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 0 0 0 (37) Z (38) N/A
7 B	9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 8	0 0 0 40 N/A
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A B301250365 B30110 PDR ADOCK 05000272 S PDR
7 8	9 10 PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY
2 0	N/A
	NAME OF PREPARER R. Heller PHONE (609) 935-6000 Ext 3078