



PassPort DATABASE INPUTs

Calculation Number: 00-CP-02958M2 Revision: 00

Vendor Calculation Number/Other: N/A Revision: N/A

CCN # N/A QA Yes No Calc Voided: Yes No

Superseded By: N/A Supersedes Calc: N/A

Discipline (Up to 10) L, T, P

Unit (M1, M2, M3)	Project Reference (EWA, DCR or MMOD)	Component Id	Computer Code	Rev. No./ Level No.
M2	N/A	SK0923	N/A	N/A

PMMS CODES*

Structure	System	Component	Reference Calculation	Rev No.	CCN
AB	<i>SWS 2326A</i>	PIP	79-176-250GP	06	

*The codes required must be alpha codes designed for structure, system and component.

Reference Drawing	Sheet	Rev. No.
25203-20150	106	21
25203-20194	923	6

Comments:

NOTE: Avoid multiple item references on a line, e.g., LT 1210 A-D requires four separate lines.

Table of Contents

Sequential Page No.	Page Identification
1	Title Page
2	Passport Input Sheet
3	Table of Contents
4-8	Calculation Body
9-10	Discipline Review Form
11	Attachment 1 (1 page)
11-14	Attachment 2 (3 pages)
15-18	Attachment 3 (4 pages)

TOTAL PAGES = 18

1.0 PURPOSE

The purpose of this calculation is to evaluate the structural integrity of a location of service water piping which was determined to have a service induced flaw. The service water line (24"-JGD-6), which is the discharge header for the reactor building component cooling water (RBCCW) heat exchangers, was determined to have a through-wall leak on the -5' elevation of the Unit 2 Auxiliary Building in the vicinity of the PMW pumps as described in CR M2-00-0155 (Reference 1). This calculation supports operation until a scheduled outage exceeding 30 days or refueling is reached and a code repair can be made.

2.0 BACKGROUND

Generic Letter 90-05 (Reference 2) provides NRC guidance regarding flaws that exceed the code acceptance limits for piping that is in service. Specifically, it permits non-code repairs to be made to Class 3 piping systems provided that, in part, adequate structural integrity can be demonstrated. Generic Letter 90-05 also provides an analytical technique based upon linear fracture mechanics for demonstrating structural integrity.

Recently, the NRC approved use of ASME Section XI, Code Case N-513 (Reference 3) as indicated in the Federal Register dated September 22, 1999 (Volume 64, Number 183, Rules and Regulations, page 51369-51400). This Code Case also provides evaluation criteria for temporary acceptance of flaws in Class 3 piping. This Code Case is limited to moderate energy Class 3 piping and is also based upon linear fracture mechanics. However, this Code Case addresses planar flaws and has limited non-planar flaw geometry size which does not encompass a hole similar to that found in the plant.

3.0 SCOPE

This calculation performs an assessment of structural integrity for the local stress conditions in line 24"-JGD-6, spool piece SK0923, at the location of the flaw. This calculation does not demonstrate design basis qualification but supports continued operation with a temporary non-structural repair. The methods employed include are valid for moderate energy piping systems (design pressure < 275 psig, maximum operating temperature < 200°F).

This calculation is part of the justification for continued operation.

4.0 REFERENCES

4.1 CR M2-00-0155, dated 1/18/00.

4.2 NRC Letter, "Guidance for Performing Temporary Non-Code Repair of ASME Code Class 1, 2, and 3 Piping (Generic Letter 90-05)" dated June 15, 1990.

CRS 2/3/00
AK 2/3/00

4.3 Case N-513, "Evaluation Criteria for Temporary Acceptance of Flaws in Class Three Piping, Section XI, Division 1," approval date August 14, 1997.

4.4 Ultrasonic Examination Straight Beam Measurements, AWO Number M2-00-00899, dated 1/19/00 (Attachment 1).

4.5 NU Calculation No. 79-176-250GP, Revision 06, "Service Water Discharge Header Problem 112," dated 8/17/99.

4.6 Ultrasonic Examination Straight Beam Measurements, AWO Number M2-00-00924, dated 1/20/00 (Attachment 2).

4.7 NU drawing 25303-20150 Sh. 106 Rev. 21, "Millstone Nuclear Power Station-Unit 2, Service Water Return From RBCCW Exchangers."

4.8 NU drawing 25303-20194 Sh. 923 Rev. 6, "Millstone Unit #2, Serv. Water Return Fr. RBCCW Exch."

5.0 ASSUMPTIONS

5.1 The flaw geometry found represents localized corrosion with a hole like appearance extending radially from the inside surface due to a defect in the lining. The diameter appears to be approximately 2 inches (Reference 4.4). A hole of 2.5 inches will be assumed to provide additional conservatism and margin for further degradation.

5.2 The flaw will be assumed to be through-wall for the 2.5 inch assumed length.

6.0 METHOD OF CALCULATION

The structural evaluation of the identified flaw will be performed in accordance with the guidance provided by Generic Letter 90-05. This method utilizes linear fracture mechanics to determine the crack driving force of the assumed crack size. In the case of piping, it postulates that the flaw is circumferentially oriented and the stresses are assumed to be bending stresses. The resultant "K" determined from the closed form solution is compared to a bounding critical stress intensity factor appropriate for the material.

The stresses used in the evaluation of this flaw were obtained from the pipe stress analysis of record (Reference 4.5). The stresses and the flawed location should include the effects of dead weight, pressure, thermal expansion and safe-shutdown earthquake. The node which is closest to the flaw will be used to obtain the stresses and loads. The other material properties and loads required for this information will be extracted from this calculation.

7.0 BODY OF CALCULATION

The equations used in determination of the applied stress intensity factor, K (ksi√in), will be computed based upon the following equations obtained from Reference 4.2 for through-wall flaws.

$$K = 1.4*s*F*(3.1416*a)^{0.5} \quad (\text{ksi}\sqrt{\text{in}})$$

where; F = the geometry factor (dimensionless)
 a = the half crack length (inches)
 s = the stress at the flawed location (ksi)

The geometry factor, F, is determined by the following:

$$F = 1 + A*c^{1.5} + B*c^{2.5} + C*c^{3.5}, \text{ where:}$$

the coefficients of the polynomial distribution are given by:

$$A = -3.26543 + 1.52784*r - 0.072698*r^2 + 0.0016011*r^3$$

$$B = 11.36322 - 3.91412*r + 0.18619*r^2 - 0.004099*r^3$$

$$C = -3.18609 + 3.84763*r - 0.18304*r^2 + 0.00403*r^3$$

$$\text{and } c = a/(3.1416*R) \text{ (non-dimensional)}$$

$$r = R/t_{\min} \text{ (non-dimensional)}$$

In the preceding equations for A, B and C, the variables "R" is the mean radius of the degraded pipe (inches) and the "t_{min}" is interpreted to be the minimum thickness of the remaining pipe. This value of the "t_{min}" will be established based upon review of the ultrasonic inspection data from around the remainder of the section of the pipe. The variable "a" is the half crack length (inches) assumed to be 1.25 inches (2.5inches/2).

A summary of pertinent design information follows.

The flaw location is approximately six feet above the floor on the -5' elevation. Based upon review of the isometric drawing (Reference 4.7), the flaw location is spool piece SK-923 [JGD-6-20] (Reference 4.8).

Pipe Line No. 24"-JGD-6 (References 4.4 and 4.5 page 25)

Design Pressure = 100 psig (Reference 4.5 page 25)

Maximum Operating Temperature = 120°F (Reference 4.5 page 25)

Pipe Size and Schedule = 24 inch schedule 40 (Reference 4.8)

CD 2/9/00

2/9/00

Pipe OD = 24 inches , Nominal Pipe Thickness = 0.688 inches (Reference 4.5 page 35)

Pipe Material = A 53 Gr B seamless steel pipe (Reference 4.8)

The applied stress, s , was determined from review of the B31.1 piping stress analysis (Reference 4.5). Review of the ADLPIPE model was performed to determine the correct nodal location. The vertical run of piping which contains the flaw begins at node 960 and 980 (elbow to elbow, reference 4.5 page 25). Further review (Reference 5, Attachment J, Sheet J12) shows that piping run 970 to 975 provides the closest elevation (4.66 ft above the floor) and consequently Node 975 will be used to represent the flaw loading conditions.

The applied stress, s , at the flawed location (Node 975) is the combination of dead weight, pressure, thermal expansion and design basis earthquake (DBE).

Dead weight + pressure + DBE = 1544 psi = 1.544 ksi (Reference 4.5, Attachment J, Sh. J623)

The thermal expansion stress was obtained based upon the maximum value of bending stress from the parametric of hot run values performed in Reference 5. The maximum thermal stress at node 975 was determined to be "A & C Hot".

Thermal Expansion Stress = 1109 psi = 1.109 ksi (Reference 4.5, Attachment J, Sh. J240.)

The Total Applied Bending Stress, s , = 1.544 ksi + 1.109 ksi = 2.653 ksi

Based upon review of the available ultrasonic inspection information (Reference 4.4 and 4.6), there is a hole-like radial flaw of approximately 2 inches in diameter. Outside this region, the data indicates approximately nominal pipe thickness as would be expected since this is a coated pipe (no general surface corrosion). Review of Reference 7 shows that the minimum readings are O3, O4, P3 and P4 which occur on the periphery of the hole-like flaw. The remaining values approach nominal pipe thickness. Therefore, an average value of 0.691 inch (Ref. 4.8) is appropriate for representing the remaining pipe section. Paint thickness measurements were also taken which reflect an average paint thickness of 10.3 mils. To ensure a conservative pipe thickness a value of 0.031 inch or three times the paint thickness will be subtracted from the average wall thickness providing a " t_{min} " of 0.660 inches (0.691 inch - 0.031 inch).

Computing values,

$$R = (24 \text{ in}/2) - (0.66 \text{ in}/2) = 11.67 \text{ in}$$

$$r = 11.662 \text{ in} / 0.66 \text{ in} = 17.682 \text{ in}$$

$$A = -3.26543 + 1.52784 * 17.682 - 0.072698 * (17.682)^2 + 0.0016011 * (17.682)^3 \\ = 9.87191$$

$$B = 11.36322 - 3.91412 * 17.682 + 0.18619 * (17.682)^2 - 0.004099 * (17.682)^3 \\ = -22.2938$$

$$C = -3.18609 + 3.84763 * (17.682) - 0.18304 * (17.682)^2 + 0.00403 * (17.682)^3 \\ = 29.89865$$

$$\text{Given } a = 1.25 \text{ in, then } c = 1.25 \text{ in} / (3.1416 * 11.67 \text{ in}) = 0.034095$$

Calculating the Shape Factor , F,

$$F = 1 + 9.676647 * (0.034095)^{1.5} + -21.7939 * (0.034095)^{2.5} + 29.40716 * (0.034095)^{3.5} \\ = 1.058$$

Computing K,

$$K = 1.4 * 2.653 \text{ ksi} * 1.058 * (3.1416 * 1.25 \text{ in})^{0.5} = 7.78 \text{ (ksi}\sqrt{\text{in}})$$

Given that the material is a ferritic steel, the lower bound fracture toughness provided by reference 4.2 is 35 ksi $\sqrt{\text{in}}$. Since the applied stress intensity factor is less than the available fracture toughness of 35 ksi $\sqrt{\text{in}}$, crack extension is not expected to occur and structural integrity will be maintained for all the design loads including earthquake.

8.0 SUMMARY OF RESULTS

The flaw found in service water piping line 24-JGD-6, spool piece SK-923, was evaluated for structural integrity using the methods provided by Generic Letter 90-05. This method uses linear elastic fracture mechanics to determine an applied stress intensity factor using all the design loads with DBE and compares it to a lower bound fracture toughness. The applied stress intensity factor of 7.8 ksi $\sqrt{\text{in}}$ is less than the available fracture toughness of 35 ksi $\sqrt{\text{in}}$, crack extension is not expected to occur and structural integrity will be maintained for all the design loads including earthquake.

Calculation Review Comment and Resolution Form

(Sheet 1 of 2)

Calculation Number: 00-CP-02598M2 Revision: 00 CCN N/A

Calculation Title: Structural Integrity of Flaw Found in Service Water Line 24-JGD-6

Calc. Originator: C. Stewart Reviewer (PRINT): G. Gardner

This form is intended to document significant comments and their resolutions. Typographical errors and other editorial recommendations may be marked up in the calculation text and presented to the originator

Review Type **Independent** **Interdiscipline**

Reviewer (SIGN) _____ Date: _____

(signature signifies all comments have been resolved to your satisfaction)

Item	Page/Section	Comments	Response
1	All	Reviewed all pages with only minor editorial comments, incorporated. In addition, prepared alternative evaluation attached.	N/A

CALC 00-CP-02598 M2 REV 00

PG 9 OF 18

Alternative Evaluation of Non-Planar Through-Wall Flaw

This evaluation of the subject flaw is prepared as an alternative to the evaluation performed in accordance with GL 90-05.

ASME Code Case N-597 has been accepted as an alternative by the NRC per letter dated 2/23/1999 for use on Millstone Units 2 and 3. In this case, paragraph -3500(5)(f) states that for low energy Class 3 piping exhibiting through-wall leakage, "evaluation methods and acceptance criteria shall be specified by the Owner." No further requirements are provided.

A reasonable approach for relatively small through-wall flaws in ductile piping materials is the branch reinforcement rules and acceptance criteria as given in the original construction Code, which is ANSI B31.1-1967 for this piping. The Code approach for branch connections is basically an area replacement evaluation, in which the area lost by cutting the hole for the branch piping is compensated for by existing or added reinforcing material surrounding the hole. Any pipe wall thickness not needed for pressure boundary integrity is considered available for reinforcement. A non-planar through-wall flaw is structurally similar to the lost pipe wall area cut out for a branch connection. The Code rules and criteria are specified in paragraph 104.3, "Intersections", in parts 2(b) and 2(c) and are illustrated in Figure 104.3.1(d).

For the subject flaw with a conservatively assumed diameter of 2.5", per 104.3(2)(b) the required reinforcing area, A_{req} is

$$A_{req} = 1.07 t_{mh} d_1$$

where t_{mh} is the header pipe minimum required wall thickness, calculated as 0.079 inches in the main body of the calculation and d_1 is 2.5 inches as assumed

$$A_{req} = (1.07)(0.079)(2.5) = 0.21 \text{ inches}^2$$

The available reinforcing area, considering both sides of the flaw, is calculated as

$$A_1 = 2(d_2)(T_h - \text{mill tolerance} - t_{mh})$$

where for $T_h - \text{mill tolerance}$ we will use the measured wall thickness adjacent to the flaw, 0.65 inches, d_2 is equal to d_1 , and t_{mh} is as stated above

$$A_1 = 2(2.5)(0.650 - 0.079) = 2.85 \text{ inches}^2$$

Since the available reinforcing area greatly exceeds the required reinforcing area:

$$A_1 = 2.85 > A_{req} = 0.21 \text{ inches}^2,$$

the branch reinforcement rules of B31.1 are effectively satisfied and the through-wall flaw is considered structurally stable.

The piping stresses for longitudinal pressure + deadload + DBE loadings at node 970 was calculated as 1,711 psi in the design basis calculation (page J196), compared to an allowable of 34,380 psi (page 62). Since the through-wall flaw constitutes a relatively small reduction in the piping cross section the presence of the flaw is not significant.

In conclusion, the flaw is acceptable from a structural standpoint and occurs at a location of low service stress. Therefore it is acceptable for continued operation.

ATTACHMENT 1 - EXAM DATA SHEET



Northeast Nuclear Energy

ULTRASONIC EXAMINATION
STRAIGHT BEAM MEASUREMENTS

Plant: Millstone	Unit: II	Page: 1 of 1
Region & Zone: 2326A	Exam Data Sheet No: N/A	
Component ID: SK0923	Asset Number: M2-00-00899	
Component Description: VERT. straight pipe	Drawing No: 25203-20150 SH. 106	
Examination Purpose: Eng. Info	Line No: 24"-JGD-6	

Instrument & Settings	
Manufacturer	PANA.
Model No	26 DL Plus
Serial No	92097812
Range	1.000"
Velocity	233 μs
Delay	N/A
Zero Value	494 μs
Cal Tolerance	$\pm .005"$

Calibration Block(s)		
Type	Serial No	Material
step blk.	91-5932	CS
step blk.	91-6373	CS

Component Data	
Component From	
Component Dia.	24"
Attachments	.688"

Calibration Checks		Block Thickness		Instrument Reading	
Type	Time	Min.	Max	Min.	Max
Initial	1445	.100"	.750"	.100"	.750"
Intermediate	N	N	N	N	N
Intermediate	A	A	A	A	A
Final	1510	.100"	.750"	.100"	.750"

Search Unit Data	
Manufacturer	PANA.
Type No.	D791-RM
Serial No.	19510
Frequency	5 MHz.
Size	.312"

Couplant Data	
Brand	SoundSafe
Batch No.	99120 B
MRIR/UTC No.	0000387211

Coatings Factor Data	
Surface Painted	Yes
ACT* mils =	X
ACT X 3 mils =	X

* Average Coating Thickness

Sketch/Comments Area - Attach Photo(s) of Relevant Conditions Separately

Performed UT Scan of 2 Areas around Blistered Paint, recorded a UT thickness range in 2" Area of .060" - .260"

12" Area ^{MCB} ~~.676~~ - .694" $\frac{1}{2}$ " dia. Blistered Paint

2" dia. .060" - .260

12" dia. .676" - .694"

* No paint thickness data taken due Area requiring A Mechanical Patch Based on initial UT, per Eng.

Examiner (print & sign) Michael Braehler / Michael Buhla	Level II	Date 1/18/00
Reviewer (sign) M. Muller	Level III	Date 1/19/00
ANII if Required (sign) N/A	Date	

Level of Use Information



ATTACHMENT 1 - EXAM DATA SHEET



Northeast Nuclear Energy

ULTRASONIC EXAMINATION
STRAIGHT BEAM MEASUREMENTS

Plant <u>MP</u> Unit <u>2</u>	Page <u>1</u> of <u>2</u>
System & Zone No. <u>2326A</u>	Exam Data Sheet No. <u>N/A</u>
Component ID <u>SK0923</u>	AWO Number <u>M2-00-00924</u>
Component Description <u>SPOOL - FROM RBCCW HXR</u>	Drawing No. <u>25203-20194-923</u>
Examination Purpose <u>INFORMATIONAL</u>	Line No. <u>24-JGD-6</u>

Instrument & Settings	
Manufacturer	<u>PANA.</u>
Model No.	<u>26 DL Plus</u>
Serial No.	<u>91034408</u>
Range	<u>1.0"</u>
Velocity	<u>233 μS</u>
Delay	<u>N/A</u>
Zero Value	<u>489 μS</u>
Cal Tolerance	<u>\pm.005"</u>

Calibration Block(s)		
Type	Serial No.	Material
<u>STEP BIK.</u>	<u>91-6475</u>	<u>CS</u>
<u>STEP BIK.</u>	<u>91-6469</u>	<u>CS</u>

Component Data	
Component T _{nom}	<u>.688"</u>
Component Dia.	<u>2.4"</u>
Attachments.	<u>N/A</u>

Calibration Checks		Block Thickness		Instrument Reading	
Type	Time	Min.	Max.	Min.	Max.
Initial	<u>1830</u>	<u>.100"</u>	<u>1.060"</u>	<u>.100"</u>	<u>1.000"</u>
Intermediate	<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>	<u>N</u>
Intermediate	<u>A</u>	<u>A</u>	<u>A</u>	<u>A</u>	<u>A</u>
Final	<u>1905</u>	<u>.100"</u>	<u>1.060"</u>	<u>.100"</u>	<u>1.000"</u>

Search Unit Data	
Manufacturer	<u>PANA.</u>
Type No.	<u>D791-RM</u>
Serial No.	<u>129816</u>
Frequency	<u>5 MHZ</u>
Size	<u>.312"</u>


Couplant Data	
Brand	<u>SOUNDsafe</u>
Batch No.	<u>99120 B</u>
MRIR/UTC No.	<u>0000387211</u>

Coatings Factor Data	
Surface Painted	<u>YES</u>
ACT* mils =	<u>10.3</u>
ACT X 3 mils =	<u>30.9</u>

* Average Coating Thickness

Sketch/Comments Area - Attach Photo(s) of Relevant Conditions Separately

Performed Grid + UT
Around Pipe in leak area.
2" Grid AI-ALS
See Attached For
UT data.



Examiner (print & sign) <u>Michael Brewer / Michael Brewer</u>	Level <u>III</u> Date <u>1/19/00</u>
Reviewer (sign) <u>AJ Puller</u>	Level <u>III</u> Date <u>1/20/00</u>
ANII if Required (sign) <u>N/A</u>	Date <u>N/A</u>

Level of Use Information



Main Section (0)

Rows : 5 Cols : 38 Direction : Clockwise Offset : 0


	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
1	0.694	0.699	0.690	0.687	0.690	0.686	0.697	0.697	0.684	0.700	0.692	0.698	0.698	0.700	0.692	0.685	0.687	0.692	0.691	0.689	0.685
2	0.688	0.692	0.685	0.687	0.684	0.683	0.691	0.694	0.688	0.690	0.698	0.697	0.704	0.700	0.695	0.691	0.693	0.692	0.691	0.690	0.690
3	0.688	0.686	0.689	0.690	0.688	0.683	0.691	0.699	0.694	0.698	0.712	0.706	0.701	0.703	0.662	0.653	0.693	0.695	0.698	0.693	0.691
4	0.687	0.695	0.685	0.686	0.687	0.684	0.695	0.696	0.689	0.691	0.700	0.691	0.719	0.706	0.689	0.636	0.687	0.693	0.691	0.690	0.686
5	0.695	0.687	0.679	0.671	0.659	0.680	0.686	0.680	0.691	0.684	0.690	0.698	0.700	0.695	0.689	0.688	0.687	0.687	0.690	0.690	0.684
ColMx	0.695	0.699	0.690	0.690	0.690	0.686	0.697	0.699	0.694	0.700	0.712	0.706	0.719	0.706	0.695	0.691	0.693	0.695	0.698	0.693	0.691
ColMn	0.687	0.686	0.679	0.671	0.659	0.680	0.686	0.680	0.684	0.684	0.690	0.691	0.698	0.695	0.662	0.636	0.687	0.687	0.690	0.689	0.684
Delta	0.008	0.013	0.011	0.019	0.031	0.006	0.011	0.019	0.010	0.016	0.022	0.015	0.021	0.011	0.033	0.055	0.006	0.008	0.008	0.004	0.007
Ave	0.690	0.692	0.686	0.684	0.682	0.683	0.692	0.693	0.689	0.693	0.698	0.698	0.704	0.701	0.685	0.671	0.689	0.692	0.692	0.690	0.687

	V	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AL
1	0.687	0.686	0.688	0.692	0.693	0.694	0.699	0.708	0.691	0.681	0.690	0.688	0.694	0.687	0.685	0.693	0.694
2	0.691	0.696	0.692	0.689	0.691	0.695	0.706	0.696	0.697	0.692	0.696	0.689	0.688	0.690	0.688	0.688	0.695
3	0.690	0.692	0.689	0.690	0.691	0.699	0.709	0.709	0.701	0.690	0.689	0.690	0.689	0.686	0.686	0.689	0.699
4	0.689	0.692	0.687	0.688	0.692	0.682	0.705	0.695	0.698	0.691	0.690	0.685	0.691	0.689	0.693	0.685	0.682
5	0.686	0.685	0.683	0.687	0.690	0.687	0.692	0.695	0.690	0.692	0.692	0.691	0.685	0.689	0.692	0.683	0.687
ColMx	0.691	0.696	0.692	0.692	0.693	0.699	0.709	0.709	0.701	0.692	0.696	0.691	0.694	0.690	0.693	0.693	0.699
ColMn	0.686	0.685	0.683	0.687	0.690	0.682	0.692	0.695	0.690	0.681	0.689	0.685	0.685	0.686	0.685	0.683	0.682
Delta	0.005	0.011	0.009	0.005	0.003	0.017	0.017	0.014	0.011	0.011	0.007	0.006	0.009	0.004	0.008	0.010	0.017
Ave	0.689	0.690	0.688	0.689	0.691	0.691	0.702	0.701	0.695	0.689	0.691	0.689	0.689	0.688	0.689	0.688	0.691

RowMx	RowMn	Delta	Ave	
1	0.708	0.681	0.027	0.692
2	0.706	0.683	0.023	0.692
3	0.712	0.653	0.059	0.692
4	0.719	0.636	0.083	0.690
5	0.700	0.659	0.041	0.687

Section Summary

Maximum Reading = 0.719 (4, M) Average = 0.691
 Minimum Reading = 0.636 (4, P) Standard Deviation = 0.692
 Total Readings = 190



ATTACHMENT 1



Northeast Nuclear Energy

COATING THICKNESS EXAM DATA SHEET

Plant MP Unit 2
 System 2326A Zone N/A
 AWO No. M2-00-00924
 Exam. Purpose Eng. Info.

Design DWG Number 25203-20194-923
 Component Description SERV WATER FROM RECCW
 Component Identification SK-0924
 Pipe Size 24 INCH

Thickness Meter
 Make/Model Fischer/Deltascop
 RE/PMMS No. N/A
 Serial Number 042-12554A
 Calibration Range 2.93 - 25.8 Mils

Micrometer
 Micrometer PMMS No. 1682
 Serial Number 1682
 Calibration Due Date 2-13-00

Readings

1	<u>10.4</u>	11	<u>8.77</u>	21	<u>7.16</u>
2	<u>7.43</u>	12	<u>10.7</u>	22	<u>8.92</u>
3	<u>11.1</u>	13	<u>9.59</u>	23	<u>10.3</u>
4	<u>9.09</u>	14	<u>10.6</u>	24	<u>12.9</u>
5	<u>11.3</u>	15	<u>7.78</u>	25	<u>12.8</u>
6	<u>13.0</u>	16	<u>12.1</u>	26	<u>10.9</u>
7	<u>13.9</u>	17	<u>8.70</u>	27	<u>9.07</u>
8	<u>11.2</u>	18	<u>9.51</u>	28	<u>11.9</u>
9	<u>9.06</u>	19	<u>7.99</u>	29	<u>11.2</u>
10	<u>10.9</u>	20	<u>11.3</u>	30	<u>10.8</u>

Coating Thickness Minimum 7.16 Maximum 13.9 Average 10.3

Comments

N/A

Examiner (print & sign) Michael Breher / Michael Breher Level III Date 1/19/00
 Reviewer (print & sign) R.J. Fuller / R.J. Fuller Level III Date 1/20/00
 Engineering Reviewer (print & sign) N/A Level N/A Date N/A
 ANII (when applicable) N/A Date N/A

Level III or Designee Signature for Certification _____ Date _____

Safety Evaluation Screen Form [Comm. 4.1.6]

(Sheet 1 of 4)

Unit 2 Document No. 00-CP-02598M2 Revision No. 00 Change No. NZ *NA/AK 1/24/94*

(Attachment 6 Provides Guidance)

A. SUMMARY INFORMATION (Completed by the Preparer)

1. Description of the Proposed Change, Test or Experiment

A degraded condition exists in Unit 2 service water piping spool piece, as documented in CR M2-00-0155. The degraded condition is a localized corrosion of the pipe pressure boundary, resulting in loss of pressure boundary thickness including a small region that is through-wall and permits leakage of service water. The degraded pipe wall is limited to a region about 2 inches in diameter. As permitted by NRC Generic Letter 90-05, an evaluation has been performed in accordance with criteria stated in the letter, with the conclusion that the flaw will remain structurally stable until a Code repair or replacement can be performed at the next outage.

This safety evaluation screening is prepared relative to the determination of the flaw's structural integrity as documented in this calculation. The calculation and this screen do not address the compensatory actions to limit leakage or any other aspects of compliance with GL 90-05; these aspects are considered in DCN DM2-00-0039-00.

B. SCREENING QUESTIONS (Completed by the Preparer)

1. Will implementation of the proposed Change, Test or Experiment require a revision to the Operating License or the Technical Specifications? (If "Yes," complete (a.), go to Section D and sign as Preparer - prior NRC review and approval is required. If "No," complete (b) and go to Question 2.)

Yes (OL or T/S change required) No

a. Reason OL or T/S change required and sections impacted:

b. Reason OL or T/S change not required and sections reviewed:

Evaluation of degraded piping for continued operation is permitted by the NRC in accordance with GL 90-05. The process requires submittal of the evaluation to the NRC and is subject to NRC review and approval. A GL 90-05 request was most recently submitted for Unit 2 in 1994 under letter B14776. There are no licensing provisions or commitments which prohibit implementing the process at Millstone. Therefore the GL 90-05 evaluation is in accordance with the licensing basis, and no change to the license is required.

Reviewed OL and T/S through change 253, T/S section 3/4.4.10.

Searched Licensing Commitment Database keywords "90-05", "flaw", "leak"

2. Is the proposed Change, Test or Experiment fully bounded by the scope of a previously approved Safety Evaluation? (Refer to Section B.2 of Attachment 6 to determine if fully bounded. If "Yes," complete (a.) and (b.), go to Section D and sign as Preparer - a new SE is not required. If "No," go to Question 3.)

Yes (new SE not required) No

a. Identification of previously approved SE:

b. Reason previously approved SE fully bounds proposed activity:

Safety Evaluation Screen Form [Comm. 4.1.6]

(Sheet 2 of 4)

Unit 2 Document No. 00-CP-02598M2 Revision No. 00 Change No. NZ ^{NA, AA 1/24/00}

3. Is it obvious that the proposed Change, Test or Experiment requires a Safety Evaluation?
(If "Yes," a SE is required - complete (a.), go to Section D and sign as Preparer. If "Not Obvious," go to Question 4. If it is not clear, a SE is required.)

Yes (SE required) Not Obvious

a. Reason SE required:

4. Does the proposed activity meet the criteria of a Non-Intent Change to the Facility or procedures as described in the SAR? (Refer to the guidance in Section B.4 of Attachment 6 to determine if Non-intent. If a Non-intent Change, check "Yes," complete (a.) go to Section D, and sign as Preparer - a SE is not required. If "No," go to Question 5.)

Yes (SE not required) No

a. Reason SE not required and SAR sections reviewed:

5. Will implementation of the proposed activity modify the Facility as described in the SAR? (Per the guidance in Section B.5 of Attachment 6, ensure that you check "Yes" if the proposed activity could directly or indirectly as a result of a system interaction, introduce different failure modes or affect the function or reliability of equipment described in the SAR. If "Yes," complete (a.), go to Section D and sign as Preparer. - a SE is required. If "No," complete (b.) and go to Question 6.)

Yes (SE required) No

a. Reason SE required and SAR sections impacted:

b. Basis for "No" and SAR sections reviewed:

The flaw has been identified as a degraded condition under Millstone's corrective actions program, which meets the requirements of 10CFR 50 Appendix B. Since the flaw is scheduled for corrective action at the next available outage of sufficient duration, by the guidance provided in Generic Letter 91-18 Rev.1 the flaw itself is not required to be considered a plant change for the purpose of 10CFR 50.59 evaluations.

Reviewed UFSAR through change 57, 7/16/99, Section 9.7, and TRM through change 53, 1/6/00.

6. Will implementation of the proposed activity modify procedures as described in the SAR? (Refer to the list of supplemental questions in Section B.6 of Attachment 6 to evaluate the need for a SE. If "Yes," complete (a.), go to Section D and sign as Preparer - a SE is required. If "No," complete (b.) and go to Question 7.)

Yes (SE required) No

a. Reason SE required and SAR sections impacted:

b. Basis for "No" and SAR sections reviewed:

The evaluation of the flaw was performed consistent with the existing procedure for GL 90-05 evaluations, specification SP-ST-ME-947 Rev. 1. There are no procedural

Safety Evaluation Screen Form [Comm. 4.1.6]

(Sheet 3 of 4)

NA, AH 1/26/00

Unit 2 Document No. 00-CP-02598M2 Revision No. 00 Change No. NZ

changes required for evaluation of the flaw. Therefore there are no required changes to procedures as described in the SAR.

Reviewed UFSAR through change 57, 7/16/99, Chpt. 12 and Section 9.7, and TRM through change 53, 1/6/00.

7. Will implementation of the proposed activity involve a Test or Experiment not described in the SAR? (Refer to the list of examples in Section B.7 of Attachment 6 to determine the need for a SE. If "Yes," complete (a.), go to Section D and sign as Preparer - a SE is required. If "No," complete (b.), go to Section D and sign as Preparer.)

Yes (SE required) No

a. Reason SE required:

b. Basis for "No" and SAR sections reviewed:

Evaluation of the flaw is a technical activity that does not itself affect operation of the plant. The evaluation activity does not require operation of the plant in any specified manner, and there are no required plant parameter changes. Therefore there is no Test or Experiment associated with the flaw evaluation.

Reviewed UFSAR through change 57, 7/16/99, Chpt. 13 and Section 9.7, and TRM through change 53, 1/6/00.

C. SUMMARY (Completed by the Approver)

1. Is a revision to the technical specifications or operating license required? ("Yes, if Question B.1 checked, "Yes")

Yes No

2. Is a Design Engineering Screening Evaluation per the Design Change Manual Required? (Yes, if proposed Change is an Intent Change to the Facility as described in the SAR)

Yes No Not Applicable

3. Is a new Safety Evaluation required? (Yes, if Question B.1, B.3, B.5, B.6 or B.7 is checked "Yes")

Yes No

4. Is a FSARCR per RAC 03 necessary? (Yes, if responses to Question B.5 or B.6 indicate proposed activity will cause the FSAR description to be incorrect)

Yes No Not Applicable

5. Is the proposed activity fully bounded by a previously approved Safety Evaluation? (Yes, if Question B.2 is checked "Yes")

Yes No

6. Is the Quality Assurance Plan, Emergency Plan or Security Plan affected, requiring an evaluation per RAC 01? (Yes, if response to Question B.5, B.6, or B.7 identifies these portions of the SAR as being affected by the proposed activity)

Yes No Not Applicable

Safety Evaluation Screen Form [Comm. 4.1.6]

(Sheet 4 of 4)


NA AK 1/24/00

Unit 2 Document No. 00-CP-02598M2 Revision No. 00 Change No. NZ

D. APPROVAL

Preparer: GLENN A. GARDNER  Date: 1/24/00
Print and Sign

Reviewer: N/A Date: _____
(if required) Print and Sign

Approver: PROY RB /  Date: 1/26/00
Print and Sign NELSON AZEVEDO