March 17, 2000

Mr. William T. Cottle President and Chief Executive Officer STP Nuclear Operating Company South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, TX 77483

SUBJECT: SOUTH TEXAS PROJECT, UNITS 1 AND 2, RE: COMPLETION OF LICENSING ACTION FOR GENERIC LETTER 98-02, "LOSS OF REACTOR COOLANT INVENTORY AND ASSOCIATED POTENTIAL FOR LOSS OF EMERGENCY MITIGATION FUNCTION WHILE IN A SHUTDOWN CONDITION" (TAC NOS. MA4806 AND MA4807)

Dear Mr. Cottle:

On May 28, 1998, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 98-02 to all holders of operating licenses for Pressurized Water Reactors (PWR), except those who have permanently ceased operations, and have certified that fuel has been permanently removed from the reactor vessel. The NRC issued GL 98-02 to request that PWR licensees evaluate a September 17, 1994, event, which occurred at Wolf Creek, which had the potential to draindown the reactor coolant system (RCS) to the refueling water storage tank (RWST) and, at the same time, render the emergency core cooling system (ECCS) and residual heat removal (RHR) system inoperable by introducing a steam/water mixture to the suction side of the ECCS and RHR pumps. Addressees of GL 98-02 were requested to provide the following information within 180 days: (1) an assessment of whether the addressee's facility is vulnerable to the September 17, 1994, Wolf Creek event, and (2), if the facility is found to be vulnerable, an assessment of the plant-specific 10 CFR Part 50, Appendix B, quality assurance program attributes which will prevent the subject event. If the addressee's facility was determined to be vulnerable, a response to information item (1) was to be provided pursuant to 10 CFR 50.54(f) and 10 CFR 50.4, and the responses to information items (1) and (2) were to be kept in a licensee's retrievable system for use by the NRC staff on an as-needed basis.

In response to GL 98-02, you provided a letter dated November 18, 1998, for South Texas Project (STP), Units 1 and 2. The submittal indicated that STP, Units 1 and 2, were vulnerable to the type of incident which occurred at Wolf Creek and further indicated that the plant evaluation concerning the subject vulnerability (information item (2) of GL 98-02), was being kept in a retrievable licensee system that the NRC can verify on an as-needed or sample basis, in accordance with GL 98-02.

W. Cottle

By letter dated December 2, 1999, the Region IV NRC staff issued NRC Inspection Report No. 50-498/99-18; 50-499/99-18. The subject inspection report contained details of the NRC staff's on-site verification of activities which you undertook in response to GL 98-02 for STP, Units 1 and 2. Specifically, the inspector verified that the licensee had effectively implemented administrative controls, configuration management, and operating procedures to preclude an inadvertent draindown event as described in GL 98-02. STP, Units 1 and 2 utilize three trains of RHR and ECCS. The high head safety injection pumps, low head safety injection pumps, and containment spray pumps take suction from a common header connected to the refueling water storage tank, each with their own isolation valves. The RHR pumps do not take suction from this header. RHR Trains B and C share a cross-connect on the discharge side of the pumps for reactor cavity draindown. Each of these trains include two normally locked closed containment insolation valves on the drain line. The above measures were found by the inspector to be appropriate.

The NRC staff has reviewed your response to GL 98-02 and has concluded that (1) all the information requested by GL 98-02 has been provided, and (2) that your on-site activities adequately addressed the concerns of GL 98-02 for STP, Units 1 and 2; therefore, we consider GL 98-02 to be closed for STP, Units 1 and 2.

Sincerely,

/RA/

John A. Nakoski, Senior Project Manager, Section 1 Project Directorate IV & Decommissioning Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket Nos. 50-498 and 50-499

cc: See next page

South Texas, Units 1 & 2

CC:

Mr. Cornelius F. O'Keefe Senior Resident Inspector U.S. Nuclear Regulatory Commission P. O. Box 910 Bay City, TX 77414

A. Ramirez/C. M. Canady City of Austin Electric Utility Department 721 Barton Springs Road Austin, TX 78704

Mr. M. T. Hardt Mr. W. C. Gunst City Public Service Board P. O. Box 1771 San Antonio, TX 78296

Mr. G. E. Vaughn/C. A. Johnson Central Power and Light Company P. O. Box 289 Mail Code: N5012 Wadsworth, TX 74483

INPO

Records Center 700 Galleria Parkway Atlanta, GA 30339-3064

Regional Administrator, Region IV U.S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011

D. G. Tees/R. L. Balcom Houston Lighting & Power Co. P. O. Box 1700 Houston, TX 77251

Judge, Matagorda County Matagorda County Courthouse 1700 Seventh Street Bay City, TX 77414 A. H. Gutterman, Esq. Morgan, Lewis & Bockius 1800 M Street, N.W. Washington, DC 20036-5869

Mr. J. J. Sheppard, Vice President Engineering & Technical Services STP Nuclear Operating Company P. O. Box 289 Wadsworth, TX 77483

S. M. Head, Supervisor, Licensing Quality & Licensing Department STP Nuclear Operating Company P. O. Box 289 Wadsworth, TX 77483

Office of the Governor ATTN: John Howard, Director Environmental and Natural Resources Policy P. O. Box 12428 Austin, TX 78711

Jon C. Wood Matthews & Branscomb One Alamo Center 106 S. St. Mary's Street, Suite 700 San Antonio, TX 78205-3692

Arthur C. Tate, Director Division of Compliance & Inspection Bureau of Radiation Control Texas Department of Health 1100 West 49th Street Austin, TX 78756

Jim Calloway Public Utility Commission of Texas Electric Industry Analysis P. O. Box 13326 Austin, TX 78711-3326

W. Cottle

By letter dated December 2, 1999, the Region IV NRC staff issued NRC Inspection Report No. 50-498/99-18; 50-499/99-18. The subject inspection report contained details of the NRC staff's on-site verification of activities which you undertook in response to GL 98-02 for STP, Units 1 and 2. Specifically, the inspector verified that the licensee had effectively implemented administrative controls, configuration management, and operating procedures to preclude an inadvertent draindown event as described in GL 98-02. STP, Units 1 and 2 utilize three trains of RHR and ECCS. The high head safety injection pumps, low head safety injection pumps, and containment spray pumps take suction from a common header connected to the refueling water storage tank, each with their own isolation valves. The RHR pumps do not take suction from this header. RHR Trains B and C share a cross-connect on the discharge side of the pumps for reactor cavity draindown. Each of these trains include two normally locked closed containment insolation valves on the drain line. The above measures were found by the inspector to be appropriate.

The NRC staff has reviewed your response to GL 98-02 and has concluded that (1) all the information requested by GL 98-02 has been provided, and (2) that your on-site activities adequately addressed the concerns of GL 98-02 for STP, Units 1 and 2; therefore, we consider GL 98-02 to be closed for STP, Units 1 and 2.

Sincerely,

/RA/

John A. Nakoski, Senior Project Manager, Section 1 Project Directorate IV & Decommissioning Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket Nos. 50-498 and 50-499

cc: See next page

DISTRIBUTION:

File Center	PUBLIC	PDIV-1 Rdg	OGC	ACRS JTapia, RIV	JDonohew
MRazzaque	CLauron	JDavis			

DOCUMENT NAME: G:\PDIV-1\SouthTexas\STP9802close.wpd

To receive a copy of this document, indicate "C" in the box											
OFFICE	PDIV-1/PM	С	PDIV-1/LA	С	PDIV-1/LPM	С	SRXB/SC	С	PDIV-1/SC	С	
NAME	JNakoski		CJamerson		JDonohew		RCaruso		RGramm		
DATE	3/3/00		3/9/00		3/13/00		3/15/00		3/17/00		

OFFICIAL RECORD COPY