

March 4, 2003

Mr. A. C. Bakken III  
Senior Vice President  
Nuclear Generation Group  
American Electric Power Company  
500 Circle Drive  
Buchanan, MI 49107

SUBJECT: ANNUAL ASSESSMENT LETTER - D.C. COOK NUCLEAR POWER STATION  
(REPORT 50-315/03-01; 50-316/03-01)

Dear Mr. Bakken:

On February 11, 2003, the NRC staff completed its end-of-cycle plant performance assessment of D.C. Cook Nuclear Power Station. The end-of-cycle review for D.C. Cook Nuclear Power Station involved the participation of all technical divisions in evaluating performance indicators (PIs) for the most recent quarter and inspection results for the period from January 1, 2002, through December 31, 2002. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility so that you will have an opportunity to prepare for these inspections and to inform us of any planned inspections that may conflict with your plant activities.

Overall, D.C. Cook Nuclear Power Station operated in manner that preserved public health and safety and met all cornerstone objectives with moderate degradation in safety performance. Plant performance for the most recent quarter was within the Degraded Cornerstone Column of the NRC's Action matrix based on two WHITE inspection findings identified on Unit 2 in the Mitigating Systems Cornerstone. The first finding was identified in the first quarter of the assessment period and involved Unit 2 turbine driven auxiliary feedwater pump start failures. The second finding, which was associated with degraded essential service water system performance on both Unit 1 and Unit 2, was identified in the second quarter of the assessment period. Plant performance for Unit 1 for the most recent quarter was within the Regulatory Response Column of the Action Matrix based on the WHITE inspection finding associated with the essential service water system. All other inspection findings and PIs for the most recent quarter for both units were GREEN. The NRC has conducted a supplemental inspection for the WHITE finding associated with the Unit 2 turbine driven auxiliary feedwater pump start failures. A supplemental inspection in accordance with inspection procedure 95002 "Inspection for One Degraded Cornerstone or Any Three White Inputs in a Strategic Performance Area" is ongoing. Upon completion, the results of this inspection will be transmitted to you by separate correspondence.

In our mid-cycle letter dated August 23, 2002, we advised you of a substantive cross-cutting issue in the area of Problem Identification and Resolution. A Problem Identification and Resolution inspection was completed in the second quarter of the assessment period. That inspection identified several issues with the adequacy of apparent cause evaluations and with

the implementation of corrective actions. Baseline inspection results involving recent examples of poor corrective action program implementation indicate that this continues to be an area of concern. In addition, repetitive equipment problems have resulted in plant transients and challenges to plant operators. For example, repeat failures of the Unit 2 CD emergency diesel generator, and repeat failures of reactor control instrumentation power supplies were indicative of poor corrective action implementation. Based on the continued identification of findings associated with poor corrective actions, the NRC is concerned that your performance in this area is on a declining trend. You are requested to specifically address the actions that you are taking to improve performance in this cross cutting area at the end of cycle public meeting currently scheduled for April 10, 2003. Your performance in this area will be monitored via the baseline inspection program which includes a Problem Identification and Resolution inspection scheduled for August 2003. In addition, because Unit 2 has a degraded cornerstone and because your performance in this cross-cutting area continues to decline, the NRC intends to also conduct a Problem Identification and Resolution inspection in 2004.

The enclosed inspection plan details the inspections scheduled through March 31, 2004. The inspection plan is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last 6 months of the inspection plan are tentative and may be revised at the mid-cycle review meeting.

As you are aware, since the terrorist attacks on September 11, 2001, the NRC has issued several Orders and threat advisories to enhance security capabilities and improve guard force readiness. We have conducted inspections to review your implementation of these requirements and have monitored your actions in response to changing threat conditions. For calendar year 2003, we plan to continue these inspections, conduct portions of the security baseline inspection program, as well as perform additional inspections to evaluate your compliance with new requirements that may be ordered. Based on our final determinations in this regard, we will notify you of any inspection plan changes.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact Anton Vogel at 630-829-9620 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

*/RA/*

J. E. Dyer  
Regional Administrator

Docket Nos. 50-315, 50-316  
License Nos. DPR-58, DPR-74

Enclosure: D.C. Cook Inspection/Activity Plan

cc w/encls: J. Pollock, Site Vice President  
M. Finissi, Plant Manager  
R. Whale, Michigan Public Service Commission  
Michigan Department of Environmental Quality  
Emergency Management Division  
MI Department of State Police  
D. Lochbaum, Union of Concerned Scientists  
B. Witkowski, County Board Chairman  
J. M. Henry, Berrien County Coordinator  
Sheriff L. Paul Bailey  
M. Bradley, Berrien County Emergency Management Coordinator  
The Honorable Charles Yarbough  
C. Roberts, Benton Harbor City Manager  
The Honorable Mary Goff  
F. Walsh, St. Joseph City Manager  
The Honorable William Skiba  
A. Anthony, City Manager  
The Honorable David Hagey  
C. Weaver, City Manager  
M. Harris, President, Village of Stevensville  
J. Choudoir, President, Village of Berrien Springs  
L. Larsen, President, Village of Shorham  
INPO

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact Anton Vogel at 630-829-9620 with any questions you may have regarding this letter or the inspection plan.

Sincerely,

**/RA/**

J. E. Dyer  
Regional Administrator

Docket Nos. 50-315, 50-316  
License Nos. DPR-58, DPR-74

Enclosure: D.C. Cook Inspection/Activity Plan

cc w/encls: J. Pollock, Site Vice President  
M. Finissi, Plant Manager  
R. Whale, Michigan Public Service Commission  
Michigan Department of Environmental Quality  
Emergency Management Division  
MI Department of State Police  
D. Lochbaum, Union of Concerned Scientists  
B. Witkowski, County Board Chairman  
J. M. Henry, Berrien County Coordinator  
Sheriff L. Paul Bailey  
M. Bradley, Berrien County Emergency Management Coordinator  
The Honorable Charles Yarbough  
C. Roberts, Benton Harbor City Manager  
The Honorable Mary Goff  
F. Walsh, St. Joseph City Manager  
The Honorable William Skiba  
A. Anthony, City Manager  
The Honorable David Hagey  
C. Weaver, City Manager  
M. Harris, President, Village of Stevensville  
J. Choudoir, President, Village of Berrien Springs  
L. Larsen, President, Village of Shorham  
INPO

DOCUMENT NAME: G:\Branch TSS\EOC Ltrs\eoc 030403\Cook EOC Ltr 2002.wpd

To receive a copy of this document, indicate in the box "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RIII		RIII		RIII				
NAME	TVegel:co		GGrant		JDyer				
DATE	03/ /03		03/ /03		03/ /03				

**OFFICIAL RECORD COPY**

ADAMS Distribution:

WDR

DFT

JFS2

H. Nieh, OEDO

Project Director, NRR

Project Mgr., NRR

RidsNrrDipmlipb

J. Caldwell, RIII

G. Grant, RIII

B. Clayton, RIII

R. Lickus, RIII

SRI Cook

DRPIII

DRSIII

PLB1

JRK1

**D.C. Cook**  
**Inspection / Activity Plan**  
**03/01/2003 - 03/31/2004**

Unit Number	Inspection Activity	Title	No. of Staff on Site	Planned Dates Start	Planned Dates End	Inspection Type
	<b>HT SNK B - HEAT SINK BIENNIAL (DRS)</b>		<b>1</b>			
1, 2	IP 7111107B	Heat Sink Performance		03/10/2003	03/14/2003	Baseline Inspections
	<b>FPI - TRIENNIAL FIRE PROTECTION</b>		<b>4</b>			
1, 2	IP 7111105T	Fire Protection		03/24/2003	04/11/2003	Baseline Inspections
	<b>71121.02 - OUTAGE ALARA INSPECTION</b>		<b>1</b>			
1, 2	IP 7112102	ALARA Planning and Controls		04/21/2003	04/25/2003	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		04/21/2003	04/25/2003	Baseline Inspections
	<b>7111108 - ISI AND TI-150 FOR UNIT 2</b>		<b>1</b>			
2	IP 2515/150	Reactor Pressure Vessel Head and Vessel Head Penetration Nozzles (NRC Bulletin 2002-02)		05/12/2003	05/23/2003	Safety Issues
2	IP 7111108P	Inservice Inspection Activities - PWR		05/12/2003	05/23/2003	Baseline Inspections
	<b>SSDI - SAFETY SYSTEM DESIGN</b>		<b>5</b>			
1, 2	IP 7111121	Safety System Design and Performance Capability		06/23/2003	07/11/2003	Baseline Inspections
	<b>71114 - EP EXERCISE &amp; PI VERIFICATION</b>		<b>3</b>			
1, 2	IP 71151	Performance Indicator Verification		07/21/2003	07/25/2003	Baseline Inspections
	<b>71114.01 - BIENNIAL EP EXERCISE</b>		<b>3</b>			
1, 2	IP 7111401	Exercise Evaluation		07/21/2003	07/25/2003	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		07/21/2003	07/25/2003	Baseline Inspections
	<b>71122.03 - REMP/RAD MTL CONTROL INSP</b>		<b>1</b>			
1, 2	IP 7112203	Radiological Environmental Monitoring Program		07/28/2003	08/01/2003	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		07/28/2003	08/01/2003	Baseline Inspections
	<b>BIP - ID AND RESOLUTION OF PROBLEMS</b>		<b>1</b>			
1, 2	IP 71152B	Identification and Resolution of Problems		08/18/2003	09/05/2003	Baseline Inspections
	<b>IP 71121 - RP ACCESS CONTROLS INSPECTION</b>		<b>1</b>			
1, 2	IP 7112101	Access Control to Radiologically Significant Areas		09/08/2003	09/12/2003	Baseline Inspections
1, 2	IP 71151	Performance Indicator Verification		09/08/2003	09/12/2003	Baseline Inspections
	<b>71111.08 - ISI AND TI-150 FOR UNIT 1</b>		<b>2</b>			
1	IP 2515/150	Reactor Pressure Vessel Head and Vessel Head Penetration Nozzles (NRC Bulletin 2002-02)		10/20/2003	11/15/2003	Safety Issues
1	IP 7111108P	Inservice Inspection Activities - PWR		10/20/2003	11/15/2003	Baseline Inspections
	<b>71121 - RP INSTRUMENTATION INSP</b>		<b>1</b>			
1, 2	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment		01/12/2004	01/16/2004	Baseline Inspections
	<b>FY 2004 - D. C. COOK INIT PREP 02/2004</b>		<b>3</b>			
1	W90075	OL - INITIAL EXAM - DC COOK - FEB/MAR 2004		02/23/2004	02/27/2004	Not Applicable
	<b>FY 2004 - D. C. COOK INIT EXAM 03/2004</b>		<b>3</b>			
1	W90075	OL - INITIAL EXAM - DC COOK - FEB/MAR 2004		03/15/2004	03/26/2004	Not Applicable

This report does not include INPO and OUTAGE activities.  
This report shows only on-site and announced inspection procedures.