

Serial: HNP-09-076 10 CFR 50.55a

AUG 0,6 2009

U.S. Nuclear Regulatory Commission ATTENTION: Document Control Desk Washington, DC 20555

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/LICENSE NO. NPF-63 90-DAY INSERVICE INSPECTION (ISI) SUMMARY REPORT

Ladies and Gentlemen:

In accordance with 10 CFR 50.55a, Carolina Power and Light Company, doing business as Progress Energy Carolinas, Inc., submits the attached Inservice Inspection (ISI) Summary Report for the Harris Nuclear Plant (HNP). This report has been prepared in accordance with Section XI of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, 2001 Edition with addenda through 2003, and ASME Code Case N-532-4, as approved in Regulatory Guide 1.147. This report is for HNP's Cycle 15 operations and Refueling Outage No. 15 (RFO-15) of the third 10-year ISI interval.

This document contains no new regulatory commitments.

Please refer any question regarding this submittal to me at (919) 362-3137.

Sincerely,

D. H. Corlett

Supervisor – Licensing/Regulatory Programs

Harris Nuclear Plant

DHC/kms

Enclosure

cc: Mr. J. D. Austin, NRC Sr. Resident Inspector, HNP

Mr. J. M. Given, Jr., NC Department of Labor, Boiler Safety Bureau

Mr. L. A. Reyes, NRC Regional Administrator, Region II

Ms. M. G. Vaaler, NRC Project Manager, HNP

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

CAROLINA POWER AND LIGHT COMPANY dba PROGRESS ENERGY CAROLINAS, Inc. SHEARON HARRIS NUCLEAR POWER PLANT Unit One

Inservice Inspection Summary Report For RFO-15

Carolina Power and Light PO Box 1551 Raleigh, NC 27602-1551

Shearon Harris Nuclear Power Plant 5413 Shearon Harris Road New Hill, NC 27562

> Date of Commercial Service May 2, 1987

SHEARON HARRI\$ NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

Committee of the Committee of

INDEX

| Summary | Section 1 |
|---|-----------|
| OAR-1 Form, Report of Inservice Inspections | Section 2 |
| Table 1 | Section 3 |
| Table 2 | Section 4 |

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

SECTION 1 (2 Pages)

SUMMARY

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

SUMMARY

The Shearon Harris Nuclear Power Plant, Unit 1, Third Ten-Year Inservice Inspection (ISI) Plan is being developed to comply with 10CFR50.55a(g), which implements, by reference, the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, Section XI, 2001 Edition with 2003 Addenda.

The following summary report is being submitted pursuant to the reporting requirements of ASME Section XI as amended by ASME Code Case N-532-4.

This summary report contains the Form OAR-1 Owner's Activity Report and Tables 1 and 2 of the Code Case for Harris Nuclear Plant (HNP) during cycle 15 and Refueling Outage No. 15 (RFO-15). No indications were found that required evaluation for continued service. RFO-15 is the second outage of the first period in the third inspection interval and includes Repair/Replacement Activities from October 23, 2007 to August 03, 2009.

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

SECTION 2 (2 Pages)

OAR-1 FORM OWNER'S ACTIVITY REPORT

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

FORM OAR-1 OWNER'S ACTIVITY REPORT

| Report Number HNP-09-076 | | | | | |
|---|--|--|--|--|--|
| Plant Harris Nuclear Plant, 5413 Shearon Harris Rd, New Hill, NC 27562 | | | | | |
| Unit No1 Commercial Service Date May 2, 1987 Refueling Outage No. RFO-15 | | | | | |
| Current Inspection Interval Third interval | | | | | |
| Current Inspection period First period | | | | | |
| Edition and Addenda of Section XI applicable to the inspection plan 2001 Edition with 2003 Addenda | | | | | |
| Date and revision of inspection plan June 09, 2009 | | | | | |
| Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan | | | | | |
| | | | | | |
| Code Cases used: N-307-3, N-460, N508-3, N-532-4, N-533-1, N-722, N-729-1 | | | | | |
| . ` | | | | | |
| CERTIFICATE OF CONFORMANCE | | | | | |
| | | | | | |
| I certify that (a) the statements made in this Owner's Activity Report are correct; (b) and the examinations and tests met the Inspection Plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of | | | | | |
| RFO-15 conform to the requirements of Section XI. | | | | | |
| Signed S. J. Volk, ISI Program Manager Date August 03, 2009 | | | | | |
| Signed S. J. Volk, ISI Program Manager Date August 03, 2009 | | | | | |
| | | | | | |
| CERTIFICATE OF INSERVICE INSPECTION | | | | | |
| I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State | | | | | |
| or Province of North Carolina and employed by HSBCT of Hartford Connecticut have inspected the items described in this Owner's | | | | | |
| Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI. | | | | | |
| By signing this certificate neither the inspector nor his employer makes any warranty, expressed or implied, concerning the | | | | | |
| repair/replacements activities and evaluation described in this report. Furthermore, neither the inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection. | | | | | |
| | | | | | |
| Never CRiticology Storytu Commissions NB8447ABNI NC1169 | | | | | |
| Inspector's Signature National Board, State, Province, and Endorsements | | | | | |
| Date 8/3/09 | | | | | |
| | | | | | |

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

SECTION 3 (1 Page)

TABLE 1

ITEMS WITH FLAWS OR RELEVANT CONDITION THAT REQUIRED EVALUATION FOR CONTINUED SERVICE

| Examination Category and Item Number | Item Description | Evaluation Description |
|--------------------------------------|--------------------------|------------------------|
| None | Mileson - reconstruction | |

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

SECTION 4 (2 Pages)

TABLE 2

ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 INSERVICE INSPECTION SUMMARY REPORT FOR RFO-15

Table 2
Abstract of Repair/Replacement Activities Required for Continued Service

| Code Class | Item Description | Description of Work | Date Completed | Repair/Replacement Plan Number |
|------------|------------------|-----------------------------------|----------------|-----------------------------------|
| 1 | 1RC-902 | Replace valve | 6 /8 /2009 | 0198181 -05 |
| 1 . | 1RC-905 | Rebuild valve | 6 /9 /2009 | 0198188 -01 |
| 1 | 1RC-905 | Replace valve | 5 /28/2009 | 0198188 -04 |
| 3 | 1SW-19 | Replace valve | 5 /28/2009 | 0687148 -01 |
| 3 | 1SW-179 | Replace valve | 5 /28/2009 | 0687399 -05 |
| 3 | 1SW-206 | Replace valve | 5 /22/2009 | 0855580 -01 |
| 1 | 1RC3/4-133-SN1 | Replace piping | 6 /11/2009 | 1074620 -01 |
| 3 | 1CC-CCWHXA | Install pipe cap over 3/4" piping | 1 /8 /2008 | 1120016 -04 |
| 2 | 1CS-347 | Replace valve | 6 /24/2009 | 1130793 -01 |
| 3 | 1SW-140 | Replace valve and piping | 6 /10/2009 | 1136644 -01 |
| 3 | 3SW1.5-167SA-1 | Replace piping | 5 /27/2009 | 1136644 -02 |
| 3 | 1SW-151 | Replace valve and piping | 6 /11/2009 | 1136644 -03 |
| 3 | 1CC-211 | Replace valve | 6 /24/2009 | 1155139 -01 |
| 2 | 1CV-E004 | Remove coil; blind flange piping | 8 /18/2008 | 1168269 -01 |
| 2 | 1CV-E004 | Replace cooling coils | 5 /28/2009 | 1168269 -05 |
| 3 | AF-H-682 | Add new support | 8 /18/2008 | 1169868 -01 |
| 2 | 1CV-E004 | Replace cooling coils and bolting | 5 /22/2009 | 1278401 - 01 |
| 2 | 1CS-382 | Replace valve and piping | 5 /28/2009 | 1304543 -01 |
| 3 | 1SW-83 | Replace valve | 5 /28/2009 | 1308702 -01 |
| 3 | 1SC-37 | Replace valve plug | 1 /15/2009 | 1313092 -01 |
| 3 | 3SW1-267SA-1 | Install pipe cap over 1" piping | 6 /10/2009 | 1355811 -06 |
| 2 | · 1CT-119 | Replace valve and piping | 8 /18/2008 | 1375342 - 04 |
| 1 | 1RC-115 | Replace valve disc | 5 /28/2009 | 1417909 -01 |
| 2 | 1CV-E005 | Install blind flanges | 10/27/2008 | 1434118 -01 |
| 2 | 1CV-E005 | Install new cooling coils | 5 /22/2009 | 1434118 -04 |
| 3 | 3SW1.5-389SB-1 | Replace piping | 5 /28/2009 | 1539081 -01 |
| 3 | 1AF-E003 | Replace balancing line | 5 /9 /2009 | 1541948 -01 |