IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS. IOWA DUANE ARNOLD ENERGY CENTER PALO, IOWA JUNE 10, 1974 DAEC - 74 - 216

Mr. James Keppler Regional Director Directorate of Regulatory Operations U. S. Atomic Energy Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

> SUBJECT: Abnormal Occurrence No. DPR 49/74-10

PILE A-118a

A-110

Dear Mr. Keppler:

In accordance with the DAEC Technical Specifications, Section 6.11.2A.1, this letter is intended as notification of an Abnormal Occurrence at the Duane Arnold Energy Center on June 8, 1974.

Identification of Occurrence

Loss of power to buses supplying power to LPCI injection valve motors which could have prevented the performance of the intended safety function of an engineered safety feature system.

Description of Occurrence

During the conduct of loss of power testing, 480 Volt Motor Control Center buses 1834A and 1844A failed to pick-up on loss of off-site power. These buses supply power to the LPCI injection valve motors.

Investigation is continuing.

A formal written report will be submitted to the Office of the Directorate of Regulatory Operations within 10 days of the subject Abnormal Occurrence.

> Yours truly, G. G. Hunt

Chief Engineer

DLW/GGH/bh

John O'Leary

C. W. Sandford

J. A. Wallace

B. R. York

J. H. Gebert D. L. Wilson

E. L. Hammond

B. L. Hopkins

MESEN WIN

TELLIGIALIS (CITHER THAN MONEY OFFERS) 2/1/A
VEC128(1443) (2-0 Is PHYSICAS) PD GEV 15 774 1443 (1443) (2-0 IS PHYSICAS FEET)
ICS IPMBNGZ CSP Nor. & Name 144
3198515611 TDBN PALO Date dld OS 15 0243P EDI// 2 17 TO be mailed or The Day 15 0243P
PMS MRE JAMES KEPPLERAttempts to deliver (Indicate DA op)
REGIONAL DIRECTOR DIRECTORATE OF REGULARTORY OPERATIONS U.S. AJOMIC
ENERGY COMMISSSION REGION 3 799 ROSSEVELT RD (16 Oct 145)
THIS TELEGRAM IS INTENDED AS NOTIFICATION OF AN ABNORMAL OCCURRENCE MA
AT THE DUANE ARNOLD ENERGY CENTER JUNE 14 1974.
IDENTIFICATION OF OCCURRENCE-INCORRECTLY INSTALLED PRESSURE
SENSING LINE SNUBBERS ON HPCI AND RCIC HIGH FLOW ISOLATION INSTRUMENTS
CONSTITUTING AND ABNORMAL OCCURRENCE IN ACCORDANCE WITH TECHNICAL
SPECIFICATIONS SECTION 1.4.D.
THE ABOVE CONDITION WAS IMMEDIATELY CORRECTED. INVESTIGATION
Gis continuing.
G G HUNT CHIEF ENGINEER DAEC JUN 1 8 1974

SF-1201 (R5-69)

G G HUNT CHIEF ENGINEER DAEC