

Rec. 409 1/16/75 gw

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA

DUANE ARNOLD ENERGY CENTER

PALO, IOWA

JANUARY 16, 1975

DAEC - 18 - 1975

Mr. James Keppler, Director
Regulatory Operations Regional Office
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. AO 50-331/75-1
FILE: A-118a
A-110

Dear Mr. Keppler:

In accordance with DAEC Technical Specifications, Section 6.11.2A.1 this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on January 15, 1975. This letter, telecopied to your office, is intended to satisfy the requirements for notification by telegram within 24 hours of an abnormal occurrence.

Identification of Occurrence

Out-of-calibration main steam line high flow pressure differential indicating switches, reportable in accordance with Appendix A, Operating License DPR-49, Specification 1.0.4.B.

Description of Occurrence

During the performance of Surveillance Test Procedure 42A004 - Main Steam Line High Flow, it was determined that the following pressure differential indicating switches were out-of-calibration:

- | | |
|------------|------------|
| PDIS 4432A | PDIS 4434C |
| PDIS 4436A | PDIS 4436C |
| PDIS 4438A | PDIS 4434D |
| PDIS 4432B | PDIS 4436D |
| PDIS 4434B | PDIS 4438D |
| PDIS 4436B | |

AO 50-331/75-1
Page 2
January 16, 1975

The as-found trip settings of the above switches will be indicated in the ten-day report. Although the switches were slightly out-of-calibration, all were mechanically operable.

All switches were re-calibrated immediately.

A formal written report will be submitted to the Office of Directorate of Regulatory Operations within 10 days of the subject abnormal occurrence.



G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

DLW/GGH/dg

cc: E. G. Case
C. W. Sandford
J. A. Wallace
E. L. Hammond
B. R. York
D. L. Wilson
R. R. Rinderman
L. D. Root
H. W. Rehrauer - Chairman, Safety Committee
G. A. Cook