

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

Cedar Rapids, Iowa

DUANE ARNOLD ENERGY CENTER

PAID, IOWA

NOVEMBER 19, 1974

DAEC - 74 - 396

Mr. James Keppeler, Director
Regulatory Operations Regional Office
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. AO-50-331/74-50
FILE: A-110a
A-110

Dear Mr. Keppeler:

In accordance with the DAEC Technical Specifications, Section 6.11.2.A.1, this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on November 19, 1974. This letter, telecopied to your office, is intended to satisfy the requirements for notification by telegram within 24 hours of the abnormal occurrence.

Identification of Occurrence:

Core Spray Sparger to Reactor Pressure Vessel Differential Pressure Trip Level Setting reportable per Appendix A, Operating License DFR-49, Specification 1.0.4.b and Table 3.2-B.

Description of Occurrence:

On November 19, 1974, it was noted that during the conduct of surveillance test procedure 42B018, PDIB 2119 was found to be out-of-calibration.

The switch was immediately recalibrated.

11/19/74

A formal written report will be submitted to the Office of the Directorate of Regulatory Operations within 10 days of the identification of the abnormal occurrence.

Very truly yours,



G. G. Hart
Chief Engineer

Duane Arnold Energy Center

FG:GCH:mc

CC: E. G. Case
C. W. Sanford
J. A. Wallace
E. L. Hammond
E. R. York
D. L. Wilson
R. R. Binkerman
L. D. Root
H. W. Rebrauer, Chairman, Safety Committee
G. A. Cook
B. L. Hopkins