

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 01/31/2013)**

| TAC NO. | TAC TITLE | STATUS | AGE (Mon) | TAC OPENED | LEAD ORG |
|----------------|---|---------------|----------------------|-----------------------|---------------------|
| ME5167 | RIS 'Staff Position on the Clarification of Submitting of Alter. Under 10 CFR 50.55' | O | 26.0 | 12/13/2010 | DCI |
| ME7896 | RIS 'Content Specification and Shielding Evaluations for Type B Packages' | O | 13.0 | 01/27/2012 | NMSS |
| ME8702 | RIS 'Applicability of GDC Requirements for External Events in Operability Determinations' | O | 9.0 | 05/17/2012 | DSS |
| ME8865 | RIS 'Changes to NOED Process and Staff Guidance' | O | 8.0 | 06/12/2012 | DPR |
| ME9020 | RIS 'Embedded Digital Devices in Safety Systems' | O | 7.0 | 07/09/2012 | NRO |
| ME9732 | RIS 'Resolution of Top Nozzles Stress Corrosion Cracking Issues' | O | 4.0 | 10/04/2012 | NMSS |
| MF0415 | RIS 'Use of Aftermarket Sealed Sources Registered Under 10 CFR 32.210' | O | 2.0 | 12/21/2012 | FSME |
| MF0416 | RIS 'NRC Staff Position on Use of ASME Certification Mark' | O | 2.0 | 12/21/2012 | DE |
| MF0467 | RIS 'Maintaining Effective Aging Management Programs' | O | 1.0 | 01/07/2013 | DLR |
| MF0541 | RIS 'NRC Position on SSCs Requiring Protection from Tornado Missiles | O | 1.0 | 01/23/2013 | DSS |
| ME8473 | IN 'Seismic Instrumentation Issues' | O | 10.0 | 04/24/2012 | PGCB |
| ME9179 | IN 'Counterfeit Fire Protection Equipment' | O | 6.0 | 08/06/2012 | DE |
| ME9258 | IN 'Emergency Action Level Thresholds Outside the Range of Radiation Monitors' | O | 6.0 | 08/16/2012 | PGCB |

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 01/31/2013)**

| TAC NO. | TAC TITLE | STATUS | AGE (Mon) | TAC OPENED | LEAD ORG |
|----------------|---|---------------|----------------------|-----------------------|---------------------|
| ME9615 | IN 'Recent Issue With The Definition Of Core Quadrant' | O | 5.0 | 09/25/2012 | DSS |
| ME9779 | IN 'Concrete Subsurface Laminar Cracking' | O | 4.0 | 10/15/2012 | RIII |
| ME9789 | IN 'Design Vulnerabilities in Dry Pipe and Pre-Action Fire Water Systems' | O | 4.0 | 10/15/2012 | DRA |
| MF0327 | IN 'Cracking Issues Related to Steam Dryer Component in BWR Units with Power Uprates' | O | 2.0 | 12/06/2012 | DE |
| MF0386 | IN 'Noncompliance with NRC Regulation that Prohibits Foreign Ownership of Licensees' | O | 2.0 | 12/17/2012 | DIRS |
| MF0492 | IN 'Battery Aging Margin and Its Potential Impact on Surveillance Requirements' | O | 1.0 | 01/12/2013 | DE |
| MF0580 | IN 'Radioactive Effluent Radiation Monitoring Systems' | O | 1.0 | 01/29/2013 | DPR |
| ME7544 | GL 'Degraded Voltage Protection' | O | 15.0 | 11/09/2011 | DE |
| ME9142 | GL 'Post-Fire Safe-Shutdown Circuit Analysis Spurious Actuations' | O | 7.0 | 07/26/2012 | DRA |
| ME9843 | GL 'Treatment of Natural Phenomena Hazards At Fuel Cycle Facilities' | O | 4.0 | 10/25/2012 | NMSS |
| MF0581 | GL 'Degradation of Neutron Absorbing Material in Spent Fuel Pools' | O | 1.0 | 01/29/2013 | DSS |