



Duke Energy Florida
**Levy Nuclear Plant
 Units 1 and 2
 Part 2, Final Safety Analysis Report**

Primary and Orthogonal Fracture Pattern
 Local Avon Park Formation Outcrops
 FIGURE 2.5.4.1-202