

50-244

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER  
INCIDENT REPORT

TO: Mr O'Reilly

FROM: Rochester Gas & Electric Co  
Rochester, NY  
L D White Jr

DATE OF DOCUMENT  
3-11-76

DATE RECEIVED 3-16-76

LETTER  
 ORIGINAL  
 COPY

NOTORIZED  
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED  
none signed

DESCRIPTION

Ltr trans the following:

PLANT NAME: RE Ginna

ENCLOSURE

Fourteen Day Report re Reportable Occurrence #76-08 which concerned abnormal degradation of steam generator tubes...(1 cy encl rec'd)

ACKNOWLEDGED

DO NOT REMOVE

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO

3-18-76 elf

BRANCH CHIEF:

Purple

W/3 CYS FOR ACTION

LIC. ASST:

Sheppard

W/1 CYS

ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC (3)

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CUECK

GRIMES/SCHWENCER

CASE

F. WILLIAMS

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION


LPDR: Lyons + Rochester, NY


TIC

NSIC

CONTROL NUMBER

9  
2659






ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

March 11, 1976

REGULATORY DOCKET FILE COPY



Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-08 (14-day report), Abnormal  
degradation of steam generator tubes  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2a, the attached  
report of Reportable Occurrence 76-08, 14-day, is hereby submitted. Two  
additional copies of this letter and the attachment are enclosed.

Very truly yours,

*L.D. White, Jr.*  
L. D. White, Jr.

Attachment

cc: Mr. Ernst Volgenau (40)  
Mr. William G. McDonald (3)  
Mr. Robert A. Purple, (3)



2659

210

LER 76-08/1T  
INDIANEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ]  
1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: [01] [N] [Y] [R] [E] [G] [I] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]  
7 8 9 14 15 25 26 30 31 32

CATEGORY: [01] [CON]T [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]  
7 8 57 58 59 60 61 68 69 74 75 80

EVENT DESCRIPTION

[02] During the planned eddy current inspection of the Steam Generator (SG) tubes, 39 tubes  
[03] in the "A" SG inlet and 2 tubes in the "B" SG inlet showed defects above the wastage  
[04] limit of 40%. These tubes have been plugged. (Reportable Occurrence 76-08, 14-day)

SYSTEM CODE: [07] [C] [I] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]  
7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

[08] Local corrosion of tube OD surface caused by concentrations of residual phosphates.  
[09] A complete eddy current program description and report is attached.

FACILITY STATUS: [11] [H] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]  
7 8 9 10 12 13 44 45 48 80

PERSONNEL EXPOSURES: [13] [0] [0] [0] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]  
7 8 9 11 12 13 80

PERSONNEL INJURIES: [14] [0] [0] [0] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]  
7 8 9 11 12 80

OFFSITE CONSEQUENCES: [15] [ ]  
7 8 9 80

LOSS OR DAMAGE TO FACILITY: [16] [Z] [ ]  
7 8 9 10 80

PUBLICITY: [17] [ ]  
7 8 9 80

ADDITIONAL FACTORS

[18] An all volatile treatment water chemistry control was started November 1975 and  
[19] adherence to this has been good to date.