

231 W. Michigan, PO. Box 2046, Milwaukee, WI 53201

VPNPD-90-217 NRC-90-043

May 9, 1990

U.S. NUCLEAR REGULATORY COMMISSION Document Control Desk Mail Station P1-137 Washington, D.C. 20555

Gentlemen:

DOCKET NOs. 50-266 AND 50-301 LICENSEE EVENT REPORT 90-003-00 DIESEL GENERATOR FUEL OIL SUPPLY POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

Enclosed is Licensee Event Report 90-003-00 for Foint Beach Nuclear Plant, Units 1 and 2. This report is being provided in accordance with 10 CFR 50.73 (a)(2)(v), "The licensee shall report ... any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems..."

This report describes the condition that existed when it was determined that a portion of the fuel oil piping between the emergency fuel oil tank and the emergency diesel generator fuel oil day tanks was not seismically supported. Therefore we could not prove extended operability of our diesel generators due to the potential for a seismic induced failure of the fuel oil line from the onsite storage tanks to the diesels. This condition was the subject of a requested Temporary Waiver of Compliance documented in our letter, NRC 90-136, dated April 10, 1990.

If you have any questions regarding this Licensee Event Report, please do not hesitate to contact us.

Very truly yours,

Linko for Chiling

C. W. Fay Vice President Nuclear Power

Attachments

Copies to NRC Regional Administrator, Region III NRC Fesident Inspector 9005160033 900509 EDR ADOCK 05000266 FDC

(414) 221-2345

A subsidiary of Wisconsin Energy Corporation