



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

February 1, 1983

DJS Ltr. #82-105

James G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #82-34/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(d), abnormal degradation of systems other than those specified in item B.1.e. above designed to contain radioactive material resulting from the fission process. This revised report indicates replacement of the eroded segment of the pipe with an identical piece of pipe. The repair was performed after the original report was submitted.

D. G. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Management Branch  
File/NRC

8302160154 830201  
PDR ADOCK 05000237  
S PDR

FEB 10 1983

IE22