NRC FORM 366 (12-81)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB
(12.81) 10 CFR 50 CONTROL BLOCK	(1) IPLEASE PRINT OR TYPE ALL REC	DUIRED INFORMATION
OT CADCPIDE	0  -  0  0  0  0  -   0   0   3  4  1  1	1 1 1 0 57 CAT 30 5
O 1 SOURCE L 6 0 5 0	0 0 2 7 5 7 0 4 1 9 8 3 0 0	1 1 7 8 4 9
Prior to fuel load, gri	nding wheel and rotary file gouges were	discovered on the
olant system pip	ing on the discharge side of #3 main co	olant pump. Of the
o 4   four gouges discovered,	the most severe is approximately 0.150	inches deep x 2.0
os Linches long x 0.150 inch	es wide causing a less than required mi	nimum wall thickness.
O 6 This event has in no wa	y affected public health and safety, an	d is reportable per
0 7 [Technical Specification	6.9.1.12.c.	
0 8	CAUSE COMP.	VALVE 80
C B T X	SUBCODE COMPONENT CODE SUBCODE	15 Z 16
1) REPORT   8   3	O O 4 O 8	
	Z 2) 0 0 0 0 Y 23 N 24	SUPPLIER COMPONENT 20 W 1 2 0
CAUSE DESCRIPTION AND CORRECTS Gouges were intentional	ly caused by persons unknown. Gouges h	ave been repaired
1 by weld build up and gr	inding flush, in accordance with an app	proved ASME Section
1 2 XI procedure. Addition	al corrective actions taken are describe	ed in the attached
supplemental information. This is a final report.		
14	· ·	
1 5 B 28 0 0 0 0 0 NA	Discovered during	g construction
ACTIVITY CONTENT AMOUNT OF A	ACTIVITY 35 LOCATION OF	RELEASE 36
TYPE DESCRIPTION OF TYPE D	N 39	
PERSONNEL INJURIES DESCRIPTION (1)	8401260352 840117 PDR ADOCK 05000275 PDR	168
DESCRIPTION (3)  1 9 D (2) Small gouges in R	Reactor Coolant piping	
2 0 Y 4 PG&E News Releas	se of April 22, 1983	NRC USE ONLY

W. W. Kessinger

## PACIFIC GAS AND ELECTRIC COMPANY DIABLO CANYON UNIT 1 DOCKET NO. 50-275 LER 83-004/08X-1

## SUPPLEMENTAL INFORMATION

- A 100% visual inspection of the reactor coolant system pressure boundary, where insulation was removed, was conducted. No other indications of unauthorized work were detected.
- All uninsulated Class 2 piping connected to the reactor coolant system inside containment has had a 100% visual inspection. No indication of unauthorized work was detected.
- Construction and contractor supervisors and PGandE Nuclear Plant
  Operations personnel were informed of the incident in order to increase
  general awareness and to promote watchfulness for potential similar
  events.
- The PGandE/Bechtel Project increased supervision of all construction activities within the Protected Area.
- 5. Supervision will continue to promote increased awareness of specfic work tasks in progress and the specific individuals assigned to each work task.
- The Security Department increased the frequency of patrols within the work force areas in order to increase the visibility of security forces.
- Construction personnel have been and will continue to be informed of job security as related to work schedules in order to minimize the possibility of deliberate acts to extend work.
- 8. Investigation is continuing in an effort to identify the individual or individuals responsible for this incident.

RECEIVED PACIFIC GAS AND ELECTRIC COMPANY 77 BEALE STREET . SAN FRANCISCO, CALIFORNIA 941064 415 781, 211 : TWX 910-372-6587 PGME JAMES D. SHIFFER REGION V ISP DEPARTMENT OF NUCLEAR PLANT OPERATIONS NUCLEAR POWER GENERATION January 17, 1984 PGandE Letter No.: DCL-84-016 Mr. John B. Martin, Regional Administrator U. S. Nuclear Regulatory Commission, Region V 1450 Maria Lane, Suite 210 Walnut Creek, CA 94596-5368 Re: Docket No. 50-275, OL-DPR-76 Diablo Canyon Unit 1 Update Licensee Event Report 83-004/08X-1 Gouge in Main Coolant System Piping Dear Mr. Martin: Pursuant to Section 6.9.1.12c of the Technical Specifications, Appendix A to the Diablo Canyon Unit 1 Operating License, the enclosed updated Licensee Event Report is submitted concerning the discovery and repair of gouges in the main coolant system piping. This event has in no way affected the public's health and safety. Sincerely, for James D. Shiffer **Enclosure** cc: G. W. Knighton Director, Office of Management Information and Program Control Service List