




KANSAS GAS AND ELECTRIC COMPANY



GLENN L. KOESTER  
VICE PRESIDENT - NUCLEAR

January 13, 1985

Mr. R.P. Denise, Director  
Wolf Creek Task Force  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

KMLNRC 85-021  
Re: Docket No. STN 50-482  
Ref: Interim Report KMLNRC 84-083, dated 6/1/84  
From GLKoester, KG&E, to EHJohnson, NRC  
Subj: Final 10CFR50.55(e) Report - Standby Diesel Generator  
"B" Left Bank Turbocharger (53564-K138)

Dear Mr. Denise:

This letter provides the final report submitted pursuant to 10CFR50.55(e) concerning the "B" standby diesel generator left bank turbocharger at Wolf Creek Generating Station. This matter was initially reported on May 4, 1984 with supplemental information provided in the reference.

As indicated in the reference the turbocharger failure was apparently the result of a loose lock nut on the left bank turbocharger lubricating oil pump centrifuge. The damaged turbocharger has been repaired and the other standby diesel generator turbochargers were inspected to preclude any similar failures.

The aforementioned corrective actions have been completed. If you have any questions concerning this matter, please contact me or Mr. Otto Maynard of my staff.

Yours very truly,

Glenn L. Koester  
Vice President - Nuclear

GLK:dab

xc: RCDeYoung  
PO'Connor  
HBundy  
WGuldmond

8502010541 850113  
PDR ADOCK 05000482  
S PDR

IE-27  
1/0