

April 23, 1985

Mr. J. M. Taylor, Director
Office on Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington D. C. 20555

Subject: 10CFR 21 Report
Inspection Procedure Revision


Reference: H. H. Leusink Letter dated April 15, 1985

Dear Mr. Taylor:

Please find enclosed Revision 1 to the inspection procedure prepared for the purpose of investigating the emergency diesel generators, which was included with my April 15, 1985 letter.

A copy of this revision will be forwarded to each site's Quality Assurance Department as indicated below.

Sincerely,



H. H. Leusink
Vice President, Engineering

HHL:sd
Attachment

cc: Project Manager
Nuclear Quality Assurance
Washington Public Power System
P.O. Box 968
Richland, Washington 99352

Quality Engineering Manager
Public Service of Indiana
Marble Hill Nuclear Division
P.O. Box 190
New Washington, Indiana 47162

8504300459 850423
PDR ADOCK 05000272
S PDR

Louis Allis:
J. Borman
D. Bryant
M. Buckna
A. Giesecke
H. Schreiber
J. Treible

Nuclear Quality Assurance
Public Service Electric & Gas Company
P.O. Box 236
Hancock's Bridge, New Jersey 08038

Quality Assurance Manager
Kansas Gas & Electric Company
P.O. Box 208
Wichita, Kansas 67201

Quality Assurance Manager
Union Electric Company
P.O. Box 149
St. Louis, Missouri 63166

50-272
50-311
50-397
50-482
50-483

IE19
11

M9537 - 4/82

ENGINEERING REPORT

ALTERNATORS - CONTROLS - ROTARY COMPRESSORS

FILE NUMBER

DATE April 15, 1985

REFERENCE NUMBER 10CFR 21 - Emergency Stand By Generators

PREPARED BY

SUBJECT Inspection Procedure for Fractured Welds on Air Deflectors

APPROVED BY H. H. Leusink

Q.A. Appl.
Eng. Appl.
Chkd. By
Was
Loc.
Date
Serial No.
Rev. No.
Chkd. By
Was
Loc.
Date
Serial No.
Rev. No.
Eng. Appl.
A. Appl.

