

UNITED STATES

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064 JUN 23 1997

Charles M. Dugger, Vice President Operations - Waterford 3 Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

SUBJECT: NRC INSPECTION REPORT 50-382/50-382/97-04

Dear Mr. Dugger:

Thank you for your letter of June 4, 1997, in response to our letter and Notice of Violation dated May 5, 1997. We have reviewed your reply and determined that your letter specified that your interim corrective action had restored compliance to requirements. However, you did not provide a date, as required by 10 CFR 2.201(a)(3), by which full compliance will be achieved. As discussed with Mr. Early Ewing of your staff, we understand that a supplemental response will be forthcoming to specify the required completion dates.

Sincerely,

tomas Thomas P. Gwynn, Director Division of Reactor Projects

Docket No.: 50-382 License No.: NPF-38

cc: Executive Vice President and Chief Operating Officer Entergy Operations. Inc. P.O. Box 31995 Jackson, Mississippi 39286-1995

9706270064 970623 PDR ADOCK 05000382 G PDR

Vice President, Operations Support Entergy Operations, Inc. P.O. Box 31995 Jackson, Mississippi 39286-1995

Wise, Carter, Child & Caraway P.O. Box 651 Jackson, Mississippi 39205

General Manager, Plant Operations Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

Manager - Licensing Manager Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

Chairman Louisiana Public Service Commission One American Place, Suite 1630 Baton Rouge, Louisiana 70825-1697

Director, Nuclear Safety & Regulatory Affairs Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

William H. Spell, Administrator Louisiana Radiation Protection Division P.O. Box 82135 Baton Rouge, Louisiana 70884-2135

Parish President St. Charles Parish P.O. Box 302 Hahnville, Louisiana 70057

Mr. William A. Cross Bethesda Licensing Office 3 Metro Center Suite 610 Bethesda, Maryland 20814

Winston & Strawn 1400 L Street, N.W. Washington, D.C. 20005-3502

JUN 23 1997

bcc to DCD (IE01)

bcc distrib. by RIV: Regional Administrator DRP Director Branch Chief (DRP/D) Project Enginecr (DRP/D) Branch Chief (DRP/TSS)

Resident Inspector DRS-PSB MIS System RIV File

DOCUMENT NAM	E: R:\	WAIWI	104AK LAK
--------------	--------	-------	-----------

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" - Copy with enclosures "N" = No copy

RIV:PE:DRP/D	C:DRP/D	D:DRP	N	
GAPick; df Bey	PHHarrel	TPGwynn	my	
6/20/97	6/20/97	6/22/97		

OFFICIAL RECORD COPY

.4-

JUN 23 1997

bcc to DCD (IE01)

bcc distrib. by RIV: Regional Administrator DRP Director Branch Chief (DRP/D) Project Engineer (DRP/D) Branch Chief (DRP/TSS)

Resident Inspector DRS-PSB MIS System RIV File

DOCUMENT	NAME:	R:\ WAT	WT704AK.LAK

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

6/20/97	6/20/97	6122/97	
GAPick; df 95eu	PHHarren	TPGwynn MM	
RIV:PE:DRP/D	C:DRP/D	D:DRP	

OFFICIAL RECORD COPY



Entergy Operations, Inc. P.O. Box B Kullona: LA 70066 Tel 504 739 6242

Early C. Ewing, III

Nuclear Safety & Regulatory Attains Waterford 3

W3F1-97-0125 A4.05 PR

June 4, 1997

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Subject: Waterford 3 SES Docket No. 50-382 License No. NPF-38 NRC Inspection Report 97-04 Reply to Notice of Violation

Gentlemen:

In accordance with 10CFR2.201, Entergy Operations, Inc. hereby responds to the notice of violation enclosed in the subject Inspection Report.

5 57

According to the notice of violation, our response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. Licensee Event Reports (LERs) 97-012-01, 97-010-00 and 97-001-00 meet that criterion. LER 97-012-01 adequately addresses violation 9704-01. LER 97-010-00 adequately addresses violation 9704-02 and LER 97-001-00 adequately addresses violation 9704-06. Attached for your review are LERs 97-012-01, 97-0/01-6.7 and 97-010-00.

The first violation, 9704-01, concerns a failure to comply with the Technical Specification requirements for the use of overtime. The requirements of the Technical Specification and the working hour policy have been reemphasized to management and supe: 'sory personnel. In addition, the working hour procedure will be revised to clarify requirements. Detailed corrective actions are included in LER 97-012-01.

The second violation, 9704-02, concerns a failure to recognize that Shield Building Ventilation (SBV) Train B failed its Technical Specification surveillance for maximum air flow. Also, the surveillance review process allowed the surveillance failure to go

9706060215 2pp, 97-1240

Reply to Notice of Violation (IR 97-04) W3F1-97-0125 Page 2 June 4, 1997

undetected greater than the Technical Specification allowed outage time. The SBV flow rate was adjusted to be within Technical Specification range and the surveillance test was re-performed. Detailed corrective actions are included in LER 97-010-00.

The third violation, 9704-06, concerns inadequate 10 CFR 50.59 evaluations which resulted in crediting an EFW Flow Control Valve for containment isolation, without having position indication as required by RG 1.97. An instance was identified which exceeded the allowed outage time of TS 3.3.3.6 "Accident Monitoring Instrumentation", resulting in a violation of the TS. The Technical Requirements Manual and the Final Safety Analysis Report were revised to address this issue. Detailed corrective actions are included in LER 97-001-00.

Waterford 3 is currently in full compliance with the requirements referenced in each violation.

Should you have any questions regarding this response, please contact me at (504) 739-6242 or Tim Gaudet at (504) 739-6666.

Very truly yours,

E.Č. Ewing Director, Nuclear Safety & Regulatory Affairs

ECE/GCS/tjs Attachments

CC:

(w/Attachments) E.W. Merschoff (NRC Region IV) C.P. Patel (NRC-NRR)

(w/o Attachments) J. Smith N.S. Reynolds NRC Resident Inspectors Office