



# SAFEGUARDS INFORMATION

UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
101 MARIETTA ST., N.W.  
ATLANTA, GEORGIA 30323

NOV 2 1988

Report Nos.: 50-335/88-23 and 50-389/88-23

Licensee: Florida Power and Light Company  
9250 West Flagler Street  
Miami, FL 33102

Docket Nos.: 50-335 and 50-389

License Nos.: DPR-67 and NPF-16

Facility Name: St. Lucie 1 and 2

Inspection Conducted: September 25-30, 1988

Inspector: W. W. Stansberry  
W. W. Stansberry, Physical Security Inspector

11/1/88  
Date Signed

Approved by: D. McGuire  
D. McGuire, Section Chief  
Physical Security Section  
Division of Radiation Safety and Safeguards

11/2/88  
Date Signed

## SUMMARY

Scope: This routine unannounced inspection was conducted in the areas of Security Plan and Implementing Procedures; Management Effectiveness; Security Organization; Records and Reports; Testing and Maintenance; Locks, Keys and Combinations; Physical Barriers-Protected and Vital Areas; Lighting; Compensatory Measures; Assessment Aids; Access Control-Personnel, Packages and Vehicles; Detection Aids-Protected and Vital Areas; Alarm Stations; Personnel Training and Qualification; Safeguards Contingency Plan; and Physical Protection Safeguards Information.

Results: In the areas inspected, violations were not identified. However, the following Inspector Follow-up Items were identified:

1. Physical Security Plan commitments for administrative controls missing (Paragraph 5).
2. Perimeter lighting lacked appropriate maintenance (Paragraph 6).
3. Administrative controls of the Key and Core Program needs improvement (Paragraph 7).
4. Perimeter detection aids need calibration (Paragraph 16).
5. Contingency Plan needs to address Radiological Emergencies (Paragraph 20).

BB11180146 BB1102  
PDR ADOCK 05000335  
Q PNU

# SAFEGUARDS INFORMATION

Document transmitted herewith contains sensitive unclassified information. When separated from enclosures, this document is decontrolled.