FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)					Page (3)		
		Year	144	Sequential Number	1//	Revision Number			
Byron, Unit 2	0   5   0   0   0   4   5	816	-	01 0 1 1	-	010	14	OF	014

F. PREVIOUS OCCURRENCES:

LER NUMBER

TITLE

NONE

G. COMPONENT FAILURE DATA:

MANUFACTURER NOMENCLATURE MODEL NUMBER

MFG PART NUMBER


Crosby Relief Valve

J0-25WR

N57027-00-0008

B702180352 B70206 PDR ADDCK 05000455 S PDR

(1135M)



February 6, 1987

LTR:

BYRON 87-0173

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Dear Sir:

It has come to our attention that some of the distributees of Licensee Event Report 455-86-001-00 did not receive page four of the report. Please check your copy and insert the attached if page four is missing. Thank you.

Very truly yours,

R. E. Querio

Station Manager

Byron Nuclear Power Station

REQ/JL/bf

Attachment

cc:

J. G. Keppler

NRC Region III Administrator J. Hinds, NRC Resident Inspector

INPO Record Center

CECo Distribution List

#43/02

JE27