

## UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

June 6, 1989

Docket No. 50-254

Mr. Thomas J. Kovach Nuclear Licensing Manager Commonwealth Edison Company Post Office Box 767 Chicago, IL 60690

Dear Mr. Kovach:

SUBJECT: SAFETY EVALUATION OF THE QUAD CITIES, UNIT 1, IGSCC INSPECTION PLAN AND REPAIRS (TAC NO. 66529)

RE:

(a) Letter from I. Johnson (CECo) to T. Murley (NRC) dated, December 10, 1987

(b) Letter from I. Johnson (CECo) to T. Murley (NRC) dated, December 17, 1987

(c) Letter from T. Ross (NRC) to L. Butterfield (CECo) dated, December 18, 1987

(a) Letter from T. Ross (NRC) to L. Butterfield (CECo) dated, April 13, 1988

(e) Letter from I. Johnson (CECo) to T. Murley (NRC) dated, May 31, 1988

(f) Letter from W. Morgan (CECo) to T. Murley (NRC) dated, July 29, 1988

In reference (a), Commonwealth Edison Company (CECo) submitted their final report detailing the results of the Quad Cities (Unit 1) augmented inspection program for piping welds susceptible to Intergranular Stress Corrosion Cracking (IGSCC) pursuant to General Letter (GL) 84-11. This report provided descriptions of flaws, along with analyses and repair actions conducted during the Reload 9/Cycle 10 Refueling Outage for Quad Cities, Unit 1. In addition to their final report, CECo committed (reference (b)) to upgrade two particular weld repairs and reevaluate another weld during the next refueling outage, and institute an augmented leakage monitoring program in accordance with GL 84-11 during Cycle 10.

Based upon a preliminary review of the aforementioned documentation, we determined in reference (c), that the condition of respective Unit 1 pipe welds should not preclude restart. However, in reference (d), we requested additional information from CECo inorder to satisfactorily complete our safety evaluation of the IGSCC inspection plan results and repairs. CECo responded to this request with reference (e).

Enclosed is the final NRC Safety Evaluation for the IGSCC inspection program conducted at Quad Cities, Unit 1, during the Reload 9/ Cycle 10 Refueling Outage. We have concluded that the inspections, repairs, and mitigations performed during this outage met the guidelines of GL 84-11 and Quad Cities Unit 1 can continue to operate safely for at least an 18-month fuel cycle (Cycle 10) in its present configuration.

8906090193 890606 PDR ADOCK 05000254 Q PDC CECo's plans for inspection and/or modification of the recirculation system piping, and any other piping systems susceptible to IGSCC, during the next refueling outage must now follow the guidelines in Generic Letter 88-01. CECo did already respond to Generic Letter 88-01 in reference (f) regarding their IGSCC program for future outages related to piping replacement, inspection, repair and leakage detection. However, we have not completed our evaluation of this response because additional information is needed. When our review is completed, a separate safety evaluation will be forthcoming.

With regard to the specific IGSCC inspection plan of the upcoming Unit 1 refueling outage (scheduled to begin September 1989), CECo should incorporate the additional weld repairs and examinations recommended in our SER or provide detailed justification for not doing so. These recommendations include previous CECo commitments identified by reference (b).

Should you have any particular questions concerning our conclusions and recommendations contained in the enclosed SER, please do not hesitate to contact me.

Thierry M. Ross, Project Manager

Project Directorate III-2

Division of Reactor Projects III, IV. V. and Special Projects

Enclosure: As stated

cc w/enclosure: See next page Mr. Thomas J. Kovach Commonwealth Edison Company Quad Cities Nuclear Power Station Units 1 and 2

cc:

Mr. Stephen E. Shelton Vice President Iowa-Illinois Gas and Electric Company P. O. Box 4350 Davenport, Iowa 52808

Michael I. Miller, Esq. Sidley and Austin One First National Plaza Chicago, Illinois 60603

Mr. Richard Bax Station Manager Quad Cities Nuclear Power Station 22710 206th Avenue North Cordova, Illinois 61242

Resident Inspector U. S. Muclear Regulatory Commission 22712 206th Avenue North Cordova, Illinois 61242

Chairman
Rock Island County Board
of Supervisors
1504 3rd Avenue
Rock Island County Office Bldg.
Rock Island, Illinois 61201

Mr. Michael E. Parker, Chief Division of Engineering Illinois Department of Nuclear Safety 1035 Outer Park Drive, Springfield, Illinois 62704

Regional Administrator, Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road, Bldg. #4 Glen Ellyn, Illinois 60137 CECo's plans for inspection and/or modification of the recirculation system piping, and any other piping systems susceptible to IGSCC, during the next refueling outage must now follow the guidelines in Generic Letter 88-01. CECo did already respond to Generic Letter 88-01 in reference (f) regarding their IGSCC program for future outages related to piping replacement, inspection, repair and leakage detection. However, we have not completed our evaluation of this response because additional information is needed. When our review is completed, a separate safety evaluation will be forthcoming.

With regard to the specific IGSCC inspection plan of the upcoming Unit 1 refueling outage (scheduled to begin September 1989), CECo should incorporate the additional weld repairs and examinations recommended in our SER or provide detailed justification for not doing so. These recommendations include previous CECo commitments identified by reference (b).

Should you have any particular questions concerning our conclusions and recommendations contained in the enclosed SER, please do not hesitate to contact me.

151

Thierry M. Ross, Project Manager Project Directorate III-2 Division of Reactor Projects III, IV, V, and Special Projects

Enclosure: As stated

cc w/enclosure: See next page

DISTRIBUTION:
Docket file
NRC & local PDRs
MVirgilio
TRoss
EJordan

PDIII-2 r/f PShemanski LLuther OGC BGrimes

PDIII-2:PM/A TRoss:dmj 6/5/89

ACRS (10)

PDIII-2:LA LLuther 22 6/5 /89 P. 5.
PDIII-2:(A)PD
PShemanski
6/5/89

OFOI