U. S. NUCLEAR REGULATORY COMMISSION

NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | O H D B S 1 (2) | Ø Ø - Ø Ø N P F - Ø 3 (3) | 4 1 1 1 1 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 | REPORT SOURCE L (6) | Ø 5 Ø - Ø 3 4 6 (7) | 1 1 1 0 7 8 (8) | 1 2 Ø 7 7 8 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On November 10, 1978 and on November 17, 1978, fluctuating signals from the absolute
0 3 | position indicator for Control Rod 4 of Group 3 caused asymmetric rod alarms. Abso-
0 4 | lute position indication for this rod was declared inoperable at each of these times,
0 5 | placing the unit in the Action Statement of Technical Specification 3.1.3.3. There
0 6 | was no danger to the health and safety of the public or to unit personnel. Relative
0 7 | position indication, as well as zone reference indication for Rod 4, Group 3 was
0 8 | operable. (NP-33-78-135)
7 8 9 80

0 9 | SYSTEM CODE I F (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE E L E C C N (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 8 (21 22) | — (23) | SEQUENTIAL REPORT NO. 1 1 3 (24 26) | / (27) | OCCURRENCE CODE Ø 3 (28 29) | REPORT TYPE L (30) | — (31) | REVISION NO. 1 (32)

ACTION TAKEN X (18) | FUTURE ACTION C (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) Ø Ø Ø Ø (37 40) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER B 3 6 5 (26)
33 34 35 36 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | After access to containment was permitted, investigation of the absolute position in-
1 1 | dication for Control Rod 4 of Group 3 resumed by testing the individual components of
1 2 | the PI string. The cause of the occurrence has been determined to be an intermittent
1 3 | failure of a component within the position indicator tube. The position indicator
1 4 | tube was replaced.
7 8 9 80

1 5 | FACILITY STATUS E (28) | % POWER Ø 4 9 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Fluctuating Signals
7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES NUMBER Ø Ø Ø (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER Ø Ø Ø (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION NA
7 8 9 10 80

2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA
7 8 9 10

7903230170

NRC USE ONLY
68 69 80

DVR 78-171 & NAME OF PREPARER Susan A. Kovach PHONE 419-259-5000, Ext. 230

GPO 91 7-926