Lake, Louis

From: Orf, Tracy
Sent: Friday, November 13, 2009 7:47 AM
To: Lake, Louis
Cc: Khanna, Meena
Subject: Containment liner condition

Lou,

I got a call from Darrell Dunn in RES asking about the as-found condition of the containment liner during the SGR. Specifically, was there any pitting or corrosion of the containment liner, and if so was there/will there be an assessment of the liner thickness? He also asked if any corrosion of the rebar was found during demolition. If you could point me to the information, I would appreciate it.

Thanks,

Tracy J. Orf, Project Manager
H.B. Robinson
Plant Licensing Branch II-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation
Phone: (301) 415-2788