R2

Outside of Scope

PLANT ISSUE TRACKING APPLICATION

Nuclear Regulatory Commission - Reg

plant status daily archives | enter daily plant status | saf in

Oconee Information for 09/17/2009 (Modify/Update)

Outside of Scope

Outside of Scope

Risk Significant / Emergent Activities:

Information in this record was deleted in accordance with the Freedom of Information Act. Exemptions Outside of Scope FOIA/PA 2011-0021

C/15

Work on the excavation of the ASW piping adjacent to the SSF is on hold today for the scheduled KHU-2 train maintenance (quarterly PMs). Some excavation was done yesterday however, the area around the existing ASW piping has not been removed which keeps the licensee from entering the section of the critical plan which requires comp measures to be implemented. Excavation is slated to start up tomorrow (Friday) with tie-in work to start next week (this work will inop the SSF ASW pump for all three units and the LCO will be entered for this condition). The RI's are following the work under 1R12 (Maintenance Effectiveness) and the risk management / critical plan implementation under 1R13 (Risk Management).

9:15 mtg. ○ Yes ◉ No

delete

ASW Piping Work 005.jpg

add attachment

Findings and Observations:

Resident Issue Summary:
==========
We are drafting up the following issues for this inspection report (2009-004) and should have files in for review shortly:

Outside of Scope

Outside of Scope

4) 10CFR50.65(a)(4) issue: Tied to the removal of the SSF from service due to the ASW leak and deficiencies in what equipment was protected during that time. Awaiting risk values from General Office to process ands draft up issue in terms of SDP color. Licensee understands the issue and wis working with the GO to get us what we need to process.

Outside of Scope

Outside of Scope

Outside of Scope

Outside of Scope

Outside of Scope

Outside of Scope

Existing ASW pipes run in this area (12.5' down)
SSF
New headers will come out from the bldg. here and angle to the existing headers for tie-in