NRC FORM 366
(7-77)

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS2 (2) | 00-000000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000311 (7) | 011182 (8) | 102082 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At approximately 0815 hours, January 11, 1982, the Control Room Operator noticed
03 No. 2A1 Battery Charger had tripped. Upon resetting the breaker, it tripped again.
04 No. 2A2 Battery Charger was put in service. No. 2A1 Battery Charger was declared
05 inoperable and Action Statement 3.8.2.3.c was entered at 0815 hours, January 11, 1982.
06
07
08

09 | SYSTEM CODE EC (11) | CAUSE CODE A (12) | CAUSE SUBCODE B (13) | COMPONENT CODE BATTRY (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 002 | / | OCCURRENCE CODE 03 | REPORT TYPE X | — | REVISION NO. 1

ACTION TAKEN H (18) | FUTURE ACTION G (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER E355 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The trips were caused by a difference between the battery and battery charger voltages.
11 Personnel were instructed as to the problem. No. 2A1 Battery Charger was back in
12 service and Action Statement 3.8.2.3.c was terminated at 2130 hours, January 11, 1982.
13 The battery charger operating instruction was revised to have an electrician adjust
14 the float voltage prior to charging the battery.

15 | FACILITY STATUS E (28) | % POWER 030 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 | NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) NA

8211060299 821020
PDR ADOCK 05000311
S PDR

NRC USE ONLY

NAME OF PREPARER R. Heller PHONE: 609/935-6000 Ext. 3078