NRC Medium Voltage Circuit Breaker Training

Attachment 8A

ABB HK Work Shop

Remove front cover

Racking Mechanism gap check



Checking puffer operation



Checking the gap on the control device actuator



Trapping the springs for slow close



Slow closing to check simultanious meet



Main contact pressure check



NSPECT the groove pins



Remove and lubricate MOC Switch Actuator