



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
801 WARRENVILLE ROAD
LISLE, ILLINOIS 60532-4351

December 23, 1999

Mr. Oliver D. Kingsley
President, Nuclear Generation Group
Commonwealth Edison Company
ATTN: Regulatory Services
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT: QUAD CITIES INSPECTION REPORT 50-254/99023(DRP);
50-265/99023(DRP)

Dear Mr. Kingsley:

On December 3, 1999, the NRC completed an inspection at your Quad Cities Units 1 and 2 reactor facilities. The results were discussed with Mr. Dimmette and other members of your staff. The enclosed report presents the results of that inspection.

The inspection was an examination of activities conducted under your license as they relate to safety and to compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas the inspection consisted of a selective examination of procedures and representative records, observations of activities, and interviews with personnel. Specifically, this inspection was conducted by the resident inspectors and focused on reactor safety.

Based on the results of this inspection, NRC identified three issues which were categorized as being of low risk significance. The issues involve two incorrect classifications of equipment failures in the maintenance rule program, and inadequate corrective action related to design control of software. These issues have been entered into your corrective action program. These issues are listed in the summary of findings and are discussed in the report.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response, if you choose to provide one, will be placed in the NRC Public Document Room.

Sincerely,

A handwritten signature in black ink, appearing to read "Mark A. Ring".

Mark A. Ring, Chief
Reactor Projects Branch 1

Docket Nos. 50-254; 50-265
License Nos. DPR-29; DPR-30

Enclosure: Inspection Report 50-254/99023(DRP);
50-265/99023(DRP)

PDR A DOCK

O. Kingsley

-2-

cc w/encl: D. Helwig, Senior Vice President, Nuclear Services
C. Crane, Senior Vice President, Nuclear Operations
H. Stanley, Vice President, Nuclear Operations
R. Krich, Vice President, Regulatory Services
DCD - Licensing
J. Dimmette, Jr., Site Vice President
G. Barnes, Quad Cities Station Manager
C. Peterson, Regulatory Affairs Manager
M. Aguilar, Assistant Attorney General
State Liaison Officer, State of Illinois
State Liaison Officer, State of Iowa
Chairman, Illinois Commerce Commission
W. Leech, Manager of Nuclear
MidAmerican Energy Company

Distribution:

AJM (E-Mail)
RPC (E-Mail)
RMP3 (Project Mgr.) (E-Mail)
J. Dyer, RIII w/encl
J. Caldwell, RIII w/encl
B. Clayton, RIII w/encl
SRI Quad Cities w/encl
DRP w/encl
DRS w/encl
RIII PRR w/encl
PUBLIC IE-01 w/encl
Docket File w/encl
GREENS
IEO (E-Mail)
DOCDESK (E-Mail)
M. Branch, NRR (E-Mail)
T. Frye, NRR (E-Mail)
A. Madison, NRR (E-Mail)
S. Stein, NRR (E-Mail)
R. Mathew, NRR (E-Mail)

Mr. Oliver D. Kingsley
 President, Nuclear Generation Group
 Commonwealth Edison Company
 ATTN: Regulatory Services
 Executive Towers West III
 1400 Opus Place, Suite 500
 Downers Grove, IL 60515

**SUBJECT: QUAD CITIES INSPECTION REPORT 50-254/99023(DRP);
 50-265/99023(DRP)**

Dear Mr. Kingsley:

On December 3, 1999, the NRC completed an inspection at your Quad Cities Units 1 and 2 reactor facilities. The results were discussed with Mr. Dimmette and other members of your staff. The enclosed report presents the results of that inspection.

The inspection was an examination of activities conducted under your license as they relate to safety and to compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas the inspection consisted of a selective examination of procedures and representative records, observations of activities, and interviews with personnel. Specifically, this inspection was conducted by the resident inspectors and focused on reactor safety.

Based on the results of this inspection, NRC identified three issues which were categorized as being of low risk significance. The issues involve two incorrect classifications of equipment failures in the maintenance rule program, and inadequate corrective action related to design control of software. These issues have been entered into your corrective action program. These issues are listed in the summary of findings and are discussed in the report.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response, if you choose to provide one, will be placed in the NRC Public Document Room.

Sincerely,

Mark A. Ring, Chief
 Reactor Projects Branch 1

Docket Nos. 50-254; 50-265
 License Nos. DPR-29; DPR-30

Enclosure: Inspection Report 50-254/99023(DRP);
 50-265/99023(DRP)

DOCUMENT NAME: G:\QUAD\qua99023 drp.wpd

To receive a copy of this document, indicate in the box "C" = Copy w/o att/encl "E" = Copy w/att/encl "N" = No copy

OFFICE	RIII	E	RIII	E			
NAME	Lerch:dp/ALF		Ring				
DATE	12/13/99		12/13/99				

OFFICIAL RECORD COPY

O. Kingsley

-2-

cc w/encl: D. Helwig, Senior Vice President, Nuclear Services
C. Crane, Senior Vice President, Nuclear Operations
H. Stanley, Vice President, Nuclear Operations
R. Krich, Vice President, Regulatory Services
DCD - Licensing
J. Dimmette, Jr., Site Vice President
G. Barnes, Quad Cities Station Manager
C. Peterson, Regulatory Affairs Manager
M. Aguilar, Assistant Attorney General
State Liaison Officer, State of Illinois
State Liaison Officer, State of Iowa
Chairman, Illinois Commerce Commission
W. Leech, Manager of Nuclear
MidAmerican Energy Company