

Mr. M. Wadley  
 President, Nuclear Generation  
 Northern States Power Company  
 414 Nicollet Mall  
 Minneapolis, MN 55401

SUBJECT: MONTICELLO INSPECTION REPORT 50-263/99008(DRP)

Dear Mr. Wadley:

On December 16, 1999, the NRC completed an inspection at the Monticello reactor facility. The enclosed report presents the results of that inspection.

During the 6-week period covered by this inspection, the conduct of operations at the Monticello facility was generally characterized by safety-conscious operations. Evolutions, such as surveillance tests and routine plant power changes, were well controlled, deliberate, and performed in accordance with procedures. No significant issues were identified.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Sincerely,

/s/ R. Lanksbury

Roger D. Lanksbury, Chief  
 Reactor Projects Branch 5

Docket No. 50-263  
 License No. DPR-22

Enclosure: Inspection Report 50-263/99008(DRP)

cc w/encl: Site General Manager, Monticello  
 Plant Manager, Monticello  
 S. Minn, Commissioner, Minnesota  
 Department of Public Service

DOCUMENT NAME: G:\MONT\MON99008DRP.WPD

To receive a copy of this document, indicate in the box "C" = Copy w/o attach/encl "E" = Copy w/attach/encl "N" = No copy

OFFICE	RIII:DRP	E	RIII:DRP	E				
NAME	Kunowski/co	MAK	Lanksbury	MAK				
DATE	1/11/00		1/11/00					

OFFICIAL RECORD COPY

PDR ADOCU



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION III  
801 WARRENVILLE ROAD  
LISLE, ILLINOIS 60532-4351

January 11, 2000

Mr. M. Wadley  
President, Nuclear Generation  
Northern States Power Company  
414 Nicollet Mall  
Minneapolis, MN 55401

SUBJECT: MONTICELLO INSPECTION REPORT 50-263/99008(DRP)

Dear Mr. Wadley:

On December 16, 1999, the NRC completed an inspection at the Monticello reactor facility. The enclosed report presents the results of that inspection.

During the 6-week period covered by this inspection, the conduct of operations at the Monticello facility was generally characterized by safety-conscious operations. Evolutions, such as surveillance tests and routine plant power changes, were well controlled, deliberate, and performed in accordance with procedures. No significant issues were identified.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Sincerely,

A handwritten signature in cursive script that reads "Michael Kunowski for".

Roger D. Lanksbury, Chief  
Reactor Projects Branch 5

Docket No. 50-263  
License No. DPR-22

Enclosure: Inspection Report 50-263/99008(DRP)

cc w/encl: Site General Manager, Monticello  
Plant Manager, Monticello  
S. Minn, Commissioner, Minnesota  
Department of Public Service

M. Wadley

-3-

Distribution:

CMC1 (E-Mail)

WES (E-Mail)

CFL (Project Mgr.) (E-Mail)

J. Caldwell, RIII w/encl

B. Clayton, RIII w/encl

SRI Monticello w/encl

DRP w/encl

DRS w/encl

RIII PRR w/encl

PUBLIC IE-01 w/encl

Docket File w/encl

GREENS

IEO (E-Mail)

DOCDESK (E-Mail)