Dave Morey Vice President Farley Project Southern Nuclear Operating Company P.O. Box 1295 Birmingham, Alabama 35201 Tel 205.992.5131

January 10, 2000

Docket Nos.: 50-348 50-364 SOUTHERN COMPANY Energy to Serve Your World[®] NEL-00-0008

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant Monthly Operating Report

Ladies and Gentlemen:

Enclosed are the December 1999 Monthly Operating Reports for Joseph M. Farley Nuclear Plant Units 1 and 2, as required by Section 6.9.1.10 of the Technical Specifications.

If you have any questions, please advise.

Respectfully submitted,

or mory

Dave Morey

RWC:mor

Enclosures:

- 1. December Monthly Operating Report for Plant Farley Unit 1
- 2. December Monthly Operating Report for Plant Farley Unit 2



Page 2

U. S. Nuclear Regulatory Commission

cc: <u>Southern Nuclear Operating Company</u> Mr. L. M. Stinson, General Manager

> U. S. Nuclear Regulatory Commission, Washington, D. C. Mr. L. M. Padovan, Licensing Project Manager – Farley

U. S. Nuclear Regulatory Commission, Region II Mr. L. A. Reyes, Regional Administrator Mr. T. P. Johnson, Senior Resident Inspector – Farley

OPERATING DATA REPORT

DOCKET NO.:	50-348
UNIT NAME:	J. M. Farley - Unit 1
DATE:	January 4, 2000
COMPLETED BY:	W. L. Marlar
TELEPHONE:	(334) 814-4554

OPERATING STATUS

1.	Reporting Period:	DECEMBER 1999
2.	Design Electrical Rating (Net MWe):	854
3.	Maximum Dependable Capacity (Net MWe):	847

		This Month	Year to Date	<u>Cumulative</u>
4.	Number Of Hours Reactor Was Critical:	744.0	8,722.2	157,625.4
5.	Hours Generator On-line:	744.0	8,695.6	155,455.3
6.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
7.	Net Electrical Energy Generated (MWH):	622,457.0	7,226,516.0	122,760,833.0

CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		There were no challenges to Pressurizer PORV or Pressurizer Safety Valves.

DOCKET NO.:	50-348	
UNIT NAME:	J. M. Farley - Unit 1	
DATE:	January 4, 2000	
COMPLETED BY	W. L. Marlar	
TELEPHONE:	(334) 814-4554	

REPORTING PERIOD: DECEMBER 1999

No.	Date	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
						There were no unit shutdowns during the month.
					· · ·	
(1) REAS					(2) METHOD:	
 (1) REASON: A - Equipment Failure (Explain) B - Maintenance or Test C - Refueling D - Regulatory Restriction E - Operator Training/License Examination 		 (2) METHOD: 1 - Manual 2 - Manual Trip/Scram 3 - Automatic Trip/Scram 4 - Continuation 5 - Other (Explain) 				

F - Administrative

G - Operational Error (Explain)

H - Other (Explain)

CAUSE/CORRECTIVE ACTION/COMMENTS

NARRATIVE REPORT

At 2315 on 991222, with the unit operating at 100% reactor power, the unit was ramped to 65% reactor power for 1A Steam Generator Feed Pump Lube Oil System repairs. Repairs were completed and the unit was returned to 100% power at 1207 on 991224. At 1000 on 991228 with the unit operating at 100% reactor power, the unit was ramped to 98.5% reactor power for trouble-shooting 6A Feedwater Heater Drain Valve. Trouble-shooting was completed and the unit returned to 100% power at 1311 on 991228.

OPERATING DATA REPORT

DOCKET NO.:	50-364
UNIT NAME:	J. M. Farley - Unit 2
DATE:	January 4, 2000
COMPLETED BY:	W. L. Marlar
TELEPHONE:	(334) 814-4554

OPERATING STATUS

1.	Reporting Period:	DECEMBER 1999
2.	Design Electrical Rating (Net MWe):	855
3.	Maximum Dependable Capacity (Net MWe):	852

		This Month	Year to Date	Cumulative
4.	Number Of Hours Reactor Was Critical:	436.6	7,290.4	139,758.8
5.	Hours Generator On-line:	401.0	7,242.4	137,887.8
6.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
7.	Net Electrical Energy Generated (MWH):	285,293.0	5,353,242.0	109,452,528.0

CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		On 991212 PORV 444B lifted. No safety valves lifted. This occurred during the return to power after U2RF13 when placing the pressurizer pressure controller PK444A in auto. The cause was attributed to controller windup.

UNIT SHUTDOWNS

DOCKET NO.:	50-364	
UNIT NAME:	J. M. Farley - Unit 2	
DATE:	January 4, 2000	
COMPLETED BY	W. L. Marlar	
TELEPHONE:	(334) 814-4554	

REPORTING PERIOD: DECEMBER 1999

No.	Date	Type F: Forced S: Scheduled	Duration (Hours)	Reason (1)	Method of Shutting Down (2)	Cause/Corrective Actions Comments
2	991016	S	343.0	С	1	The thirteenth refueling outage was completed on 991215.
 (1) REASON: A - Equipment Failure (Explain) B - Maintenance or Test C - Refueling D - Regulatory Restriction E - Operator Training/License Examination F - Administrative G - Operational Error (Explain) 					 (2) METHOD: I - Manual 2 - Manual Trip/Scram 3 - Automatic Trip/Scram 4 - Continuation 5 - Other (Explain) 	

H - Other (Explain)

CAUSE/CORRECTIVE ACTION/COMMENTS

NARRATIVE REPORT

The following refueling activities were completed:

1) Steam Generator eddy current testing.

2) Baffle former bolt inspection and replacement.

3) Guide Tube Support Pin replacement.

4) 10 Year Reactor Vessel ISI

5) Steam Generator Replacement N-1 Outage Modifications

On 991215 at 0700 the U2RF13 outage was completed and the unit was synchronized to the grid.