

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920

10 CFR 50.4
10 CFR 50.55a



January 25, 2000

JMHLTR: #00-0051

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555


Dresden Nuclear Power Station Unit 2
Facility Operating License No. DPR-19
NRC Docket No. 50-237

Subject: Inservice Inspection (ISI) Summary Report
Fall 1999 Inservice Inspection Period

Enclosed please find the Commonwealth Edison (ComEd) Company Post-Outage (90 day) Summary Report for Inservice Inspection examinations and Repair/Replacement activities conducted from July 15, 1998 to January 10, 2000 for the Dresden Nuclear Power Station Unit 2. Unit 2 completed its sixteenth refueling outage (D2R16) on October 27, 1999. This report has been submitted to you in accordance with the requirements of ASME Boiler and Pressure Vessel Code Section XI, "Rules for Inservice Inspection of Nuclear Power Plant Components," Article IWA-6200.

If there are any questions or comments concerning this letter, please refer them to Mr. Dale Ambler, our Regulatory Assurance Manager, at (815) 942-2920, extension 3800.

Respectfully,


J. M. Heitley
Site Vice President
Dresden Nuclear Power Station

Attachment

cc: Regional Administrator – Region III
NRC Senior Resident Inspector, Dresden Station