

January 27, 2000

C0100-15 10 CFR 50.4

Docket Nos:

50-315 50-316

U. S. Nuclear Regulatory Commission ATTN:Document Control Desk Mail Stop O-P1-17 Washington, D.C. 20555

## Donald C. Cook Nuclear Plant Units 1 and 2 SPILL OF HYDRAULIC OIL TO THE GROUND NPDES NOTIFICATION

Indiana Michigan Power Company is the holder of National Pollutant Discharge Elimination System (NPDES) permit number MI0005827 for Donald C. Cook Nuclear Plant. Section 5.4.2 to Part II of Appendix B (Environmental Technical Specifications) to Facility Operating Licenses DPR-58 and DPR-74 requires reports of non-routine events that are reportable to state agencies to be submitted to the NRC.

In a letter dated January 20, 2000, the Michigan Department of Environmental Quality (MDEQ) was notified of a spill of hydraulic oil to the ground. The notification of this spill was provided to MDEQ per Part II, Section A.6 of the NPDES permit. In accordance with the Environmental Technical Specifications, a copy of the report is hereby provided to the NRC.

Should you have any questions or concerns regarding this notification, please contact John Carlson at (616) 465-5901, x 1153.

Sincerely,

Robert C. Godley

Director Regulatory Affairs

Attachment

/dms

IE23

c: J. A. Abramson
MDEQ - DW & RPD
NRC Resident Inspector
C. J. Paperiello

## ATTACHMENT TO C0100-15

## NPDES Notification to

Michigan Department of Environmental Quality

Indiana Michigan Power Company Cook Nuclear Plant One Cook Place Bridgman. MI 49106 616-465-5901



Mr. Fred Morley, District Supervisor Surface Water Quality Division Michigan Department of Environmental Quality 1342 SR 89 West Suite B Plainwell, MI 49080

January 20, 2000

Dear Mr. Morley:

Subject:

Donald C. Cook Nuclear Plant NPDES Permit No. MI 0005827

This notification is made pursuant to Cook Nuclear Plant's NPDES Permit MI 0005827, Part II. Section A. 6, Spill Notification.

On January 18, 2000 at 0030 hrs, a hydraulic line failed on one of the plant's cranes. The cracked line leaked approximately 5- 20 gallons of hydraulic oil to the ground. The spilled oil was immediately cleaned up along with the soil that had oil in it. No oil was discharged to the groundwater or surface water. This spill does not pose a threat to the environment or public health or safety.

The crane was immediately shut down to depressurize the system. The failed hose was repaired. The spilled oil and soil was collected and properly disposed.

Mr. John Vollner of the MDEQ Plainwell Office was notified of the spill on January 18, 2000. An inspection of the crane's hydraulic system was completed to verify that the hydraulic hoses were in good repair to prevent further spills.

Should you have any questions, please contact me at (616) 465-5901 ext. 1153.

Sincerely,

John P. Carlson

Environmental Superintendent

C: U.S. Nuclear Regulatory Commission per App. B T.S.

Page 2

Mr. Fred Morley

Re: Cook Nuclear Plant

NPDES Permit No. MI 0005827

I certify under penalty of law that I have personally examined and am familiar with the information submitted on this and all attached documents; and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

A.C. Bakken

Site Vice President

bc: R. C. Godley

A. C. Bakken

J. P. Carlson

D. M. Fitzgerald

C. E. Hawk

T. P. Noonan

T. J. O'Leary

W. H. Schalk/T. Kratt

B. K. Zordell

MDEQ File

Human Performance - Corrective Action Department