

**EPSC CONTROLLED DOCUMENT TRANSMITTAL AND
RECEIPT ACKNOWLEDGEMENT FORM**

ORIGINATOR: COLETTE M. HANDY DATE: January 25, 2000

List of Contents/Enclosures:

Corrected **Section 7** of the *Steam Generator tubing ODS/CC at tube support plates for alternate repair limits, Database Update 1999, Addendum 3, NP-7480 (TR-113861)*.

Comments/Actions:

An error was found in the POPCD section of the report. It was found that data for 2 inspections in 7/8" tubing plants were included twice in the analysis. There is no significant impact on the generic POPCD due to the large amount of data.

Please insert corrected Section 7 into the Addendum 3 manual.

Recipient Name and Address:

Document Control Desk
U.S. Nuclear Regulatory Commission
Document Control Desk
Washington Dc, DC 20555-0001

Recipient Signature: _____ **Date:** _____

Please mail or fax acknowledgment form to:

**Electric Power Software Center
Attn: QA Records Coordinator
110803 Sorrento Valley Road
San Diego, CA 92121
Fax# (858) 453-4495**

1007